

**REPORT OF PHASE I ENVIRONMENTAL SITE ASSESSMENT
FORMER US PLAYING CARD
4590 BEECH STREET
NORWOOD, HAMILTON COUNTY, OHIO**

**PREPARED FOR:
THE CITY OF NORWOOD
4645 MONTGOMERY ROAD
NORWOOD, OHIO 45212**

AND

**CORE REDEVELOPMENT
549 NORTH SENATE AVENUE
INDIANAPOLIS, IN 46204**

JUNE 10, 2015



SRW ORDER NO. 340.007.01

PREPARED BY:

**SRW ENVIRONMENTAL SERVICES, INC.
55 WEST TECHNECENTER DRIVE, SUITE C
MILFORD, OHIO 45150
Phone: (513) 576-0009
Fax: (513) 576-9756**



TABLE OF CONTENTS

	<u>Page</u>
1.0 EXECUTIVE SUMMARY.....	1
1.1 General Property Characteristics	1
1.2 Summary	2
1.3 Findings and Conclusions	2
1.4 Opinions and Recommendations	5
2.0 INTRODUCTION.....	5
2.1 Purpose	5
2.2 Methodology Used	6
2.3 User Reliance	6
2.4 Limiting Conditions	7
2.4.1 Data Gaps and Failures	7
2.4.2 Limitations and Exceptions.....	7
3.0 PROPERTY INFORMATION.....	9
3.1 Property Name and Address	9
3.2 Legal Description	9
3.3 Property Description.....	9
3.4 Building Information	9
3.5 Current Uses and Activities of the Property	10
3.6 Owners and Occupants of the Property	10
3.7 Activity and Use Limitations	10
3.8 Current Land Uses and Tenants of Adjoining Properties.....	10
3.9 Current Land Uses in Surrounding Area	10
4.0 USER-PROVIDED INFORMATION.....	10
4.1 Specialized Knowledge	11
4.2 Purchase Price to Fair-Market Value Evaluation	11
4.3 Owner, Property Manager, and Occupant Information	11
4.4 Reason for Performing Phase I ESA	11
4.5 Title Records/Environmental Liens and Activity Use Limitations	11
5.0 RECORDS REVIEW.....	11
5.1 Standard Federal and State Environmental Record Sources	11
5.2 Agency File and Records Review	17
5.3 Additional Environmental Record Sources	17
5.4 Physical Setting Sources	18
5.4.1 Topography	18
5.4.2 Soils.....	19
5.4.3 Geology	19
5.4.4 Hydrogeology.....	19
5.4.5 Surface Water Bodies.....	19
5.4.6 Vapor Migration Potential.....	19
5.5 Historical Use Information	19
5.5.1 Sources Relied Upon.....	19
5.5.2 Historical Uses of the Property	20
5.5.3 Historical Uses of the Adjoining Properties.....	20



TABLE OF CONTENTS

(CONTINUED)

	<u>Page</u>
5.6 Vapor Encroachment Condition (VEC)	23
6.0 INTERVIEWS.....	23
6.1 Interview With Owner Representative	23
6.2 Interview With Site Manager	23
6.3 Interview With Local Government Officials.....	24
6.4 Interviews With Others	24
7.0 INFORMATION FROM PROPERTY RECONNAISSANCE	24
7.1 Hazardous Substances and Petroleum Products Used or Stored at the Property.....	24
7.2 Unidentified Substance Container.....	25
7.3 Aboveground Storage Tanks (ASTs)	25
7.4 Underground Storage Tanks (USTs).....	25
7.5 Hazardous Waste Generation Activities.....	26
7.6 Solid Waste Disposal.....	26
7.7 PCBs.....	26
7.8 Other.....	26
8.0 NON-SCOPE SERVICES	27
9.0 EVALUATION.....	27
9.1 Summary	27
9.2 Findings and Conclusions	29
9.3 Opinions and Recommendations.....	32
9.4 Limiting Conditions and Deletions	32
9.5 Environmental Professional	32
10.0 REFERENCES.....	33

FIGURES

Figure 1	Property Location Map
Figure 2	Property Sketch
Figure 3	Historical Operations Locations Map
Figure 4	Recognized Environmental Conditions and De Minimis Conditions Map

APPENDICES

Appendix 1	Legal Description
Appendix 2	Phase I Environmental Site Assessment User Questionnaire
Appendix 3	EDR Regulatory Report
Appendix 4	Records Request Responses
Appendix 5	User Provided Environmental Documents
Appendix 6	Historical Source Documentation
Appendix 7	Photographs
Appendix 8	Qualifications



TABLE OF CONTENTS

(CONTINUED)

ACRONYMS AND ABBREVIATIONS

amsl	above mean sea level
AST	aboveground storage tank
ASTM	American Society for Testing & Materials
bgs	below ground surface
BUSTR	Bureau of Underground Storage Tank Regulations
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CERCLIS	Comprehensive Environmental Response, Compensation, and Liability Information System
CREC	Controlled Recognized Environmental Condition
DERR	Division of Emergency & Remedial Response
EDR	Environmental Data Resources, Inc.
EPA	Environmental Protection Agency
ESA	environmental site assessment
HREC	Historical Recognized Environmental Condition
ICIS	Integrated Compliance Information System
FINDS	Facility Index System/Facility Registry System
LQG	Large Quantity Generator
LUST	leaking underground storage tank
NFA	No Further Action
NFRAP	No Further Remedial Action Planned
NLR	No Longer Regulated
ODNR	Ohio Department of Natural Resources
OEPA	Ohio Environmental Protection Agency
PCBs	polychlorinated biphenyls
RCRA	Resource Conservation & Recovery Act
REC	recognized environmental condition
SRW	SRW Environmental Services, Inc.
USEPA	United States Environmental Protection Agency
USGS	United States Geological Survey
UST	underground storage tank
VEC	Vapor Encroachment Condition



**REPORT OF PHASE I ENVIRONMENTAL SITE ASSESSMENT
FORMER US PLAYING CARD
4590 BEECH STREET
NORWOOD, HAMILTON COUNTY, OHIO**

1.0 EXECUTIVE SUMMARY

SRW Environmental Services, Inc. (SRW) performed a Phase I Environmental Site Assessment (Phase I) of the property located at 4590 Beech Street in Norwood, Hamilton County, Ohio hereafter referenced as the “Property.” The Phase I was performed to identify potential or existing recognized environmental conditions (REC) as defined by ASTM E 1527-13 at the Property. Any exceptions or deletions to the standard are noted in Section 2.4 of this report. The scope of services was identified in the City of Norwood’s United States Environmental Protection Agency (USEPA) – Assessment Grant for Hazardous Substances. The findings, conclusions, opinions and recommendations presented in this executive summary should be considered in context with this report as a whole. This work was conducted for Core Redevelopment under the directive of the City of Norwood. Figure 1 depicts the Property location.

A Property reconnaissance and review of historical and regulatory records, including interviews with persons familiar with the Property, were conducted to evaluate the Property for indications of and/or the presence of RECs. Observations, records and information from interviews show that the operations conducted at the Property did involve the use of petroleum products and/or hazardous substances, which if a release occurred could result in a REC. These same sources indicate that activities at the south adjoining property also did involve said materials.

1.1 General Property Characteristics

Name:	Former US Playing Card
Parcel Numbers:	651-0019-0125
Address:	4590 Beech Street in Norwood, Hamilton County, Ohio
Acres:	20.72
Property Location/Intersection:	East side of Beech Street across from Park Avenue
Number of Buildings/Stories:	Eight interconnected buildings with 2-4 stories, several outbuildings
Approximate Square Footage:	700,000
Year Constructed:	1900 through 1924



1.2 Summary

A cursory summary of our findings is as follows:


Report Section	Description	Findings
3.5	Current Use of Property	Vacant (2010 – present)
5.5.2	Historical Use of Property	US Playing Card manufacturing facility (1901-2010)
3.8	Current Use of Adjoining Property	North Railroad and Norwood's Operations buildings (1001 Duck Creek Road)
		South Multi-Color Corporation (4500 Beech Street)
		East Interstate 71
		West Residences (2641 Park Avenue, 4543-4545 Beech Street, and 2642 Kenilworth Avenue)
		Northwest Siemens Motor Manufacturing (4620 Forest Avenue)
5.5.3	Historical Use of Adjoining Property	North (1001 Duck Creek Road) Railroad. Beyond the railroad had unknown commercial uses including Norwood Operations Buildings (1922-present)
		South (4500 Beech Street) US Printing Company (1917-at least 1981). Currently Multi-Color Corporation (a printing company).
		East (No Address) Developed as a road (1938-1968) and I-71 (1975-present).
		West (2641 Park Avenue, 4543-4545 Beech Street, 2642 Kenilworth Avenue) Developed residentially 1949-present).
5.0	Environmental Records	The User provided documentation for soil sampling conducted in 1994, Phase I ESAs conducted in 2011 and 2013, and an asbestos survey. The soil sampling indicated the presence of contamination in the vicinity of a solvent shed and transformer pad. Both of the Phase I ESAs concluded that there were no RECs on the Property. The asbestos survey found asbestos containing materials throughout the buildings.

1.3 Findings and Conclusions

SRW has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM E 1527-13 at 4590 Beech Street in Norwood, Hamilton County, Ohio. This assessment has revealed no evidence of RECs in connection with the Property except for the following.



4590 Beech Street, Norwood, Hamilton County, Ohio	Yes	No
<p>Recognized Environmental Condition (REC)¹</p> <p>REC #1: Heavy corrosion. Heavy corrosion was noted on the floor and surrounding the floor drains in the “paste mix room” on the first floor in Building 1. In addition, corrosion was observed in the basement of Building 7 in a rectangular shape. The corrosion may have been caused by a chemical which could leach through the concrete floor into the environment; therefore, the corrosion represents a REC.</p> <p>REC #2: Suspect UST. A possible fill port and possible pump island located near the northeast corner on the exterior of Building 3 represent a suspect UST. Based on the lack of information regarding the UST and its contents, and the possibility of an unknown release into the environment, it represents a REC.</p> <p>REC #3: Former USTs. During the May 21, 2015 site reconnaissance, SRW observed a possible former fill port and vent pipe adjacent to sandy fill materials on the south side of the courtyard between Buildings 1 and 3. In addition, a User provided document states that three USTs were removed from this area in 1988. User provided documentation indicates that soil sampling was performed in this area in 1994; however, the soil samples collected were from fill materials within the pit and not native materials. No closure documentation is available; therefore the former USTs represent a REC.</p> <p>REC #4: Contaminated soil south of Building 10. The laboratory analytical results from the 1994 soil sampling indicated that the soils around the solvent shed area were contaminated with tetrachloroethylene (TCE). According to the 2011 Phase I ESA, remediation via soil excavation was performed in vicinity of the TCE contaminated soils. The document states that “soil cores were taken until clean samples were obtained”; however, there is no analytical data provided and no other documentation of closure sampling. Based on the lack of substantial closure information for the soil removal, this area represents a REC.</p> <p>REC #5: Possible former AST area. Two pyramid shaped concrete pillars were observed in a lowered area on the south side of the courtyard between Buildings 6 and 7. Piping was observed on the ground surface running parallel to the pillars, and an approximately 4” pipe between the pillars extended vertically into the ground. An emergency shut off button was observed on the wall next to the pillars. Because of the unknown nature of the pillars combined with the subsurface piping, the area represents a REC.</p> <p>REC #6: Former Hazardous Waste storage area. According to a User provided document, in 1994, soil samples were collected from the Hazardous Waste storage area north of Building 10. The soil samples were analyzed for VOCs. No VOCs were detected in the laboratory analytical results; however, Hazardous Wastes can contain other chemicals of concern. Based on the lack of substantial sampling information, the former Hazardous Waste storage area is a REC.</p>	<input checked="" type="checkbox"/>	<input type="checkbox"/>



4590 Beech Street, Norwood, Hamilton County, Ohio	Yes	No
<p>REC #7: Former coal storage area. An approximately 16,000 square foot area north of Building 10 was formerly used for coal storage. Coal remnants were observed on the ground surface and a User provided document states that six (6) inches of coal was observed below the ground surface during soil sampling. Coal has the potential to leach heavy metals into the environment; therefore this area represents a REC.</p> <p>REC #8: South adjoining printing operations. Printing operations have been conducted on the south adjoining property (4500 Beech Street) for over 100 years. Printing operations have the potential to release VOCs and other chemicals of concern into the environment. Based on the concern for potential vapor intrusion from historical VOC releases, the printing operations at the south adjoining property represents a REC.</p> <p>REC #9: Transformer Pad. The laboratory analytical results from the 1994 soil sampling indicated that pad and the soils around the pad were contaminated with PCBs. According to the aforementioned Phase I ESA, remediation via soil excavation was performed in vicinity of the PCB contaminated soils. The document states that "soil cores were taken until clean samples were obtained"; however, there is no analytical data provided and no other documentation of closure sampling. Based on the lack of substantial closure information for the soil removal, the soil and pad represent a REC.</p>		
Historical Recognized Environmental Condition (HREC)²	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Controlled Recognized Environmental Condition (CREC)³	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<p><i>De minimis</i> Condition⁴</p> <p><i>De minimis</i> #1: Oil buckets. Several five (5)-gallon buckets of oil were observed in various portions of the Buildings and in a courtyard. Three of the buckets were observed to be leaking. Based on the small amount of oil in each spill (5-gallons, maximum), they represent a <i>de minimis</i> condition.</p> <p><i>De minimis</i> #2: Former drum storage. Circular rings from 55-gallon drums were observed imprinted into the asphalt west of Building 10. No staining was noted; therefore, the former drum storage area represents a <i>de minimis</i> condition.</p> <p><i>De minimis</i> #3: Flammables Shed. A "Flammables Shed" was observed east of Building 10. No staining was observed; therefore the shed represents a <i>de minimis</i> condition. The interior of the shed was inaccessible. As such, if evidence of a release is observed in the future, this area will need to be investigated as a REC.</p>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<p>¹ The presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. <i>De minimis</i> conditions are not recognized environmental conditions.</p> <p>² A past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls.</p>		



4590 Beech Street, Norwood, Hamilton County, Ohio	Yes	No
<p>³ A recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.</p> <p>⁴ A condition that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be <i>de minimis</i> conditions are not recognized environmental conditions nor controlled recognized environmental conditions.</p>		

Figure 4 depicts the locations of the RECs and de minimis conditions.

In addition to the RECs and de minimis conditions listed above, SRW observed several Universal Waste and Business Environmental Concerns:

- Wood Block Flooring: the wood block flooring observed in Buildings 1, 3, and 10 was oil soaked in certain locations. Depending on the chemicals in the oil, the disposal of the wood block flooring may be regulated if they are removed.
- Residual waste: The composition of the oils and various unknown liquids throughout the buildings and on the Property need to be characterized before they can be properly removed and disposed.
- Universal Wastes: SRW observed a large amount of mercury-containing fluorescent light tubes, potential PCB- containing fluorescent light ballasts, mercury containing thermostats, potential lead-acid batteries in emergency exit and lighting fixtures, etc. which need to be disposed of under RCRA guidelines.
- Asbestos and lead paint: SRW observed pipe wrapping with Asbestos warning labels, other potential asbestos containing materials, and possible lead paint.

Based on the above observations and the age of the buildings, SRW recommends a Hazardous Materials Assessment to inventory and sample potential Universal Wastes.

1.4 Opinions and Recommendations

Based on the foregoing, SRW does recommend additional assessment of the RECs identified at the Property.

2.0 INTRODUCTION

2.1 Purpose

The purpose of the Phase I was to identify “recognized environmental conditions” in connection with the Property, to the extent feasible, and pursuant to the processes as defined by the American Society



for Testing & Materials (ASTM) *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM E 1527-13).

In preparing this Phase I report, SRW has striven to balance between competing goals of identifying signs of RECs and a scope of work limited by both time and cost restraints.

2.2 Methodology Used

This Phase I was conducted in general accordance with the methods and procedures specified in ASTM E 1527-13. The following scope of work was performed for this Phase I:

1. The historical utilization of the Property and adjoining properties was characterized by evaluating a combination of reasonably ascertainable resources, as specified in Section 8.1.4 of ASTM E 1527-13. The resources used in this Phase I report are cited in the references (Section 10.0).
2. A review of databases obtained from federal, state, and local environmental agencies having jurisdiction in the area was conducted to identify facilities that currently use, store, treat, and/or dispose of chemical/hazardous substances, and/or store petroleum products, or previously conducted these activities. Pertinent regulatory agency files and/or records were reviewed at the discretion of the Environmental Professional.
3. Interviews with the key Property manager, owner(s), and occupant(s) of the Property were conducted to obtain historical information regarding present and past operations of the Property and adjoining properties.
4. A reconnaissance of the Property (May 21, 2015) was conducted to provide detailed descriptions of its condition and improvements, to confirm the locations of facilities identified in the regulatory databases, and to identify physical evidence that might indicate the existence of recognized environmental conditions in connection with the Property.
5. The physical setting, geology, and hydrology of the Property were evaluated by reviewing the appropriate USGS topographic map. Additional sources used are referenced in Section 10.0.
6. This Phase I report was prepared describing the methodologies and results of the assessment.

2.3 User Reliance

This Phase I report has been prepared for the exclusive use of CORE Redevelopment and the City of Norwood for specific application to the Property located at 4590 Beech Street in Norwood, Hamilton County, Ohio. This Phase I report and its findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other third party, nor used by any other party, in whole or in part, without the prior written consent of SRW.



2.4 Limiting Conditions

2.4.1 Data Gaps and Failures

Based on the information that was reasonably ascertainable, a historical data failure, as defined in ASTM 1527-13, has occurred in attempting to document the history of the Property back to 1940 or the first developed use of the Property in five year increments. However, based on the information obtained, the lack of documentation does not represent a significant data gap and did not affect the ability to identify potential REC(s) associated with the Property.

2.4.2 Limitations and Exceptions

This Phase I has been conducted to permit formulation of an opinion as to the potential for recognized environmental conditions in connection with the Property. Opinions relative to the existence of recognized environmental conditions given in this Phase I report are based upon information derived from the most recent Property reconnaissance (May 21, 2015) and from other activities described herein. CORE Redevelopment and the City of Norwood are herewith advised that the conditions observed by SRW are subject to change, and that such changes could render our opinions invalid. Furthermore, please be aware that SRW cannot warrant or guarantee that not finding indicators of chemical/hazardous substances or petroleum products means that such materials do not exist on the Property.

The findings and opinions conveyed via this Phase I report are based on information obtained from a variety of sources that SRW believes are reliable. The accuracy and completeness of such information varies among information sources. Interviews are limited by the quality and completeness of answers provided to the proposed questions during the interview(s). SRW is not obligated to identify mistakes or insufficiencies in information provided, and assumes no responsibility for information provided by others, whether they are under contract to SRW or not. For the Phase I, SRW utilized the services of Environmental Data Resources, Inc. (EDR) for the review of environmental regulatory databases. EDR relies upon published data from federal, state, and local government sources. Neither EDR nor SRW can warrant the accuracy or reliability of the information included in the EDR regulatory report, which we relied upon in drawing the conclusions stated elsewhere in this Phase I report. The extent of historical research performed by SRW is limited to availability, cost, and timeliness of utilizing various resources.



In performing this Phase I, SRW has endeavored to observe the standard of care as described in ASTM's *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM E 1527-13). No other warranty is expressed or implied. ASTM E 1527-13 provides a detailed description of the Phase I process. We recommend that the user of this report be familiar with ASTM E 1527-13. SRW accepts no responsibility for conclusions drawn by any party who claims a lack of familiarity with ASTM E 1527-13.

A Phase I is not intended to wholly eliminate uncertainty regarding the possibility of recognized environmental conditions in connection with the Property. This report is intended to reduce, but not eliminate, uncertainty regarding the possibility of recognized environmental conditions.

SRW made appropriate inquiries in the performance of the Phase I. This does not mean an exhaustive search was performed; the cost of information or time required gathering it may outweigh its usefulness.

In order for the prospective purchaser to claim protection from CERCLA liabilities, the acquisition of the suspect Property must be completed within 180 days after completion of the Phase I ESA.

It should be noted that CORE Redevelopment and the City of Norwood are the only intended beneficiaries of this Phase I report. This Phase I report and its findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other third party, nor used by any other party, in whole or in part, without the prior written consent of SRW. Reliance on this Phase I report by any party other than those identified could result in reliance on assumptions whose extent and nature would distort the meaning and impact of the findings and opinions related in this Phase I report. SRW is available to contract with other parties to develop findings and opinions related specifically to such other parties' unique risk management concerns.

In addition, this Phase I report excludes all Non-Scope Considerations identified in Section 13 of ASTM E 1527-13, including assessment of asbestos-containing building materials, biological agents, cultural and historic resources, ecological resources, endangered species, health and safety, indoor air quality (i.e. vapor intrusion) unrelated to releases of petroleum or



hazardous substances, industrial hygiene, lead-based paint, lead in drinking water, mold, radon, regulatory compliance, wetlands, and high voltage power lines in connection with the Property. This list is not intended to be all-inclusive.

3.0 **PROPERTY INFORMATION**

3.1 **Property Name and Address**

Name:	Former US Playing Card
Street Address:	4590 Beech Street
City, County, State:	Norwood, Hamilton County, Ohio
Zip:	45212
Latitude/Longitude:	39° 9'31.92" north, 84°26'29.11" west
Property location/intersection:	East side of Beech Street across from Park Avenue

3.2 **Legal Description**

Number of Parcels:	One
Auditor's Parcel Nos.:	651-0019-0125

A copy of the legal description is provided in Appendix 1.

3.3 **Property Description**

Physical Shape:	Irregular
Approximate Acres in Size:	20.72
Number of Structures:	8 interconnected and outbuildings
Topography:	Relatively flat with retention pond
Zoning:	M2 - manufacturing

3.4 **Building Information**

Number of Buildings/Stories:	8 interconnected buildings, 2-4 stories
Gross Square Footage:	700,000
Year Constructed:	Beginning in 1900
Current Use:	Boiler system active in Building 9, Ryan Carpentry leases Building 10.
Building Foundations:	slab-on-grade concrete; poured concrete walls in basements
Exterior Wall Framing:	Brick
Exterior Façade:	Brick
HVAC type:	Gas and electric
Paving:	Asphalt, gravel



Utilities

Sanitary Sewers:	Metropolitan Sewer District
Storm Sewer:	Metropolitan Sewer District
Drinking Water:	Greater Cincinnati Water Works
Natural Gas:	Duke Energy
Electric:	Duke Energy

3.5 Current Uses and Activities of the Property

Figure 2 depicts the Property and surrounding properties.

☒ Commercial: Former playing card manufacturers, currently vacant

3.6 Owners and Occupants of the Property

Current Owner:	<u>Norwood Beech, LLC</u>
Number of Tenant Spaces:	<u>One; Building 10</u>
Tenants:	<u>Ryan Carpentry</u>

3.7 Activity and Use Limitations

SRW did not discover any indication that activity or use limitations, in the forms of institutional controls or engineering controls, exist in connection with the Property.

3.8 Current Land Uses and Tenants of Adjoining Properties

The current use of the adjoining properties was observed from the subject Property as follows:

North:	<u>Norwood Operations Buildings (1001 Duck Creek Road)</u>
East:	<u>Interstate-71</u>
South:	<u>Multi-Color Corporation (4500 Beech Street)</u>
West:	<u>Residences (2641 Park Ave., 4543-4545 Beech St., and 2642 Kenilworth Ave.)</u>
Northwest:	<u>Siemens Motor Manufacturers (4620 Forest Avenue)</u>

3.9 Current Land Uses in Surrounding Area

The Property is located in a mixed residential, commercial, and manufacturing area.

4.0 USER-PROVIDED INFORMATION

A copy of the Phase I Environmental Site Assessment User Questionnaire is provided in Appendix 2.



4.1 Specialized Knowledge

SRW has no specialized knowledge of the Property beyond the information obtained through the research conducted and provided in this report. The Property owner, tenants, and individuals interviewed throughout this investigation have not reported any specialized knowledge of the Property beyond that which is contained in this report. The Property purchaser stated that he observed stained floors inside the buildings.

4.2 Purchase Price to Fair-Market Value Evaluation

Eric Seal, representative of Core Redevelopment, potential Property purchaser, believes that the purchase price of the Property reasonably reflects the fair market value of the Property.

4.3 Owner, Property Manager, and Occupant Information

Mike Ryan, a representative of Ryan Carpentry, a tenant of Building 10, was interviewed by SRW on May 21, 2015.

4.4 Reason for Performing Phase I ESA

The Phase I ESA is being prepared as part of environmental due diligence prior to the purchase of the Property.

4.5 Title Records/Environmental Liens and Activity Use Limitations

SRW did not discover any indication that activity or use limitations, in the forms of institutional controls or engineering controls, exist in connection with the Property.

5.0 RECORDS REVIEW

5.1 Standard Federal and State Environmental Record Sources

A review of federal and state regulatory databases, maintained by the United States Environmental Protection Agency (USEPA) and the Ohio Environmental Protection Agency (OEPA), was conducted by EDR. As recommended by ASTM E 1527-13, a search radius of up to one mile was used to identify and locate facilities that may operate stationary storage tanks, handle, generate, or dispose of hazardous, industrial, and/or solid waste, or have reported contamination of soil and/or groundwater. The federal and state database reviews, the date the databases were updated, and the results are described in the EDR regulatory report contained in Appendix 3. A map, showing the



Property and any identified facilities, is also provided in Appendix 3. The following table summarizes the databases reviewed and the number of facilities identified.



MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
<i>Federal NPL site list</i>								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
<i>Federal Delisted NPL site list</i>								
Delisted NPL	1.000		0	0	0	0	NR	0
<i>Federal CERCLIS list</i>								
CERCLIS	0.500		0	0	1	NR	NR	1
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
<i>Federal CERCLIS NFRAP site List</i>								
CERC-NFRAP	0.500	1	0	0	1	NR	NR	2
<i>Federal RCRA CORRACTS facilities list</i>								
CORRACTS	1.000		0	0	0	1	NR	1
<i>Federal RCRA non-CORRACTS TSD facilities list</i>								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
<i>Federal RCRA generators list</i>								
RCRA-LQG	0.250		1	1	NR	NR	NR	2
RCRA-SQG	0.250		0	1	NR	NR	NR	1
RCRA-CESQG	0.250		0	0	NR	NR	NR	0
<i>Federal institutional controls / engineering controls registries</i>								
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
LUCIS	0.500		0	0	0	NR	NR	0
<i>Federal ERNS list</i>								
ERNS	TP		NR	NR	NR	NR	NR	0
<i>State- and tribal - equivalent CERCLIS</i>								
OH SHWS	N/A		N/A	N/A	N/A	N/A	N/A	N/A
OH DERR	1.000	1	0	0	2	5	NR	8
<i>State and tribal landfill and/or solid waste disposal site lists</i>								
OH SWF/LF	0.500		0	0	0	NR	NR	0
<i>State and tribal leaking storage tank lists</i>								
OH LUST	0.500		0	3	15	NR	NR	18
OH UNREG LTANKS	0.500		0	2	0	NR	NR	2
INDIAN LUST	0.500		0	0	0	NR	NR	0



MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
OH UST	0.250		1	3	NR	NR	NR	4
OH AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
FEMA UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
OH ENG CONTROLS	0.500		0	0	0	NR	NR	0
OH INST CONTROL	0.500		0	0	0	NR	NR	0
OH HIST INST CONTROLS	0.500		0	0	0	NR	NR	0
OH HIST ENG CONTROLS	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
OH VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
OH BROWNFIELDS	0.500		0	0	1	NR	NR	1
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
OH SWRCY	0.500		0	0	1	NR	NR	1
OH HIST LF	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL	TP		NR	NR	NR	NR	NR	0
OH CDL	TP		NR	NR	NR	NR	NR	0
US HIST CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
OH ARCHIVE UST	0.250		1	3	NR	NR	NR	4
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
OH SPILLS	TP	1	NR	NR	NR	NR	NR	1
OH SPILLS 90	TP		NR	NR	NR	NR	NR	0



MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
OH SPILLS 80	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	1	0	1	NR	NR	NR	2
DOT OPS	TP		NR	NR	NR	NR	NR	0
DOD	1.000		0	0	0	0	NR	0
FUDS	1.000		0	0	0	0	NR	0
CONSENT	1.000		0	0	0	0	NR	0
ROD	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ICIS	TP	1	NR	NR	NR	NR	NR	1
PADS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
FINDS	TP	1	NR	NR	NR	NR	NR	1
RAATS	TP		NR	NR	NR	NR	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
OH TOWNGAS	1.000		0	0	0	0	NR	0
OH UIC	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250	1	0	0	NR	NR	NR	1
OH DRYCLEANERS	0.250		0	0	NR	NR	NR	0
OH NPDES	TP		NR	NR	NR	NR	NR	0
OH AIRS	TP		NR	NR	NR	NR	NR	0
OH USD	0.500		0	0	0	NR	NR	0
OH HIST USD	0.500		0	0	0	NR	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
OH Financial Assurance	TP		NR	NR	NR	NR	NR	0
OH CRO	TP		NR	NR	NR	NR	NR	0
OH COAL ASH	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	1.000		0	0	0	0	NR	0
---------	-------	--	---	---	---	---	----	---



MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
EDR US Hist Auto Stat	0.250		0	3	NR	NR	NR	3
EDR US Hist Cleaners	0.250		0	3	NR	NR	NR	3
<u>EDR RECOVERED GOVERNMENT ARCHIVES</u>								
<i>Exclusive Recovered Govt. Archives</i>								
OH RGA LF	TP		NR	NR	NR	NR	NR	0
OH RGA LUST	TP		NR	NR	NR	NR	NR	0
- Totals --		7	3	20	21	6	0	57

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

N/A = This State does not maintain a SHWS list. See the Federal CERCLIS list.



The Property was identified in the EDR regulatory report under the Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) - No Further Remedial Action Planned (CERC-NFRAP), Resource Conservation and Recovery Act (RCRA) Non-Generator/No Longer Regulated (NonGen/NLR), Ohio Division of Emergency & Remedial Response (OH DERR), NY MANIFEST, OH SPILLS, Integrated Compliance Information System (ICIS), and Facility Index System/ Facility Registry System (FINDS). The Property was assessed as a potential National Priority List site in 1985; however the initial findings concluded NFRAP. The Property used to be a RCRA Small Quantity Generator of spent halogenated solvents and methyl chloroform with no violations reported. The DERR listing was for the CERCLIS assessment. The NY MANIFEST listing was for the transportation of miscellaneous PCB wastes. The SPILLS listing was for a diesel fuel spill in 1995. The ICIS listing was for several Clear Air Act violations.

The south adjoining facility, Multi-Color Corp., was listed as a RCRA Large Quantity Generator (LQG), OH Underground Storage Tank (UST), and OH Archive UST. The facility is a RCRA-LQG of ignitable wastes, barium, methyl-ethyl-ketone, non-halogenated solvents, tetrachloroethylene, trichloroethylene, acetone, 1-butanol, 2-butanone, methapyrilene, methyl-isobutyl-ketone, 2-nitropropane, methyl-benzene (or toluene), and/or dimethyl benzene (or xylene). The facility has received multiple violations related to pre-transport practices and container use and management from 2002 to 2012. The USTs are a 5,000-gallon tank listed as currently in use which stores “other petroleum distillate” and three 5,000-gallon tanks listed as currently in use which store hazardous substances. The remaining facilities identified in the EDR regulatory report appear unlikely to impact the Property based on their distance.

5.2 Agency File and Records Review

A file review of the Property and the south adjoining property was conducted which revealed several Hazardous Waste Handler documents related to the south adjoining property. The violations noted were for pre-transport handling and container use management (i.e. mislabeled containers, extended storage times, etc.). No violations for spills or releases were reported. The documents are provided as Appendix 4.

5.3 Additional Environmental Record Sources

The User provided SRW with several previous environmental investigation reports (Appendix 5). Three were asbestos surveys which determined the location and quantity of asbestos containing



materials throughout the buildings. In addition, there was soil testing documentation from Proactive Consulting Services dated October 19, 1994. The soil testing was for volatile organic compounds (VOCs) and/or polychlorinated biphenyls (PCBs) in soils from the solvent shed, transformer pad and surrounding soils, the hazardous waste storage pad, and the location of three USTs removed in 1988. The laboratory analytical results indicated that the soils around the solvent shed area (southwest corner of Building 10) were contaminated with tetrachloroethylene (TCE) and the transformer pad (east of Building 9) samples were contaminated with PCBs. According to the 2011 Phase I ESA, soil excavations were performed in vicinity of both the PCB and TCE contaminated soils. The document states that “soil cores were taken until clean samples were obtained”; however, there is no analytical data provided and no other documentation of closure sampling.

No chemicals of concern were detected in the laboratory analytical results from the former UST area; however, the samples were collected from within the former tank pit from fill materials. No native soils were sampled. No closure documentation is available from the 1988 removal.

No chemicals of concern were detected in the laboratory analytical results from the former Hazardous Waste storage area; however, the soil samples were only analyzed for VOCs. Hazardous Wastes can contain other chemicals of concern and there is no comprehensive sampling information.

A Phase I ESA completed by Industrial Realty Group, LLC in 2013 that “no current RECs have been identified on the Property”, but that discolored soils were observed around the transformers near the southeast corner of Building 7. During SRW’s reconnaissance on May 21, 2015, no discolored soils were observed in the vicinity of those transformers.

5.4 Physical Setting Sources

5.4.1 Topography

The Property is relatively flat, and is situated at an approximate elevation of 620 feet above mean sea level (amsl), based on a review of the 7.5-Minute Topographic Quadrangle Map of Cincinnati-East, Ohio (Figure 1). Surface water on the Property is directed into municipal storm sewers and a retention pond near the center of the Property.



5.4.2 Soils

The Property is underlain by soils of the Udorthents-Urban land complex. Udorthents soils are deep, and sloping. Udorthents soils formed in loess and are found on till plains. The Urban land part of the complex is covered by streets, parking lots, and structures that obscure or alter the soils making their identification not feasible.

5.4.3 Geology

The Property is underlain by loess, which overlies a paleosol of Upper Ordovician or earlier age. Limestone and shale bedrock underlies the paleosol and is encountered at depths of less than 40 feet below ground surface (bgs).

5.4.4 Hydrogeology

Groundwater in the area is generally encountered in the underlying bedrock at depths of 25 to 35 feet bgs. Based on the surficial topography and hydrology, the flow of groundwater is generally to the south, toward the Ohio River.

5.4.5 Surface Water Bodies

The nearest surface water body is a retention pond located near the center of the Property. Historically the retention pond was used for fire suppression.

5.4.6 Vapor Migration Potential

Based on the characteristics of the soil underlying the Property, the depth to groundwater, and the assumed direction of groundwater flow, the potential for vapor migrations is considered medium.

5.5 Historical Use Information

5.5.1 Sources Relied Upon

<u>SOURCE</u>	<u>REVIEWED</u>	<u>NOT REVIEWED</u>	<u>REASON FOR NOT BEING REVIEWED</u>
Aerial Photographs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
City Directories	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Interviews	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Other Land Use Records	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not deemed necessary




<u>SOURCE</u>	<u>REVIEWED</u>	<u>NOT REVIEWED</u>	<u>REASON FOR NOT BEING REVIEWED</u>
Prior Environmental Reports	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Sanborn Fire Insurance Maps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Title Records	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not deemed necessary

5.5.2 Historical Uses of the Property

4590 Beech Street in Norwood, Hamilton County, Ohio		
YEAR	SOURCE	PROPERTY
1917	SB	Developed as US Playing Card with 10 buildings (some interconnected), a rail spur, and a 300,000 gallon reservoir
1922	SB	Similar to the 1917 Sanborn map.
1938	AP	Developed as US Playing Card.
1949	AP	Similar to the 1949 aerial photograph.
1950	SB	Five additional buildings were added.
1956	AP	Similar to the 1949 aerial photograph, several buildings added.
1960	AP	Similar to the 1956 aerial photograph.
1968	AP	Similar to the 1956 aerial photograph.
1975	AP	Similar to the 1956 aerial photograph.
1977	AP	Similar to the 1956 aerial photograph.
1981	SB	Similar to the 1950 Sanborn map.
1985	AP	Similar to the 1956 aerial photograph.
1988	AP	Similar to the 1956 aerial photograph.
1994	AP	Similar to the 1956 aerial photograph.
1998	AP	Similar to the 1956 aerial photograph.
2001	AP	Similar to the 1956 aerial photograph.
2005	AP	Similar to the 1956 aerial photograph. Several buildings were demolished.
2009	AP	Similar to the 1956 aerial photograph.
2010	AP	Similar to the 1956 aerial photograph.
2011	AP	Similar to the 1956 aerial photograph.
AP – aerial photo CD – City Directory INTER – Interview SB – Sanborn EDR – EDR database Other - Specify		


5.5.3 Historical Uses of the Adjoining Properties

North – 1001 Duck Creek Road		
Year	Source	Property
1917	SB	Not depicted.
1922	SB	A railroad adjoined the Property to the north; nothing was depicted beyond the railroad.



North – 1001 Duck Creek Road		
Year	Source	Property
1938	AP	Area appears razed.
1949	AP	Similar to the 1938 aerial photograph.
1950	SB	Not depicted.
1956	AP	Similar to the 1938 aerial photograph.
1960	AP	Similar to the 1938 aerial photograph.
1968	AP	Developed with a small commercial building.
1975	AP	Developed with several commercial buildings. Semi-trailers were visible.
1977	AP	Similar to the 1975 aerial photograph.
1981	SB	Not depicted.
1985	AP	Similar to the 1975 aerial photograph.
1988	AP	Similar to the 1975 aerial photograph.
1994	AP	Similar to the 1975 aerial photograph.
1998	AP	Similar to the 1975 aerial photograph. No semi-trailers were shown.
2001	AP	Similar to the 1998 aerial photograph.
2005	AP	Similar to the 1998 aerial photograph.
2009	AP	Similar to the 1998 aerial photograph.
2010	AP	Similar to the 1998 aerial photograph.
2011	AP	Similar to the 1998 aerial photograph.
AP – aerial photo SB – Sanborn CD – City Directory		

East – no address		
Year	Source	Property
1917	SB	Not depicted.
1922	SB	Not depicted.
1938	AP	Developed as a road.
1949	AP	Similar to the 1938 aerial photograph.
1950	SB	Not depicted.
1956	AP	Similar to the 1949 aerial photograph.
1960	AP	Similar to the 1949 aerial photograph.
1968	AP	Similar to the 1949 aerial photograph.
1975	AP	Interstate-71.
1977	AP	Similar to the 1971 aerial photograph.
1981	SB	Not depicted.
1985	AP	Similar to the 1971 aerial photograph.
1988	AP	Similar to the 1971 aerial photograph.
1994	AP	Similar to the 1971 aerial photograph.
1998	AP	Similar to the 1971 aerial photograph.
2001	AP	Similar to the 1971 aerial photograph.
2005	AP	Similar to the 1971 aerial photograph.
2009	AP	Similar to the 1971 aerial photograph.



East – no address		
Year	Source	Property
2010	AP	Similar to the 1971 aerial photograph.
2011	AP	Similar to the 1971 aerial photograph.
AP – aerial photo SB – Sanborn CD – City Directory		

South – 4500 Beech Street		
Year	Source	Property
1917	SB	Developed as United States Printing Company.
1922	SB	Similar to the 1917 Sanborn map.
1938	AP	Commercially developed.
1949	AP	Similar to the 1938 aerial photograph.
1950	SB	Similar to the 1917 Sanborn map.
1956	AP	Similar to the 1938 aerial photograph.
1960	AP	Similar to the 1938 aerial photograph.
1968	AP	Similar to the 1938 aerial photograph.
1975	AP	Similar to the 1938 aerial photograph.
1977	AP	Similar to the 1938 aerial photograph.
1981	SB	Similar to the 1917 Sanborn map.
1985	AP	Similar to the 1938 aerial photograph.
1988	AP	Similar to the 1938 aerial photograph.
1994	AP	Similar to the 1938 aerial photograph.
1998	AP	Similar to the 1938 aerial photograph.
2001	AP	Similar to the 1938 aerial photograph.
2005	AP	Similar to the 1938 aerial photograph.
2009	AP	Similar to the 1938 aerial photograph.
2010	AP	Similar to the 1938 aerial photograph.
2011	AP	Similar to the 1938 aerial photograph.
AP – aerial photo SB – Sanborn CD – City Directory		

West – 2641 Park Avenue, 4543-4545 Beech Street, 2642 Kenilworth Avenue		
Year	Source	Property
1917	SB	Developed as residential plots with no visible buildings.
1922	SB	Not depicted.
1938	AP	Developed as residential plots with no visible buildings.
1949	AP	Residences.
1950	SB	Residences.
1956	AP	Similar to the 1949 aerial photograph.
1960	AP	Similar to the 1949 aerial photograph.
1968	AP	Similar to the 1949 aerial photograph.
1975	AP	Similar to the 1949 aerial photograph.
1977	AP	Similar to the 1949 aerial photograph.



West – 2641 Park Avenue, 4543-4545 Beech Street, 2642 Kenilworth Avenue		
Year	Source	Property
1981	SB	Residences.
1985	AP	Similar to the 1949 aerial photograph.
1988	AP	Similar to the 1949 aerial photograph.
1994	AP	Similar to the 1949 aerial photograph.
1998	AP	Similar to the 1949 aerial photograph.
2001	AP	Similar to the 1949 aerial photograph.
2005	AP	Similar to the 1949 aerial photograph.
2009	AP	Similar to the 1949 aerial photograph.
2010	AP	Similar to the 1949 aerial photograph.
2011	AP	Similar to the 1949 aerial photograph.
AP – aerial photo SB – Sanborn CD – City Directory		

All documentation supporting the historical use of the Property and adjoining properties is included in Appendix 6.

5.6 Vapor Encroachment Condition (VEC)

A Vapor Encroachment Tier 1 Screening has revealed that a VEC is possible based on nearby potential sources including USTs and 100 years of printing operations on the south adjoining property.

6.0 INTERVIEWS

6.1 Interview With Owner Representative

Mr. Mike Ryan was interviewed during the reconnaissance on May 21, 2015. Mr. Ryan has leased Building 10 on the Property since 2010 and provided information regarding the historical use of Building 10. Mr. Ryan stated that Building 10 was originally a cafeteria for US Playing Card, then it was converted to a maintenance building. The only environmental concern Mr. Ryan had was related to the “creosote-soaked” wood block flooring throughout Building 10.

6.2 Interview With Site Manager

As discussed above, Mr. Ryan was interviewed regarding the historic and current uses of the Property.



6.3 Interview With Local Government Officials

SRW contacted the Norwood Fire Department (513-458-4520), Norwood Health Department (513-458-4600), and Hamilton County Local Emergency Planning Commission (513-263-8010) on May 5, 2015 to obtain information regarding past emergency responses, spills and accidents at the Property. No records were available for review.

6.4 Interviews With Others

SRW did not interview persons other than those specifically referenced in this report.

7.0 INFORMATION FROM PROPERTY RECONNAISSANCE

Mr. Ihor Melnyk, SRW's Senior Project Manager, Ms. Laura Welsh, SRW's Environmental Professional, and Mr. Fred Wolnitzek, SRW's Environmental Professional/Staff Geologist, inspected the Property on May 21, 2105. Mr. Melnyk, Ms. Welsh, and Mr. Wolnitzek visually inspected the interior and exterior of the Property and were unaccompanied. Weather conditions at that time included clouds and a temperature of approximately 70 degrees Fahrenheit. Several doors within the buildings were locked and inaccessible. The exteriors of the adjoining properties were also visually examined. Photographs obtained during the Property reconnaissance are provided in Appendix 7. A site map showing the historical operations locations was found during the reconnaissance. A copy of this map is provided as Figure 3.

7.1 Hazardous Substances and Petroleum Products Used or Stored at the Property

A full, 55-gallon drum labeled "Hazardous Waste" was observed in the eastern hallway between Buildings 1 and 3. No leaking was observed on the floor by the drum. Several five (5) gallon buckets of oil were observed throughout the buildings. Three of the observed buckets represent *de minimis* conditions:

- 1). a full bucket which was catching oil leaking from pipes on the ceiling near the center of the first floor in Building 1. The bucket was surrounded by a puddle of oil contained by oil booms.
- 2). a bucket of oil in the eastern basement of Building 1 which had leaked and spread across the floor; and
- 3). a five (5) gallon steel can of oil was leaking onto the ground in the courtyard between Buildings 1 and 3.



In addition, oil-soaked wood block flooring was noted in Building 1 (Floors 1, 2, and 4), Building 3 (Floor 4), Building 10, and hallways between Buildings 1 and 3.

A “Flammables Shed” was observed east of Building 10. No staining was observed; therefore the shed represents a *de minimis* condition. The interior of the shed was inaccessible. As such, if evidence of a release is observed in the future, this area will need to be investigated as a REC.

Two former drum storage areas were observed on the Property. The drum storage area located southeast of Building 1 was fenced in and no staining was observed. The second drum area was located west of Building 10 and was noticed by circular imprints of 55-gallon drums into the asphalt. No staining was observed.

7.2 Unidentified Substance Container

As stated above, a full, 55-gallon drum labeled “Hazardous Waste” and several five (5) gallon buckets containing oil from an unknown origin were observed. In addition a 55-gallon polyethylene drum containing an unknown substance was observed in the courtyard between Buildings 1 and 3.

7.3 Aboveground Storage Tanks (ASTs)

One approximately 150-gallon AST containing diesel fuel was observed in the basement of Building 9. The remote fill port was observed on the east side of the building. No staining was observed. The AST had a secondary containment for spills beneath it. Two locations of possible former ASTs were observed in the courtyard between Buildings 1 and 3 and on the northern side of the Property. No staining was observed on the ground near the possible former ASTs.

7.4 Underground Storage Tanks (USTs)

A former fill port and vent pipe were observed in the courtyard between Buildings 1 and 3. According to 1994 soil sampling documentation provided by the User, this is the location where three USTs were removed in 1988. Fill (sand) was observed near the surface. Although soil sampling was performed in 1994 in the vicinity of the former USTs, the samples were collected from fill materials within the former tank pit and not from the native soils.

In addition, a possible former fill port and pump island were observed near the northeast corner on the exterior of Building 3. The possible fill port and pump island characterize a suspect UST.



7.5 Hazardous Waste Generation Activities

None observed on the Property during the reconnaissance.

7.6 Solid Waste Disposal

No areas filled or graded by non-natural causes, suggesting trash construction debris, demolition debris, or other solid waste disposal or mounds or depressions suggesting solid waste disposal were observed on the Property.

7.7 PCBs

Several pad-mounted transformers were observed outside of the buildings:

- Two transformers were observed on the south side of Building 7. One was not labeled, one was labeled non-PCB.
- An unlabeled transformer was observed in the courtyard between Buildings 4 and 6, adjacent to the north side of Building 6.
- Four transformers were observed on the east side of Building 9. Three were labeled with their PCB content (approximately 56 parts per million) and one was labeled non-PCB.
- Several transformers were observed northeast of Building 10 in an inaccessible, fenced-off area. No labels were visible.

In addition, one hydraulic elevator was observed in Building 1. The hydraulic tank was located in the basement and the PCB content was not labeled. No staining was observed.

7.8 Other

TYPE	OBSERVED	LOCATION	COMMENTS
Pits	Yes	Building 5 east end	Pit of unknown use
Ponds	Yes	East of Building 9	Reservoir for former fire suppression system
Lagoons/impoundments	No		
Stained soil	Yes	Courtyard between Buildings 1 and 3	Leaking 5 gallon container
Drains/sumps	Yes	Throughout buildings	Corrosion noted around two (see below)
Stressed vegetation	No		
Stains on floors, walls, ceilings	Yes	Throughout buildings	Floor stained in several locations from oil spills (see Section 7.1)
Wastewater discharges	No		



TYPE	OBSERVED	LOCATION	COMMENTS
Septic systems	No		
Wells	Yes	Northeast corner of Property	Former Production Well
Foul odors	No		
Pools of liquid	Yes	Building 1, Floor 1 and basement	Oil bucket overflows, pipe dripping from ceiling into bucket/on ground.
Spills or releases	Yes	Building 1, Floor 1 and basement	Oil bucket overflows
Landfilling	No		
Corrosion	Yes	Paste mix room, Building 1 and basement, Building 7.	On floor and around two drains in Building 1. On floor in rectangular shape in Building 7.

Two pyramid shaped concrete pillars were observed in a lowered area on the south side of the courtyard between Buildings 6 and 7. Piping was observed on the ground surface running parallel to the pillars, and an approximately 4" pipe between the pillars extended vertically into the ground. An emergency shut off button was observed on the wall next to the pillars. Because of the unknown nature of the pillars (possibly an AST) combined with the subsurface piping, the area represents a REC.

An approximately 16,000 square foot area north of Building 10 was formerly used for coal storage. Coal remnants were observed on the ground surface and a User provided document states that six (6) inches of coal was observed below the ground surface during soil sampling. Coal has the potential to leach heavy metals into the environment; therefore this area represents a REC.

8.0 NON-SCOPE SERVICES

Non-scope services were not contracted as part of this assessment.

9.0 EVALUATION

9.1 Summary

The findings of the Phase I for the Property are presented below.

1. The Property has been occupied by US Playing Card Company since around 1900. The Property became vacant when US Playing Card ceased operations in 2010 and has remained vacant since.



2. The historical uses of the adjoining properties included a rail line (since 1922) and commercial buildings (including Norwood's Operations Buildings) to the north from 1968-present; a road (1938-1968) and Interstate-71 (1975-present) to the east; various printing companies to the south (1917-present); and residences to the west (1949-present).
3. Several indications of releases were observed during the reconnaissance:
 - A five (5)-gallon bucket was catching an oil drip from the ceiling on the first floor of Building 1. The bucket had overflowed and oil was on the floor surrounded by booms.
 - A five (5)-gallon bucket filled with oil was leaking onto the floor in the basement of Building 1. The oil had been spread across the floor by a water leak.
 - A five (5)-gallon steel container of oil was observed in the courtyard between Buildings 1 and 3. The container had leaked onto the grass and staining was observed.
 - Heavy corrosion was observed in the "paste mix room" on the first floor in Building 1. There was corrosion across the floor and surrounding floor drains. In addition, corrosion was observed in the basement of Building 7 in a rectangular pattern.
4. The Property was identified in the EDR regulatory report under CERC-NFRAP, RCRA NonGen/NLR, OH DERR, NY MANIFEST, OH SPILLS, ICIS, and FINDS. The Property was assessed as a potential National Priority List site in 1985; however the initial findings concluded NFRAP. The Property used to be a RCRA Small Quantity Generator of spent halogenated solvents and methyl chloroform with no violations reported. The DERR listing was for the CERCLIS assessment. The NY MANIFEST listing was for the transportation of miscellaneous PCB wastes. The SPILLS listing was for a diesel fuel spill in 1995. The ICIS listing was for several Clear Air Act violations.
5. The remaining facilities identified in the EDR regulatory report appear unlikely to impact the Property based on their distance and/or regulatory compliance status.
6. Environmental sampling conducted in 1994 discovered soil contamination in the vicinity of the former solvent shed and transformer pad. These areas were subsequently remediated via soil excavation; however, confirmation samples were not analyzed. In addition, soil samples collected in the vicinity of the USTs removed in 1988 were non-detect; however, they were from the fill in the former tank pit. Soil samples were also collected in the former Hazardous Waste area north of Building 10. The soil samples were analyzed for only VOCs. No evidence of contamination was observed in the laboratory analytical results; however, Hazardous Wastes can contain other chemicals of concern.
7. SRW observed a "Flammables Shed" east of Building 10. No staining or odors were observed; therefore it represents a *de minimis* condition. SRW also observed a former drum storage area (determined by circular rings from the drums imprinted into the asphalt) west of Building 10. No staining was observed; therefore, the former drum storage area represents a *de minimis* condition. Two pyramid shaped concrete pillars were observed in a basement-level area on the south side of the courtyard between Buildings 6 and 7. Piping was observed on the ground surface running parallel to the




pillars, and an approximately 4" pipe between the pillars extended vertically into the ground. An emergency shut off button was observed on the wall next to the pillars.

8. The conclusion of the Vapor Encroachment Tier 1 Screening is a VEC cannot be ruled out based on nearby potential sources including USTs and 100 years of printing operations on the south adjoining property.

9.2 Findings and Conclusions

SRW has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM 1527-13 at 4590 Beech Street in Norwood, Hamilton County, Ohio. This assessment has revealed no evidence of RECs in connection with the Property except for the following:

4590 Beech Street, Norwood, Hamilton County, Ohio	Yes	No
<p>Recognized Environmental Condition (REC)¹</p> <p>REC #1: Heavy corrosion. Heavy corrosion was noted on the floor and surrounding the floor drains in the "paste mix room" on the first floor in Building 1. In addition, corrosion was observed in the basement of Building 7 in a rectangular shape. The corrosion may have been caused by a chemical which could leach through the concrete floor into the environment; therefore, the corrosion represents a REC.</p> <p>REC #2: Suspect UST. A possible fill port and possible pump island located near the northeast corner on the exterior of Building 3 represent a suspect UST. Based on the lack of information regarding the UST and its contents, and the possibility of an unknown release into the environment, it represents a REC.</p> <p>REC #3: Former USTs. During the May 21, 2015 site reconnaissance, SRW observed a possible former fill port and vent pipe adjacent to sandy fill materials on the south side of the courtyard between Buildings 1 and 3. In addition, a User provided document states that three USTs were removed from this area in 1988. User provided documentation indicates that soil sampling was performed in this area in 1994; however, the soil samples collected were from fill materials within the pit and not native materials. No closure documentation is available; therefore the former USTs represent a REC.</p> <p>REC #4: Contaminated soil south of Building 10. The laboratory analytical results from the 1994 soil sampling indicated that the soils around the solvent shed area were contaminated with tetrachloroethylene (TCE). According to the 2011 Phase I ESA, remediation via soil excavation was performed in vicinity of the TCE contaminated soils. The document states that "soil cores were taken until clean samples were obtained"; however, there is no analytical data provided and no other documentation of closure sampling. Based on the lack of substantial closure information for the soil removal, this area represents a REC.</p> <p>REC #5: Possible former AST area. Two pyramid shaped concrete pillars were</p>	<input checked="" type="checkbox"/>	<input type="checkbox"/>



4590 Beech Street, Norwood, Hamilton County, Ohio	Yes	No
<p>observed in a lowered area on the south side of the courtyard between Buildings 6 and 7. Piping was observed on the ground surface running parallel to the pillars, and an approximately 4" pipe between the pillars extended vertically into the ground. An emergency shut off button was observed on the wall next to the pillars. Because of the unknown nature of the pillars combined with the subsurface piping, the area represents a REC.</p> <p>REC #6: Former Hazardous Waste storage area. According to a User provided document, in 1994, soil samples were collected from the Hazardous Waste storage area north of Building 10. The soil samples were analyzed for VOCs. No VOCs were detected in the laboratory analytical results; however, Hazardous Wastes can contain other chemicals of concern. Based on the lack of substantial sampling information, the former Hazardous Waste storage area is a REC.</p> <p>REC #7: Former coal storage area. An approximately 16,000 square foot area north of Building 10 was formerly used for coal storage. Coal remnants were observed on the ground surface and a User provided document states that six (6) inches of coal was observed below the ground surface during soil sampling. Coal has the potential to leach heavy metals into the environment; therefore this area represents a REC.</p> <p>REC #8: South adjoining printing operations. Printing operations have been conducted on the south adjoining property (4500 Beech Street) for over 100 years. Printing operations have the potential to release VOCs and other chemicals of concern into the environment. Based on the concern for potential vapor intrusion from historical VOC releases, the printing operations at the south adjoining property represents a REC.</p> <p>REC #9: Transformer Pad. The laboratory analytical results from the 1994 soil sampling indicated that pad and the soils around the pad were contaminated with PCBs. According to the aforementioned Phase I ESA, remediation via soil excavation was performed in vicinity of the PCB contaminated soils. The document states that "soil cores were taken until clean samples were obtained"; however, there is no analytical data provided and no other documentation of closure sampling. Based on the lack of substantial closure information for the soil removal, the soil and pad represent a REC.</p>		
Historical Recognized Environmental Condition (HREC)²	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Controlled Recognized Environmental Condition (CREC)³	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<p><i>De minimis</i> Condition⁴</p> <p><i>De minimis</i> #1: Oil buckets. Several five (5)-gallon buckets of oil were observed in various portions of the Buildings and in a courtyard. Three of the buckets were observed to be leaking. Based on the small amount of oil in each spill (5-gallons, maximum), they represent a <i>de minimis</i> condition.</p> <p><i>De minimis</i> #2: Former drum storage. Circular rings from 55-gallon drums were observed imprinted into the asphalt west of Building 10. No staining was noted; therefore, the former drum storage area represents a <i>de minimis</i> condition.</p>	<input checked="" type="checkbox"/>	<input type="checkbox"/>



4590 Beech Street, Norwood, Hamilton County, Ohio	Yes	No
<p><i>De minimis</i> #3: Flammables Shed. A “Flammables Shed” was observed east of Building 10. No staining was observed; therefore the shed represents a <i>de minimis</i> condition. The interior of the shed was inaccessible. As such, if evidence of a release is observed in the future, this area will need to be investigated as a REC.</p>		
<p>¹ The presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. <i>De minimis</i> conditions are not recognized environmental conditions.</p> <p>² A past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls.</p> <p>³ A recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.</p> <p>⁴ A condition that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be <i>de minimis</i> conditions are not recognized environmental conditions nor controlled recognized environmental conditions.</p>		

Figure 4 depicts the locations of the RECs and *de minimis* conditions.

In addition to the RECs and *de minimis* conditions listed above, SRW observed several Universal Waste and Business Environmental Concerns:

- Wood Block Flooring: the wood block flooring observed in Buildings 1, 3, and 10 was oil soaked in certain locations. Depending on the chemicals in the oil, the disposal of the wood block flooring may be regulated if they are removed.
- Residual waste: The composition of the oils and various unknown liquids throughout the buildings and on the Property need to be characterized before they can be properly removed and disposed.
- Universal Wastes: SRW observed a large amount of mercury-containing fluorescent light tubes, potential PCB- containing fluorescent light ballasts, mercury containing thermostats, potential lead-acid batteries in emergency exit and lighting fixtures, etc. which need to be disposed of under RCRA guidelines.
- Asbestos and lead paint: SRW observed pipe wrapping with Asbestos warning labels, other potential asbestos containing materials, and possible lead paint.

Based on the above observations and the age of the buildings, SRW recommends a Hazardous Materials Assessment to inventory and sample potential Universal Wastes.



9.3 Opinions and Recommendations

Based on the foregoing, SRW does recommend additional assessment of the RECs identified at the Property.

9.4 Limiting Conditions and Deletions


There were no limiting conditions, deletions or deviations in this report from ASTM E-1527-13 except for those described in Section 2.4.

9.5 Environmental Professional

SRW Environmental Services, Inc. prepared this Phase I report following stringent quality assurance and quality control guidelines to ensure that the information presented in this Phase I report meets the general requirements of ASTM E-1527-13. If you have any questions or comments concerning this Phase I report, please contact any of the individuals listed below.

SRW personnel responsible for this report declare that to the best of our professional knowledge and belief, SRW Personnel meet the definition of Environmental Professional as defined in 312.10 of 40 CFR Part 312. Furthermore, SRW Personnel have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. In addition, if the junior level staff participated in this assessment they were under the supervision and responsible charge of the Environmental Professional. We have developed and performed all the appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312. Resumes are provided in Appendix 8.

Environmental Assessor:



Laura Welsh
Environmental Professional

Technical Reviewer:



Mark Rhinehart
Senior Environmental Professional



10.0 REFERENCES

ASTM E 1527-13 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, 2013.

Soil Survey of Hamilton County, Ohio, United States Department of Agriculture Soil Conservation Service.

USGS 7.5-Minute Topographic Quadrangle Map of Cincinnati-East, Ohio.



FIGURES


Figure 1 – Property Location Map

Figure 2 – Property Sketch

Figure 3 – Historical Operations Locations Map

*Figure 4 – Recognized Environmental Conditions and
De Minimis Conditions Map*





NOTE: BASE MAP WAS COPIED FROM THE USGS TOPOGRAPHIC MAP OF CINCINNATI-EAST, OHIO.



QUADRANGLE LOCATION



PROPERTY LOCATION
FORMER US PLAYING CARD
4590 BEECH STREET
NORWOOD, HAMILTON COUNTY, OHIO



SRW ENVIRONMENTAL SERVICES, INC.
 55 WEST TECHNECENTER DRIVE
 SUITE C, MILFORD, OHIO 45150
 TELE: 513-576-0009
 FAX: 513-576-9756

DRAWN BY/CHECKED BY: DMS/LEW	SCALE: 1" = 2,000'	PROJECT No.: 340.007.01
DIR\FILE: 340.007\FIGURE1.DWG	REVISION DATE: 4/30/15	FIGURE No.: 1



**PROPERTY SKETCH
FORMER US PLAYING CARD
4590 BEECH STREET
NORWOOD, HAMILTON COUNTY, OHIO**




**SRW ENVIRONMENTAL
SERVICES, INC.**
55 WEST TECHNECENTER DRIVE
SUITE C, MILFORD, OHIO 45150
TELE: 513-576-0009
FAX: 513-576-9756

DRAWN BY/CHECKED BY: DMS/LEW	SCALE: 1" = 200'	PROJECT No.: 340.007.01
DIR\FILE: 340.007\FIGURE2.DWG	REVISION DATE: 4/30/15	FIGURE No.: 2




SE
WEA
SHI
P


4TH FLOOR




3RD FLOOR



2ND FLOOR





APPENDICES

Appendix 1 – Legal Description

*Appendix 2 – Phase I Environmental Assessment
User Questionnaire*

Appendix 3 – EDR Regulatory Report

Appendix 4 – Records Request Responses

Appendix 5 – User Provided Environmental Documents

Appendix 6 – Historical Source Documentation

Appendix 7 – Photographs

Appendix 8 – Qualifications



APPENDIX 1

Legal Description



12521 00812

Fee total: 1,500.00
 Conveyance fee: 500.00
 Transfer fee: 0.50

Wayne Coates
 Hamilton County Recorders Office
 Doc #: 14-0009402 Type: DE
 Filed: 01/29/14 12:56:45 PM \$44.00
 Off.Rec.: 12521 00812 F 4 305

1252100812Fb

LIMITED WARRANTY DEED

KNOW ALL MEN BY THESE PRESENTS, that, **The United States Playing Card Company, a Delaware corporation, fka USPC Operating Company, Inc., a Delaware corporation**, Grantor(s), for valuable consideration paid, grants, with limited warranty covenants to **Norwood Beech LLC, an Ohio limited liability company**, Grantee(s), whose tax-mailing address is c/o Ohio Realty Advisors, LLC, 4020 Kinross Lakes Parkway, Richfield, Ohio 44286, the following described **REAL PROPERTY**:

SEE ATTACHED EXHIBIT "A"

Permanent Parcel No.: 651-0019-0125-00; 651-0019-0126-00; 651-0019-0128-00; 651-0019-0172-00; and 651-0019-0177-00
Prior Instrument Reference: Deed Book 4233, Page 1657
Property Address: 4590 Beech Street
 Norwood, OH 45212

EXCEPTION TO THE WARRANTIES: Except as herein before provided, and excepting all easements, rights-of-way, reservations, leases, conditions and restrictions of record, if any, public highways and street, environmental and building laws, ordinances and resolutions, regulations, zoning ordinances and real estate taxes and assessments, both special and general, not yet due and payable.

Convey. number: 63594
 Deed number: 307581
 Instr. number: 310560
 Transfer date: 01/29/2014
 Sec. 319.02, R.C.
 Sec. 322.02 R.C.
Dusty Rhodes
 Hamilton County Auditor
 Sales amount: 500,000
 Permissive fee: 1,000.00

12521 00813

Executed this 24 day of January, 2014.

Witness


Witness

The United States Playing Card Company, a
Delaware corporation, fka USPC Operating
Company, Inc., a Delaware corporation

By: 

John E. Capps, Vice President

State of FLORIDA,
County of DADE, ss:

Be it remembered, that on this 24 day of January, 2014, before me, the
subscriber, personally came the above named **The United States Playing Card
Company, a Delaware corporation, fka USPC Operating Company, Inc., a
Delaware corporation, By John E. Capps, Its Vice President, the Grantor(s)**
in the foregoing deed, and acknowledged the signing of the same to be
his/her/their voluntary act and deed.

In testimony whereof, I have hereunto subscribed my name and affixed my seal
on the day and year last aforesaid.


Notary Public

This Instrument prepared by:

Mary R. Porter.

Attorney At Law

1406 West 6th Street

Suite 400

Cleveland, OH 44113

File No. 131487NS



12521 00814

EXHIBIT "A"

Parcel No. 1 - Fee Parcel

Permanent Parcel No. 651-0019-0125-00; 651-0019-0126-00; 651-0019-0128-00; 651-0019-0172-00; and 651-0019-0177-00

Situated in Sections 28 and 34, Township 4, Fractional Range 4, Columbia Township, City of Norwood, Hamilton County, State of Ohio and being more particularly described as follows:

Beginning at the intersection of the North line of Robertson Avenue with the East line of Beech Street;

Thence along the East line of Beech Street, North 5-45-2 East, for a distance of 320.00 feet to the real place of beginning;

Thence continuing along the East line of Beech Street, North 5-45-2 East, for a distance of 600.00 feet to the Northerly terminus of Beech Street, as described in Quit Claim Deed recorded in Deed Book 3545, Page 393 of Hamilton County Deed Records;

Thence along said terminus, North 84-15-58 West, for a distance of 45.00 feet to a point five (5) feet from the West line of Beech Street;

Thence parallel to said West line of Beech Street, North 5-45-2 East, for a distance of 366.29 feet to the South right-of-way of the Baltimore and Ohio Southwestern Railroad;

Thence along said railroad right-of-way, South 68-17-0 East, for a distance of 1225.75 feet to angle point in said right-of-way;

Thence along said right-of-way, South 21-43-0 West, for a distance of 20.00 feet to angle point in said right-of-way;

Thence leaving said right-of-way, South 21-43-0 West, for a distance of 50.00 feet to a point;

Thence South 6-50-0 East, 129.30 feet;

Thence South 36-44-46 East, for a distance of 62.16 feet to a point on the West line of the limited access right-of-way line of Interstate Highway I-71;

Thence along said right-of-way of I-71 the following Courses: on a curved deflecting 10-2-10 right having a radius of 602.96 feet for a distance on arc of 105.61 feet (chord of arc bears South 34-45-15 West, 105.48 feet);

DESCRIPTION ACCEPTABLE
HAMILTON COUNTY ENGINEER

Tax Map -

CAGIS -

651-19-125, 126, 128, 172, 177
CORS

1-29-14

12521 00815

Thence South 39-46-20 West, 109.72 feet;

Thence South 33-42-2 West, 135.08 feet;

Thence South 35-34-4 West, 100.27 feet;

Thence leaving said right-of-way of I-71, North 84-15-58 West, for a distance of 958.67 feet to the place of beginning. Containing 888,465.20 square feet or 20.396355 acres.

Parcel No. 2 - Easement Parcel

Appurtenant Easement pursuant to Easements, Rights of Way and Restrictions recorded in Volume 4233, Page 1657 of Hamilton County Records.

APPENDIX 2

Phase I Environmental Assessment User Questionnaire



PHASE I ESA USER QUESTIONNAIRE
FORMER US PLAYING CARD
4590 BEECH STREET
NORWOOD, HAMILTON COUNTY, OHIO

In order to qualify for one of the *Landowner Liability Protections* (LLPs)¹ offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the "*Brownfields Amendments*"), the "User" must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31 and provide the following information to the environmental professional. Failure to provide this information could result in a determination that "all appropriate inquiries" is not complete.

1. Environmental liens that are filed or recorded against the property (40 CFR 312.25).

- Did a search of recorded land title records identify any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state, or local law? *No.*

2. Activity and land use limitations (AULs) that are in place on the property or that have been filed or recorded against the property in a registry (40 CFR 312.26(a)(1)(v) and (vi)).

- Did a search of recorded land title records identify any AULs such as engineering controls, land use restrictions, or institutional controls that are in place at the property and/or have been filed or recorded in a registry under federal, tribal, state, or local law? *No.*

3. Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28).

- As the "User" of this Phase I ESA, do you have any specialized knowledge or experience related to the property or nearby properties? *No.*

(For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?)

4. Relationship of the purchase price to the fair market value of the property if it were not contaminated (40 CFR 312.29).

- Does the purchase price being paid for this property reasonably reflect the fair market value of the property? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?

Yes. Property priced like other vacant industrial properties.

5. Commonly known or reasonably ascertainable information about the property (40 CFR 312.30).

- Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases?

For example, as "User,

- a. Do you know the past uses of the Property? *Manufacture of playing cards.*
- b. Do you know of specific chemicals that are present or once were present at the property? *No*
- c. Do you know of spills or other chemical releases that have taken place at the property? *No*
- d. Do you know of any environmental cleanups that have taken place at the property? *No*


6. The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31).

- As the "User" of this Phase I ESA, based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of releases at the property? *Yes. Stained floors inside buildings.*

In addition, the following information is intended to assist the environmental professional conduction the Phase I Environmental Site Assessment, but is not necessarily required to qualify for one of the LLPs. The information includes:

- The reason why the Phase I is being performed. *Due diligence*
- The type of property and type of property transaction, for example, sale, purchase, exchange, etc. *Purchase*
- The complete and correct address for the property. *4590 Beech St.
Cincinnati, OH 45212*

Signature



Date

4-24-15

¹ LLPs is the term used to describe the three types of potential defenses to Superfund liability in EPA's *Interim Guidance Regarding Criteria Landowners Must Meet in Order to Qualify for Bona Fide Prospective Purchaser, Contiguous Property Owner, or Innocent Landowner Limitations on CERCLA Liability* ("Common Elements" Guide) issued on March 6, 2003.

APPENDIX 3

EDR Regulatory Report




Former US Playing Cards

4590 Beech Street
Cincinnati, OH 45212

Inquiry Number: 4274630.2s
April 24, 2015

The EDR Radius Map™ Report with GeoCheck®



6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	145
Government Records Searched/Data Currency Tracking	GR-1
 <u>GEOCHECK ADDENDUM</u>	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-11
Physical Setting Source Map Findings	A-12
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2015 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

4590 BEECH STREET
CINCINNATI, OH 45212

COORDINATES

Latitude (North):	39.1590000 - 39° 9' 32.40"
Longitude (West):	84.4413000 - 84° 26' 28.68"
Universal Transverse Mercator:	Zone 16
UTM X (Meters):	721086.3
UTM Y (Meters):	4337331.5
Elevation:	622 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	39084-B4 CINCINNATI EAST, OH
Most Recent Revision:	1981

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20110822
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
4590 BEECH STREET
CINCINNATI, OH 45212

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	UNITED STATES PLAYIN	PARK AVE & BEECH ST	CERC-NFRAP, RCRA NonGen / NLR, NY MOSF UST, NY...		TP
A2	FOX MIDWEST TRUCKING	4590 BEECH RD	OH SPILLS		TP
A3	UNITED STATES PLAYIN	4590 BEECH STREET	ICIS, FINDS		TP
4	MULTI-COLOR CORP - N	4500 BEECH STREET	RCRA-LQG, OH UST, OH ARCHIVE UST	Lower	189, 0.036, SSW
B5	FEDERAL EXPRESS CORP	3004 HARRIS AVE	RCRA NonGen / NLR, FINDS	Lower	856, 0.162, NE
B6	FEDERAL EXPRESS CORP	3004 HARRIS AVE	OH ARCHIVE UST	Lower	856, 0.162, NE
B7	FEDERAL EXPRESS CORP	3004 HARRIS AVE	OH LUST, OH UST	Lower	856, 0.162, NE
B8	PUBLIC WORKS BUILDIN	3001 HARRIS AVE	OH LUST, OH UST, OH ARCHIVE UST	Lower	858, 0.162, NE
B9	ACME WIPER & INDUSTR	3003 DUCK CREEK RD	EDR US Hist Cleaners	Lower	929, 0.176, NE
C10	APKING AUTO SERVICE	2793 ROBERTSON RD	EDR US Hist Auto Stat	Lower	1055, 0.200, SE
C11	MARSHALL MACHINE SER	2793 ROBERTSON AVE	EDR US Hist Auto Stat	Lower	1055, 0.200, SE
C12	ED & FRANK MOTORS	2795 ROBERTSON AVE	EDR US Hist Auto Stat	Lower	1089, 0.206, SE
C13	FORMER ED & FRANK MO	2795 ROBERTSON RD	OH LUST	Lower	1089, 0.206, SE
C14	KENNER	2950 ROBERTSON RD	OH ARCHIVE UST	Lower	1153, 0.218, SE
C15	KENNER	2950 ROBERTSON RD	OH UST	Lower	1153, 0.218, SE
C16	HARTE HANKS PRINT	2950 ROBERTSON	RCRA-SQG, FINDS	Lower	1153, 0.218, SE
C17		2950 ROBERTSON AVE	EDR US Hist Cleaners	Lower	1153, 0.218, SE
C18	OAKLEY COMMERCE CENT	2950 ROBERTSON RD	OH UNREG LTANKS	Lower	1153, 0.218, SE
19	SOUTH NORWOOD DRY CL	2409 ROBERTSON AVE	EDR US Hist Cleaners	Higher	1221, 0.231, WSW
D20	SIEMENS ENERGY & AUT	4620 FOREST AVE	OH UNREG LTANKS, OH NPDES	Higher	1229, 0.233, WNW
D21	SIEMENS INDUSTRY INC	4620 FOREST AVENUE	RCRA-LQG, TRIS, FINDS, US AIRS	Higher	1229, 0.233, WNW
E22	SHEPHERD CHEMICAL CO	4900 BEECH ST	OH DERR, OH SPILLS, OH AIRS	Lower	1356, 0.257, North
F23	KNOWLTON MFG.	2524 LESLIE AVE	OH LUST, OH UST	Higher	1440, 0.273, WSW
G24	KLEIMAN AUTO BODY IN	2506 NORWOOD AVE	OH LUST	Higher	1485, 0.281, NNW
G25	DEE SIGN CO	2501 NORWOOD	CERC-NFRAP, RCRA NonGen / NLR, OH DERR	Higher	1509, 0.286, NNW
E26	J.H. DAY COMPANY	4932 BEECH ST	OH LUST, OH UST	Lower	1516, 0.287, North
F27	UNITED DAIRY FARMERS	4344 SMITH RD	OH LUST, OH UST, OH ARCHIVE UST	Higher	1620, 0.307, WSW
28	THE C.W. ZUMBIEL CO	2339 HARRIS AVE	OH LUST, OH UST	Lower	1734, 0.328, NW
29	VACANT LOT	2970 ROBERTSON AVENU	OH LUST, OH UST	Lower	1818, 0.344, ESE
30	BP OIL CO. #08942	4004 EDWARDS RD	OH LUST, OH UST	Higher	2054, 0.389, South
31	KING RECYCLING	5038 BEECH STREET	OH SWRCY, OH SPILLS	Higher	2060, 0.390, North
32	SPEEDWAY #9582	2713 WILLIAMS AVE	OH LUST, OH UST, OH ARCHIVE UST	Higher	2068, 0.392, SSW
H33	PERRY & DERRICK PAIN	2511 HIGHLAND AVENUE	CERCLIS, ICIS, PRP	Higher	2248, 0.426, NNW
H34	PERRY & DERRICK CO.	2510 HIGHLAND AVE	OH LUST, OH UST	Higher	2257, 0.427, NNW
35	SHELL OIL CO. #23461	2564 WILLIAMS RD	OH LUST, OH UST, OH ARCHIVE UST	Lower	2259, 0.428, SSW
36	CAST-FAB TECHNOLOGIE	3040 FORRER ST	OH LUST, OH UST	Lower	2307, 0.437, East
37	KUTAL PROD	2700 HIGHLAND AVE	OH LUST	Higher	2344, 0.444, North
38	SALVATION ARMY	2250 PARK AVE	OH LUST, OH UST	Higher	2363, 0.448, West
39	MILACRON PLANT 5	3025 DISNEY STREET	OH BROWNFIELDS	Lower	2445, 0.463, ENE

MAPPED SITES SUMMARY

Target Property Address:
4590 BEECH STREET
CINCINNATI, OH 45212

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
40	SWIFTY SERVICE STATI	2265 NORWOOD AVE	OH LUST, OH UST, OH ARCHIVE UST	Higher	2543, 0.482, NW
41	DE RENNA SERV	2846 HIGHLAND AVE	OH LUST	Lower	2618, 0.496, NNE
42	GMC ASSEMBLY DIV NOR	4726 SMITH RD	CERC-NFRAP, CORRACTS, RCRA NonGen / NLR	Higher	3312, 0.627, WNW
43	GENERAL MOTORS / CPC	4726 SMITH RD	OH DERR, OH SPILLS	Higher	3312, 0.627, WNW
44	ROOKWOOD COMMONS, NO	620 THRU 2750 EDMOND	OH DERR, OH INST CONTROL, OH VCP, OH HIST INST...	Higher	3838, 0.727, SSW
45	SURREY SQUARE MALL,	4524 MONTGOMERY RD	OH DERR, OH ENG CONTROLS, OH INST CONTROL, OH VCP	Higher	3922, 0.743, West
46	CINCINNATI MILACRON	4701 MARBURG AVE	OH DERR, OH SPILLS, OH ENG CONTROLS, OH INST...	Lower	3999, 0.757, East
47	KMART FAC FORMER, CI	4400 RIDGE AVE	OH DERR, OH INST CONTROL, OH VCP	Lower	4812, 0.911, ESE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
UNITED STATES PLAYIN PARK AVE & BEECH ST CINCINNATI, OH 45212	CERC-NFRAP Site ID: 0504176 EPA Id: OHD004234217 RCRA NonGen / NLR EPA ID:: OHD004234217 OH DERR DERR Id: 531000846 Activity: SA NY MANIFEST EPA ID: OHD004234217	OHD004234217
FOX MIDWEST TRUCKING 4590 BEECH RD CINCINNATI, OH	OH SPILLS Spill No.: 9504-31-1497	N/A
UNITED STATES PLAYIN 4590 BEECH STREET CINCINNATI, OH 45212	ICIS FRS ID:: 110008118214 FINDS Registry ID:: 110008118214	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL..... National Priority List
Proposed NPL..... Proposed National Priority List Sites
NPL LIENS..... Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY..... Federal Facility Site Information listing

EXECUTIVE SUMMARY

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF..... RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-CESQG..... RCRA - Conditionally Exempt Small Quantity Generator

Federal institutional controls / engineering controls registries

US ENG CONTROLS..... Engineering Controls Sites List

US INST CONTROL..... Sites with Institutional Controls

LUCIS..... Land Use Control Information System

Federal ERNS list

ERNS..... Emergency Response Notification System

State- and tribal - equivalent CERCLIS

OH SHWS..... This state does not maintain a SHWS list. See the Federal CERCLIS list and Federal NPL list.

State and tribal landfill and/or solid waste disposal site lists

OH SWF/LF..... Licensed Solid Waste Facilities

State and tribal leaking storage tank lists

INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

OH AST..... Above Ground Storage Tanks

INDIAN UST..... Underground Storage Tanks on Indian Land

FEMA UST..... Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

OH HIST ENG CONTROLS... Operation & Maintenance Agreements Database

State and tribal voluntary cleanup sites

INDIAN VCP..... Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations

EXECUTIVE SUMMARY

ODI..... Open Dump Inventory
 OH HIST LF..... Old Solid Waste Landfill
 INDIAN ODI..... Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs
 OH CDL..... Clandestine Drug Lab Locations
 US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System
 OH SPILLS 90..... SPILLS 90 data from FirstSearch
 OH SPILLS 80..... SPILLS 80 data from FirstSearch

Other Ascertainable Records

DOT OPS..... Incident and Accident Data
 DOD..... Department of Defense Sites
 FUDS..... Formerly Used Defense Sites
 CONSENT..... Superfund (CERCLA) Consent Decrees
 ROD..... Records Of Decision
 UMTRA..... Uranium Mill Tailings Sites
 US MINES..... Mines Master Index File
 TSCA..... Toxic Substances Control Act
 FTTS..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
 HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing
 SSTs..... Section 7 Tracking Systems
 PADS..... PCB Activity Database System
 MLTS..... Material Licensing Tracking System
 RADINFO..... Radiation Information Database
 RAATS..... RCRA Administrative Action Tracking System
 RMP..... Risk Management Plans
 OH TOWNGAS..... DERR Towngas Database
 OH UIC..... Underground Injection Wells Listing
 OH DRYCLEANERS..... Drycleaner Facility Listing
 OH USD..... Urban Setting Designation Sites
 OH HIST USD..... Urban Setting Designations Database
 INDIAN RESERV..... Indian Reservations
 SCR DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing
 OH Financial Assurance..... Financial Assurance Information Listing
 OH CRO..... Cessation of Regulated Operations Facility Listing
 OH COAL ASH..... Coal Ash Disposal Site Listing
 PCB TRANSFORMER..... PCB Transformer Registration Database
 COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List
 US FIN ASSUR..... Financial Assurance Information
 EPA WATCH LIST..... EPA WATCH LIST
 COAL ASH DOE..... Steam-Electric Plant Operation Data
 2020 COR ACTION..... 2020 Corrective Action Program List

EXECUTIVE SUMMARY

LEAD SMELTERS..... Lead Smelter Sites

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP..... EDR Proprietary Manufactured Gas Plants

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

OH RGA LF..... Recovered Government Archive Solid Waste Facilities List

OH RGA LUST..... Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS list

CERCLIS: The Comprehensive Environmental Response, Compensation and Liability Information System contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the CERCLIS list, as provided by EDR, and dated 10/25/2013 has revealed that there is 1 CERCLIS site within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
<i>PERRY & DERRICK PAIN</i>	<i>2511 HIGHLAND AVENUE</i>	<i>NNW 1/4 - 1/2 (0.426 mi.)</i>	<i>H33</i>	<i>95</i>

EXECUTIVE SUMMARY

Federal CERCLIS NFRAP site List

CERC-NFRAP: Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 10/25/2013 has revealed that there is 1 CERC-NFRAP site within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
DEE SIGN CO	2501 NORWOOD	NNW 1/4 - 1/2 (0.286 mi.)	G25	76

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 12/09/2014 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
GMC ASSEMBLY DIV NOR	4726 SMITH RD	WNW 1/2 - 1 (0.627 mi.)	I42	127

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/09/2014 has revealed that there are 2 RCRA-LQG sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SIEMENS INDUSTRY INC	4620 FOREST AVENUE	WNW 1/8 - 1/4 (0.233 mi.)	D21	50
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
MULTI-COLOR CORP - N	4500 BEECH STREET	SSW 0 - 1/8 (0.036 mi.)	4	15

EXECUTIVE SUMMARY

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/09/2014 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HARTE HANKS PRINT	2950 ROBERTSON	SE 1/8 - 1/4 (0.218 mi.)	C16	47

State- and tribal - equivalent CERCLIS

OH DERR: The DERR database is an index of sites for which Ohio EPA maintains files. It includes sites with known or suspected contamination, but a site's inclusion in the database does not mean that it is now or has ever been contaminated.

A review of the OH DERR list, as provided by EDR, and dated 04/01/2015 has revealed that there are 7 OH DERR sites within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
DEE SIGN CO DERR Id: 531000221 Activity: SA	2501 NORWOOD	NNW 1/4 - 1/2 (0.286 mi.)	G25	76
GENERAL MOTORS / CPC DERR Id: 531001689 Activity: SA	4726 SMITH RD	WNW 1/2 - 1 (0.627 mi.)	I43	134
ROOKWOOD COMMONS, NO DERR Id: 531002030 Activity: VAP	620 THRU 2750 EDMOND	SSW 1/2 - 1 (0.727 mi.)	44	135
SURREY SQUARE MALL, DERR Id: 531002521 Activity: VAP	4524 MONTGOMERY RD	W 1/2 - 1 (0.743 mi.)	45	137
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SHEPHERD CHEMICAL CO DERR Id: 531000968	4900 BEECH ST	N 1/4 - 1/2 (0.257 mi.)	E22	73
CINCINNATI MILACRON DERR Id: 531002238 Activity: COF, VAP	4701 MARBURG AVE	E 1/2 - 1 (0.757 mi.)	46	139
KMART FAC FORMER, CI DERR Id: 531002630 Activity: VAP	4400 RIDGE AVE	ESE 1/2 - 1 (0.911 mi.)	47	142

EXECUTIVE SUMMARY

State and tribal leaking storage tank lists

OH LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Commerce Division of State Fire Marshal's List of Reported Petroleum Underground Storage Tank Release Incidents.

A review of the OH LUST list, as provided by EDR, and dated 03/19/2015 has revealed that there are 18 OH LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KNOWLTON MFG. FR Status: Active FR Status: T2E: Tier 2 Evaluation FR Status: Active FR Status: NFC: No Further Action Data Cleaning Facility Status: Active FR Status: T2E: Tier 2 Evaluation Facility Status: Active FR Status: NFC: No Further Action Data Cleaning	2524 LESLIE AVE	WSW 1/4 - 1/2 (0.273 mi.)	F23	74
KLEIMAN AUTO BODY IN FR Status: Active FR Status: T1S: Tier 1 Source Investigation Facility Status: Active FR Status: T1S: Tier 1 Source Investigation	2506 NORWOOD AVE	NNW 1/4 - 1/2 (0.281 mi.)	G24	76
UNITED DAIRY FARMERS FR Status: Active FR Status: T2E: Tier 2 Evaluation Facility Status: Active FR Status: T2E: Tier 2 Evaluation	4344 SMITH RD	WSW 1/4 - 1/2 (0.307 mi.)	F27	80
BP OIL CO. #08942 FR Status: Inactive FR Status: DIS: a release is disproved FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: DIS: a release is disproved Facility Status: Inactive FR Status: NFA: No Further Action	4004 EDWARDS RD	S 1/4 - 1/2 (0.389 mi.)	30	85
SPEEDWAY #9582 FR Status: Inactive FR Status: NFA: No Further Action FR Status: Inactive FR Status: DIS: a release is disproved Facility Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: DIS: a release is disproved	2713 WILLIAMS AVE	SSW 1/4 - 1/2 (0.392 mi.)	32	88
PERRY & DERRICK CO. FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	2510 HIGHLAND AVE	NNW 1/4 - 1/2 (0.427 mi.)	H34	102
KUTAL PROD FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	2700 HIGHLAND AVE	N 1/4 - 1/2 (0.444 mi.)	37	116
SALVATION ARMY FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	2250 PARK AVE	W 1/4 - 1/2 (0.448 mi.)	38	116
SWIFTY SERVICE STATI FR Status: Inactive FR Status: NFA: No Further Action FR Status: Active FR Status: T1N: Tier 1 Notification Facility Status: Inactive FR Status: NFA: No Further Action Facility Status: Active FR Status: T1N: Tier 1 Notification	2265 NORWOOD AVE	NW 1/4 - 1/2 (0.482 mi.)	40	118
Lower Elevation	Address	Direction / Distance	Map ID	Page
FEDERAL EXPRESS CORP FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	3004 HARRIS AVE	NE 1/8 - 1/4 (0.162 mi.)	B7	34
PUBLIC WORKS BUILDIN FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	3001 HARRIS AVE	NE 1/8 - 1/4 (0.162 mi.)	B8	35

EXECUTIVE SUMMARY

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
FORMER ED & FRANK MO FR Status: Active FR Status: CLO: Closure Facility Status: Active FR Status: CLO: Closure	2795 ROBERTSON RD	SE 1/8 - 1/4 (0.206 mi.)	C13	43
J.H. DAY COMPANY FR Status: Active FR Status: CLO: Closure Facility Status: Active FR Status: CLO: Closure	4932 BEECH ST	N 1/4 - 1/2 (0.287 mi.)	E26	79
THE C.W. ZUMBIEL CO FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	2339 HARRIS AVE	NW 1/4 - 1/2 (0.328 mi.)	28	83
VACANT LOT FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	2970 ROBERTSON AVENUE	ESE 1/4 - 1/2 (0.344 mi.)	29	84
SHELL OIL CO. #23461 FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	2564 WILLIAMS RD	SSW 1/4 - 1/2 (0.428 mi.)	35	109
CAST-FAB TECHNOLOGIE FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	3040 FORRER ST	E 1/4 - 1/2 (0.437 mi.)	36	113
DE RENNA SERV FR Status: Inactive FR Status: NFA: No Further Action Facility Status: Inactive FR Status: NFA: No Further Action	2846 HIGHLAND AVE	NNE 1/4 - 1/2 (0.496 mi.)	41	127

OH UNREG LTANKS: A suspected or confirmed release of petroleum from a non-regulated UST.

A review of the OH UNREG LTANKS list, as provided by EDR, and dated 08/25/1999 has revealed that there are 2 OH UNREG LTANKS sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SIEMENS ENERGY & AUT Facility Status: CON Facility Id: 311757 Incident Number: 31919000	4620 FOREST AVE	WNW 1/8 - 1/4 (0.233 mi.)	D20	50
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
OAKLEY COMMERCE CENT Facility Status: RPT Facility Id: 312065 Incident Number: 312104400	2950 ROBERTSON RD	SE 1/8 - 1/4 (0.218 mi.)	C18	49

State and tribal registered storage tank lists

OH UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Commerce Division of State Fire Marshal's Facility File.

A review of the OH UST list, as provided by EDR, and dated 02/15/2015 has revealed that there are 4

EXECUTIVE SUMMARY

OH UST sites within approximately 0.25 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
MULTI-COLOR CORP - N Facility Id: 31000033 Tank Status: CIU - Currently In Use	4500 BEECH STREET	SSW 0 - 1/8 (0.036 mi.)	4	15
FEDERAL EXPRESS CORP Facility Id: 31003236 Tank Status: REM - Removed	3004 HARRIS AVE	NE 1/8 - 1/4 (0.162 mi.)	B7	34
PUBLIC WORKS BUILDIN Facility Id: 31009465 Tank Status: REM - Removed Tank Status: CIU - Currently In Use	3001 HARRIS AVE	NE 1/8 - 1/4 (0.162 mi.)	B8	35
KENNER Facility Id: 31002065 Tank Status: REM - Removed	2950 ROBERTSON RD	SE 1/8 - 1/4 (0.218 mi.)	C15	45

State and tribal Brownfields sites

OH BROWNFIELDS: A statewide brownfields inventory. A brownfield is an abandoned, idled or under-used industrial or commercial property where expansion or redevelopment is complicated by known or potential releases of hazardous substances and/or petroleum.

A review of the OH BROWNFIELDS list, as provided by EDR, and dated 03/12/2015 has revealed that there is 1 OH BROWNFIELDS site within approximately 0.5 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
MILACRON PLANT 5 App Id: 1651	3025 DISNEY STREET	ENE 1/4 - 1/2 (0.463 mi.)	39	117

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

OH SWRCY: A listing of recycling facility locations.

A review of the OH SWRCY list, as provided by EDR, and dated 10/09/2014 has revealed that there is 1 OH SWRCY site within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
KING RECYCLING	5038 BEECH STREET	N 1/4 - 1/2 (0.390 mi.)	31	88

EXECUTIVE SUMMARY

Local Lists of Registered Storage Tanks

OH ARCHIVE UST: Underground storage tank records that have been removed from the Underground Storage Tank database.

A review of the OH ARCHIVE UST list, as provided by EDR, and dated 02/15/2015 has revealed that there are 4 OH ARCHIVE UST sites within approximately 0.25 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
MULTI-COLOR CORP - N Tank Status: CIU Facility Id: 31000033 Facility Number: 31000033	4500 BEECH STREET	SSW 0 - 1/8 (0.036 mi.)	4	15
FEDERAL EXPRESS CORP Tank Status: REM Facility Id: 31003236 Facility Number: 31003236	3004 HARRIS AVE	NE 1/8 - 1/4 (0.162 mi.)	B6	32
PUBLIC WORKS BUILDIN Tank Status: CIU Tank Status: REM Facility Id: 31009465 Facility Number: 31009465	3001 HARRIS AVE	NE 1/8 - 1/4 (0.162 mi.)	B8	35
KENNER Tank Status: REM Facility Id: 31002065 Facility Number: 31002065	2950 ROBERTSON RD	SE 1/8 - 1/4 (0.218 mi.)	C14	43

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/09/2014 has revealed that there is 1 RCRA NonGen / NLR site within approximately 0.25 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
FEDERAL EXPRESS CORP	3004 HARRIS AVE	NE 1/8 - 1/4 (0.162 mi.)	B5	31

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected

EXECUTIVE SUMMARY

listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 3 EDR US Hist Auto Stat sites within approximately 0.25 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
APKING AUTO SERVICE	2793 ROBERTSON RD	SE 1/8 - 1/4 (0.200 mi.)	C10	41
MARSHALL MACHINE SER	2793 ROBERTSON AVE	SE 1/8 - 1/4 (0.200 mi.)	C11	41
ED & FRANK MOTORS	2795 ROBERTSON AVE	SE 1/8 - 1/4 (0.206 mi.)	C12	42

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there are 3 EDR US Hist Cleaners sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SOUTH NORWOOD DRY CL	2409 ROBERTSON AVE	WSW 1/8 - 1/4 (0.231 mi.)	19	49
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
ACME WIPER & INDUSTR	3003 DUCK CREEK RD	NE 1/8 - 1/4 (0.176 mi.)	B9	40
Not reported	2950 ROBERTSON AVE	SE 1/8 - 1/4 (0.218 mi.)	C17	48

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 4 records.

Site Name

RIDGE PLAZA, CINCINNATI

GLOBE LOT NORWOOD

UNKNOWN

US PLAYING CARDS

Database(s)


OH DERR, OH ENG CONTROLS, OH
INST CONTROL, OH VCP

OH DERR, OH ENG CONTROLS, OH
INST CONTROL, OH VCP

OH LUST

OH SPILLS

OVERVIEW MAP - 4274630.2S




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Oil & Gas pipelines from USGS
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands








This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Former US Playing Cards
 ADDRESS: 4590 Beech Street
 Cincinnati OH 45212
 LAT/LONG: 39.159 / 84.4413

CLIENT: SRW Env. Services, Inc.
 CONTACT: Laura Welsh
 INQUIRY #: 4274630.2s
 DATE: April 24, 2015 2:04 pm

DETAIL MAP - 4274630.2S



-  Target Property
-  Sites at elevations higher than or equal to the target property
-  Sites at elevations lower than the target property
-  Manufactured Gas Plants
-  Sensitive Receptors
-  National Priority List Sites
-  Dept. Defense Sites
-  Indian Reservations BIA
-  Oil & Gas pipelines from USGS
-  100-year flood zone
-  500-year flood zone

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Former US Playing Cards
 ADDRESS: 4590 Beech Street
 Cincinnati OH 45212
 LAT/LONG: 39.159 / 84.4413

CLIENT: SRW Env. Services, Inc.
 CONTACT: Laura Welsh
 INQUIRY #: 4274630.2s
 DATE: April 24, 2015 2:05 pm

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
<i>Federal NPL site list</i>								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
<i>Federal Delisted NPL site list</i>								
Delisted NPL	1.000		0	0	0	0	NR	0
<i>Federal CERCLIS list</i>								
CERCLIS	0.500		0	0	1	NR	NR	1
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
<i>Federal CERCLIS NFRAP site List</i>								
CERC-NFRAP	0.500	1	0	0	1	NR	NR	2
<i>Federal RCRA CORRACTS facilities list</i>								
CORRACTS	1.000		0	0	0	1	NR	1
<i>Federal RCRA non-CORRACTS TSD facilities list</i>								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
<i>Federal RCRA generators list</i>								
RCRA-LQG	0.250		1	1	NR	NR	NR	2
RCRA-SQG	0.250		0	1	NR	NR	NR	1
RCRA-CESQG	0.250		0	0	NR	NR	NR	0
<i>Federal institutional controls / engineering controls registries</i>								
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
LUCIS	0.500		0	0	0	NR	NR	0
<i>Federal ERNS list</i>								
ERNS	TP		NR	NR	NR	NR	NR	0
<i>State- and tribal - equivalent CERCLIS</i>								
OH SHWS	N/A		N/A	N/A	N/A	N/A	N/A	N/A
OH DERR	1.000	1	0	0	2	5	NR	8
<i>State and tribal landfill and/or solid waste disposal site lists</i>								
OH SWF/LF	0.500		0	0	0	NR	NR	0
<i>State and tribal leaking storage tank lists</i>								
OH LUST	0.500		0	3	15	NR	NR	18
OH UNREG LTANKS	0.500		0	2	0	NR	NR	2
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
OH UST	0.250		1	3	NR	NR	NR	4
OH AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
FEMA UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
OH ENG CONTROLS	0.500		0	0	0	NR	NR	0
OH INST CONTROL	0.500		0	0	0	NR	NR	0
OH HIST INST CONTROLS	0.500		0	0	0	NR	NR	0
OH HIST ENG CONTROLS	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
OH VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
OH BROWNFIELDS	0.500		0	0	1	NR	NR	1
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
OH SWRCY	0.500		0	0	1	NR	NR	1
OH HIST LF	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL	TP		NR	NR	NR	NR	NR	0
OH CDL	TP		NR	NR	NR	NR	NR	0
US HIST CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
OH ARCHIVE UST	0.250		1	3	NR	NR	NR	4
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
OH SPILLS	TP	1	NR	NR	NR	NR	NR	1
OH SPILLS 90	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
OH SPILLS 80	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	1	0	1	NR	NR	NR	2
DOT OPS	TP		NR	NR	NR	NR	NR	0
DOD	1.000		0	0	0	0	NR	0
FUDS	1.000		0	0	0	0	NR	0
CONSENT	1.000		0	0	0	0	NR	0
ROD	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ICIS	TP	1	NR	NR	NR	NR	NR	1
PADS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
FINDS	TP	1	NR	NR	NR	NR	NR	1
RAATS	TP		NR	NR	NR	NR	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
OH TOWNGAS	1.000		0	0	0	0	NR	0
OH UIC	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250	1	0	0	NR	NR	NR	1
OH DRYCLEANERS	0.250		0	0	NR	NR	NR	0
OH NPDES	TP		NR	NR	NR	NR	NR	0
OH AIRS	TP		NR	NR	NR	NR	NR	0
OH USD	0.500		0	0	0	NR	NR	0
OH HIST USD	0.500		0	0	0	NR	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
OH Financial Assurance	TP		NR	NR	NR	NR	NR	0
OH CRO	TP		NR	NR	NR	NR	NR	0
OH COAL ASH	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	1.000		0	0	0	0	NR	0
---------	-------	--	---	---	---	---	----	---

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
EDR US Hist Auto Stat	0.250		0	3	NR	NR	NR	3
EDR US Hist Cleaners	0.250		0	3	NR	NR	NR	3
<u>EDR RECOVERED GOVERNMENT ARCHIVES</u>								
<i>Exclusive Recovered Govt. Archives</i>								
OH RGA LF	TP		NR	NR	NR	NR	NR	0
OH RGA LUST	TP		NR	NR	NR	NR	NR	0
- Totals --		7	3	20	21	6	0	57

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

N/A = This State does not maintain a SHWS list. See the Federal CERCLIS list.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A1
Target
Property

UNITED STATES PLAYING CARD CO
PARK AVE & BEECH ST
CINCINNATI, OH 45212

CERC-NFRAP
RCRA NonGen / NLR
OH DERR
NY MANIFEST

1000398763
OHD004234217

Site 1 of 3 in cluster A

Actual:
622 ft.

CERC-NFRAP:
Site ID: 0504176
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY
Date Started: / /
Date Completed: 08/01/80
Priority Level: Not reported

Action: ARCHIVE SITE
Date Started: / /
Date Completed: 09/25/85
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 09/25/85
Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

RCRA NonGen / NLR:

Date form received by agency: 01/24/2012
Facility name: UNITED STATES PLAYING CARD CO
Facility address: PARK AVE AND BEECH ST
CINCINNATI, OH 45212
EPA ID: OHD004234217
Contact: Not reported
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 05
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NAME NOT REPORTED
Owner/operator address: ADDRESS NOT REPORTED
CITY NOT REPORTED, AK 99998
Owner/operator country: Not reported
Owner/operator telephone: (312) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NAME NOT REPORTED
Owner/operator address: ADDRESS NOT REPORTED

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED STATES PLAYING CARD CO (Continued)

1000398763

CITY NOT REPORTED, AK 99998
Owner/operator country: Not reported
Owner/operator telephone: (312) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 08/11/1980

Site name: UNITED STATES PLAYING CARD CO

Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Facility Has Received Notices of Violations:

Regulation violated: SR - 3745-52-41
Area of violation: Generators - Records/Reporting
Date violation determined: 09/22/2005
Date achieved compliance: 01/16/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/22/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED STATES PLAYING CARD CO (Continued)

1000398763

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 01/24/2012
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/22/2005
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Records/Reporting
Date achieved compliance: 01/16/2009
Evaluation lead agency: State

DERR:

DERR ID: 531000846
District: SWDO
Alias: Not reported
Lat/Long: 39.1588 -84.4413
EPA ID: OHD004234217
Program: Site Assessment

NY MANIFEST:

EPA ID: OHD004234217
Country: USA
Location Address 1: 4590 BEECH ST
Location Address 2: Not reported
Location City: CINCINNATI
Location State: OH
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:

Name: U S PLAYING CARD CORPORATION
Contact: MIKE MASSAY
Address: 4590 BEECH ST
City/State/Zip: CINCINNATI, OH 45212
Country: USA
Phone: 513-396-5700

Manifest:

Document ID: NYB4209552
Manifest Status: Completed copy
Trans1 State ID: OHT56JZ
Trans2 State ID: Not reported
Generator Ship Date: 01/24/1995
Trans1 Recv Date: 01/24/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 01/26/1995
Part A Recv Date: / /
Part B Recv Date: 02/09/1995
Generator EPA ID: OHD004234217

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED STATES PLAYING CARD CO (Continued)

1000398763

Trans1 EPA ID: OH0000000539
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 07902
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 1995

A2
Target
Property
FOX MIDWEST TRUCKING
4590 BEECH RD
CINCINNATI, OH

OH SPILLS **S106325511**
N/A

Site 2 of 3 in cluster A

Actual:
622 ft.

SPILLS:
Spill No.: 9504-31-1497
Spill Number: 1497
Spill Month/Year: 4/1995
Date Spill Reported: 04/21/1995
Reporter Name: DISPATCHER GAYLE
Confidential: No
District Code: SW
Employee Number: Not reported
Product Spilled Name: DIESEL FUEL
Lat/Long: Not reported

A3
Target
Property
UNITED STATES PLAYING CARD CO
4590 BEECH STREET
CINCINNATI, OH 45212

ICIS **1016256581**
FINDS **N/A**

Site 3 of 3 in cluster A

Actual:
622 ft.

ICIS:
Enforcement Action ID: 05-1986-0170
FRS ID: 110008118214
Program ID: FRS 110008118214
Action Name: U.S. PLAYING CARD CO.
Full Address: 4590 BEECH STREET CINCINNATI OH 45212-3449
State: Ohio
Facility Name: UNITED STATES PLAYING CARD CO
Facility Address: 4590 BEECH STREET
CINCINNATI, OH 45212-3449
Enforcement Action Type: CAA 113 Notice Of Violation
Facility County: HAMILTON
EPA Region #: 5

Enforcement Action ID: 05-1986-0170
FRS ID: 110008118214
Program ID: RCRAINFO OHD004234217
Action Name: U.S. PLAYING CARD CO.
Full Address: 4590 BEECH STREET CINCINNATI OH 45212-3449
State: Ohio

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED STATES PLAYING CARD CO (Continued)

1016256581

Facility Name: UNITED STATES PLAYING CARD CO
Facility Address: 4590 BEECH STREET
CINCINNATI, OH 45212-3449
Enforcement Action Type: CAA 113 Notice Of Violation
Facility County: HAMILTON
EPA Region #: 5
Enforcement Action ID: 05-1986-0170
FRS ID: 110008118214
Program ID: OH-CORE 21089
Action Name: U.S. PLAYING CARD CO.
Full Address: 4590 BEECH STREET CINCINNATI OH 45212-3449
State: Ohio
Facility Name: UNITED STATES PLAYING CARD CO
Facility Address: 4590 BEECH STREET
CINCINNATI, OH 45212-3449
Enforcement Action Type: CAA 113 Notice Of Violation
Facility County: HAMILTON
EPA Region #: 5
Enforcement Action ID: 05-1986-0170
FRS ID: 110008118214
Program ID: NEI NEI40448
Action Name: U.S. PLAYING CARD CO.
Full Address: 4590 BEECH STREET CINCINNATI OH 45212-3449
State: Ohio
Facility Name: UNITED STATES PLAYING CARD CO
Facility Address: 4590 BEECH STREET
CINCINNATI, OH 45212-3449
Enforcement Action Type: CAA 113 Notice Of Violation
Facility County: HAMILTON
EPA Region #: 5
Program ID: FRS 110008118214
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2732
Program ID: FRS 110008118214
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2752
Program ID: FRS 110008118214
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3944

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED STATES PLAYING CARD CO (Continued)

1016256581

Program ID: NEI NEI40448
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2732

Program ID: NEI NEI40448
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2752

Program ID: NEI NEI40448
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3944

Program ID: OH-CORE 21089
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2732

Program ID: OH-CORE 21089
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2752

Program ID: OH-CORE 21089
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3944

Program ID: RCRAINFO OHD004234217
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2732

Program ID: RCRAINFO OHD004234217

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED STATES PLAYING CARD CO (Continued)

1016256581

Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2752

Program ID: RCRAINFO OHD004234217
Facility Name: UNITED STATES PLAYING CARD CO
Address: 4590 BEECH STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3944

FINDS:

Registry ID: 110008118214

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

The OH-CORE (Ohio - Core) database contains information commonly shared among the Ohio EPA environmental programs. The information is facility-based, general in nature, and used to support specific programmatic systems while simultaneously maintaining an inventory of common facility-related data. Specific programmatic details are maintained in programmatic databases.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

4
SSW
< 1/8
0.036 mi.
189 ft.

MULTI-COLOR CORP - NORWOOD
4500 BEECH STREET
CINCINNATI, OH 45212

RCRA-LQG
OH UST
OH ARCHIVE UST

1000146239
OHD056487101

Relative:
Lower

RCRA-LQG:

Date form received by agency: 02/24/2014

Facility name: MULTI-COLOR CORP - NORWOOD

Facility address: 4500 BEECH STREET
CINCINNATI, OH 45212

EPA ID: OHD056487101

Contact: LUKE GAMBLE

Contact address: 4500 BEECH STREET
CINCINNATI, OH 45212

Contact country: US

Contact telephone: (513) 396-5625

Contact email: LUKE.GAMBLE@GRAPHICPKG.COM

EPA Region: 05

Land type: Private

Classification: Large Quantity Generator

Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: MULTI-COLOR CORP
Owner/operator address: 4500 BEECH STREET
CINCINNATI, OH 45212

Owner/operator country: US

Owner/operator telephone: (513) 396-5625

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: 03/01/2008

Owner/Op end date: Not reported

Owner/operator name: MULTI-COLOR CORP
Owner/operator address: 4500 BEECH STREET
CINCINNATI, OH 45212

Owner/operator country: US

Owner/operator telephone: (513) 396-5625

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: 03/01/2008

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:

Date form received by agency: 02/16/2012

Site name: GRAPHIC PACKAGING INTERNATIONAL DINACAL LABEL PLANT

Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/22/2010

Site name: GRAPHIC PACKAGING INTERNATIONAL DINACAL LABEL PLANT

Classification: Large Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE WASTE
- . Waste code: D005
- . Waste name: BARIUM
- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE
- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 03/03/2009

Site name: GRAPHIC PACKAGING INTERNATIONAL DINACAL LABEL PLANT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/29/2008

Site name: BLUEGRASS LABELS

Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE(BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- Date form received by agency: 02/14/2007
- Site name: BLUEGRASS LABELS
- Classification: Large Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D005
- . Waste name: BARIUM

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: D039
- . Waste name: TETRACHLOROETHYLENE

- . Waste code: D040
- . Waste name: TRICHLOROETHYLENE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE(BY VOLUME) OF

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 07/31/2006

Site name: BLUEGRASS LABELS DBA ALTIVITY PACKAGING

Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Date form received by agency: 02/21/2006

Site name: SMURFIT STONE CONTAINER ENTERPRISES INC

Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/25/2005

Site name: SMURFIT STONE CONTAINER ENTERPRISES INC

Classification: Large Quantity Generator

Date form received by agency: 02/24/2004

Site name: SMURFIT STONE CONTAINER CORP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/24/2003

Site name: JEFFERSON SMURFIT CORPORATION (U.S.)

Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE(BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 05/25/2002

Site name: JEFFERSON SMURFIT DI-NA-CAL LABEL GROUP

Classification: Large Quantity Generator

Date form received by agency: 02/16/2000

Site name: JEFFERSON SMURFIT CORP DINAGRAPHSICS DIV

Classification: Large Quantity Generator

Date form received by agency: 02/18/1998

Site name: JEFFERSON SMURFIT CORP DINAGRAPHSICS DIV

Classification: Large Quantity Generator

Date form received by agency: 02/07/1996

Site name: JEFFERSON SMURFIT CORP DINAGRAPHSICS DIV

Classification: Large Quantity Generator

Date form received by agency: 01/28/1994

Site name: DINAGRAPHSICS

Classification: Large Quantity Generator

Date form received by agency: 02/19/1992

Site name: DINAGRAPHSICS

Classification: Large Quantity Generator

Date form received by agency: 02/13/1990

Site name: DINAGRAPHSICS INC

Classification: Large Quantity Generator

Date form received by agency: 07/24/1980

Site name: DINAGRAPHSICS INC

Classification: Large Quantity Generator

- . Waste code: D001

- . Waste name: IGNITABLE WASTE

- . Waste code: F005

- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE(BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code:	U002
Waste name:	2-PROPANONE (I) (OR) ACETONE (I)
Waste code:	U031
Waste name:	1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)
Waste code:	U112
Waste name:	ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)
Waste code:	U155
Waste name:	1,2-ETHANEDIAMINE, N,N-DIMETHYL-N'-2-PYRIDINYL-N'-(2-THIENYLMETHYL)- (OR) METHAPYRILENE
Waste code:	U159
Waste name:	2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)
Waste code:	U161
Waste name:	4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-
Waste code:	U171
Waste name:	2-NITROPROPANE (I,T) (OR) PROPANE, 2-NITRO- (I,T)
Waste code:	U220
Waste name:	BENZENE, METHYL- (OR) TOLUENE
Waste code:	U239
Waste name:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:

Waste code:	D001
Waste name:	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs):	272693
Waste code:	D005
Waste name:	BARIUM
Amount (Lbs):	272693
Waste code:	D035
Waste name:	METHYL ETHYL KETONE
Amount (Lbs):	272693
Waste code:	F003
Waste name:	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 272693

Waste code: F005

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 272693

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 01/05/2012
Date achieved compliance: 01/05/2012
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/22/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 11/30/2011
Date achieved compliance: 11/30/2011
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/21/2011
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 12/10/2007
Date achieved compliance: 12/10/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/13/2007
Enf. disposition status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 12/10/2007
Date achieved compliance: 12/10/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/13/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 12/10/2007
Date achieved compliance: 12/27/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/13/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(C)
Area of violation: Generators - Pre-transport
Date violation determined: 04/10/2002
Date achieved compliance: 04/24/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/19/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-66-73(A)
Area of violation: Generators - General
Date violation determined: 04/10/2002
Date achieved compliance: 04/10/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/19/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-66-74
Area of violation: Generators - Pre-transport
Date violation determined: 04/10/2002
Date achieved compliance: 04/10/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/19/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 01/05/2012
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 01/05/2012
Evaluation lead agency: State

Evaluation date: 11/30/2011
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 11/30/2011
Evaluation lead agency: State

Evaluation date: 12/27/2007
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/10/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 12/10/2007
Evaluation lead agency: State

Evaluation date: 12/10/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 12/27/2007
Evaluation lead agency: State

Evaluation date: 12/10/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 12/10/2007
Evaluation lead agency: State

Evaluation date: 04/10/2002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 04/10/2002
Evaluation lead agency: State

Evaluation date: 04/10/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 04/10/2002
Evaluation lead agency: State

Evaluation date: 04/10/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 04/24/2002
Evaluation lead agency: State

Evaluation date: 06/19/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

UST:

Facility Id: 31000033
Facility Type: Industrial
Owner Name: MCC-NORWOOD LLC
Owner Address: 4053 CLOUGH WOODS DR
Owner City/State/Zip: 45103

Tank Number: T00001
Status: CIU - Currently In Use
UST Capacity: 5000
Tank Content: Other Petroleum Distillate
Installation Date: 12/01/1988
Construction: CCPS - Coated/Cathodically Protected Steel
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: CAS 142-82-5 70%
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: YES
Date Of Sensitivity: 09/01/1992
UST Configurations: SC- Secondarily Contained
Construction Comments: Not reported
Corrosion Protections: FACA - Factory Installed Anodes
Corrosion Protection Comments: Not reported
Primary Release Detection: IMT - Int. Monitoring (D/W Tank)
Secondary Release Detection: IMT - Int. Monitoring (D/W Tank)
Release Detection Comments: Not reported
Piping Configuration: SW - Single Wall
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Not reported
Piping Corrosion Protections: NCWG - No piping in contact with ground
Piping Corrosion Protection Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

Piping Release Detections: MLLD - Mechanical Line Leak Detector
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: ALARM - Alarm
OverFill Prevention Comment: Not reported
Comments: 235 Solvent Blend (trade name CS-3466 containing heptane, ethanol and isopropanol)

Tank Number: T00003
Status: CIU - Currently In Use
UST Capacity: 5000
Tank Content: Hazardous Substance
Installation Date: 12/01/1988
Construction: CCPS - Coated/Cathodically Protected Steel
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 109-60-4
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: YES
Date Of Sensitivity: 09/01/1992
UST Configurations: SC- Secondarily Contained
Construction Comments: Not reported
Corrosion Protections: FACA - Factory Installed Anodes
Corrosion Protection Comments: Not reported
Primary Release Detection: IMT - Int. Monitoring (D/W Tank)
Secondary Release Detection: IMT - Int. Monitoring (D/W Tank)
Release Detection Comments: Not reported
Piping Configuration: SW - Single Wall
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Not reported
Piping Corrosion Protections: NCWG - No piping in contact with ground
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: MLLD - Mechanical Line Leak Detector
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: ALARM - Alarm
OverFill Prevention Comment: Not reported
Comments: 300 (trade name CS-3539 containing ethyl acetate, ethanol, heptane and isopropyl alcohol)

Tank Number: T00004
Status: CIU - Currently In Use
UST Capacity: 5000
Tank Content: Hazardous Substance
Installation Date: 12/01/1988
Construction: CCPS - Coated/Cathodically Protected Steel
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

CAS Number: 78-93-3
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: YES
Date Of Sensitivity: 09/01/1992
UST Configurations: SC- Secondly Contained
Construction Comments: Not reported
Corrosion Protections: FACA - Factory Installed Anodes
Corrosion Protection Comments: Not reported
Primary Release Detection: IMT - Int. Monitoring (D/W Tank)
Secondary Release Detection: IMT - Int. Monitoring (D/W Tank)
Release Detection Comments: Not reported
Piping Configuration: SW - Single Wall
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Not reported
Piping Corrosion Protections: NCWG - No piping in contact with ground
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: MLLD - Mechanical Line Leak Detector
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: ALARM - Alarm
OverFill Prevention Comment: Not reported
Comments: methyl ethyl ketone

ARCHIVE UST:

Facility Number: 31000033
Owner Name: BLUEGRASS LABELS COMPANY LLC
Owner Address: 4500 BEECH ST
Owner City,St,Zip: CINCINNATI, OH 45212

Permit:

Facility Id: 31000033
Permit Id: P00001
Permit Status: Expired
Issued Date: 11/12/1999
LFD Permit Id: Not reported

Facility Id: 31000033
Permit Id: P00001
Permit Status: Expired
Issued Date: 11/12/1999
LFD Permit Id: Not reported

Facility Id: 31000033
Permit Id: P00001
Permit Status: Expired
Issued Date: 11/12/1999
LFD Permit Id: Not reported

Inspection:

Facility Id: 31000033
Permit Number: P00001
Code: 102
Inspection Type: Final

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

Tank ID: T00001
Tank Type: CCPS - Coated/Cathodically Protected Steel
Tank Status: **Currently In Use**
Install Date: 12/1/1988
Content: Other Petroleum Distillate
Capacity: 5000
Corrosion Protection Tank: FACA - Factory Installed Anodes
CAS #: Not reported
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging;Interstitial Monitoring Double Walled
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NCWG - No Piping In Contact With
Piping Material: BM - Bare Metal
Piping Type: Pressure
Release Detection On Piping: Mechanical Line Leak Detector

Tank ID: T00002
Tank Type: CCPS - Coated/Cathodically Protected Steel
Tank Status: **Currently In Use**
Install Date: 12/1/1988
Content: Hazardous Substance
Capacity: 5000
Corrosion Protection Tank: FACA - Factory Installed Anodes
CAS #: Not reported
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging;Interstitial Monitoring Double Walled
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NCWG - No Piping In Contact With
Piping Material: BM - Bare Metal
Piping Type: Pressure
Release Detection On Piping: Mechanical Line Leak Detector

Tank ID: T00003
Tank Type: CCPS - Coated/Cathodically Protected Steel
Tank Status: **Currently In Use**
Install Date: 12/1/1988
Content: Hazardous Substance
Capacity: 5000
Corrosion Protection Tank: FACA - Factory Installed Anodes
CAS #: Not reported
Regulated: No
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging;Interstitial Monitoring Double Walled
Date Removed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MULTI-COLOR CORP - NORWOOD (Continued)

1000146239

Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NCWG - No Piping In Contact With
Piping Material: BM - Bare Metal
Piping Type: Pressure
Release Detection On Piping: Mechanical Line Leak Detector

Tank ID: T00004
Tank Type: CCPS - Coated/Cathodically Protected Steel
Tank Status: Currently In Use
Install Date: 12/1/1988
Content: Hazardous Substance
Capacity: 5000
Corrosion Protection Tank: FACA - Factory Installed Anodes
CAS #: Not reported
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging;Interstitial Monitoring Double Walled
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NCWG - No Piping In Contact With
Piping Material: BM - Bare Metal
Piping Type: Pressure
Release Detection On Piping: Mechanical Line Leak Detector

B5
NE
1/8-1/4
0.162 mi.
856 ft.

FEDERAL EXPRESS CORP
3004 HARRIS AVE
NORWOOD, OH 45212

RCRA NonGen / NLR 1000213186
FINDS OHD986981892

Site 1 of 5 in cluster B

Relative:
Lower

RCRA NonGen / NLR:
Date form received by agency: 12/15/1994
Facility name: FEDERAL EXPRESS CORP
Facility address: 3004 HARRIS AVE
NORWOOD, OH 45212
EPA ID: OHD986981892
Contact: MIKE KNOLL
Contact address: 3004 HARRIS AVE
NORWOOD, OH 45212
Contact country: US
Contact telephone: (513) 531-3737
Contact email: Not reported
EPA Region: 05
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Actual:
566 ft.

Owner/Operator Summary:
Owner/operator name: HOWARD REVELSON
Owner/operator address: NOT REPORTED
NOT REPORTED, OH 00000
Owner/operator country: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORP (Continued)

1000213186

Owner/operator telephone: (000) 000-0000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004665988

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**B6
NE
1/8-1/4
0.162 mi.
856 ft.**

**FEDERAL EXPRESS CORPORATION
3004 HARRIS AVE
NORWOOD, OH 45212**

**OH ARCHIVE UST U004090227
N/A**

Site 2 of 5 in cluster B

**Relative:
Lower**

ARCHIVE UST:
Facility Number: 31003236
Owner Name: FEDEX EXPRESS CORPORATION
Owner Address: 3620 Hacks Cross Road; Bldg. B
Owner City,St,Zip: MEMPHIS, TN 38125-7113

**Actual:
566 ft.**

Permit:
Facility Id: 31003236
Permit Id: P00001
Permit Status: Expired
Issued Date: 11/26/1993

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORPORATION (Continued)

U004090227

LFD Permit Id: Not reported

Inspection:

Facility Id: 31003236
Permit Number: P00001
Code: 101
Inspection Type: Final

Tank ID: T00001
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Removed
Install Date: 1/1/1984
Content: Gasoline
Capacity: 10000
Corrosion Protection Tank: Not reported
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Not reported
Date Removed: 10/21/1993
Date Last Use: 10/21/1993
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Fiberglass Reinforced Plastic
Piping Type: Suction: no valve at tank
Release Detection On Piping: Not reported

Tank ID: T00002
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Removed
Install Date: 1/1/1984
Content: Diesel
Capacity: 1000
Corrosion Protection Tank: Not reported
CAS #: 68334-30-5
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Not reported
Date Removed: 10/21/1993
Date Last Use: 10/21/1993
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Fiberglass Reinforced Plastic
Piping Type: Suction: no valve at tank
Release Detection On Piping: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

B7
NE
1/8-1/4
0.162 mi.
856 ft.

FEDERAL EXPRESS CORPORATION
3004 HARRIS AVE
NORWOOD, OH 45212

Site 3 of 5 in cluster B

OH LUST
OH UST

U004206868
N/A

Relative:
Lower

LUST:

Release Number: 31003236-N00001

Release Date: Not reported

Facility Status: Inactive

LTF Status: 6 Closure of regulated UST

FR Status: NFA: No Further Action

Priority: 3

Review Date: 06/20/2000

Class: Viable Responsible Party has been identified

Actual:
566 ft.

UST:

Facility Id: 31003236
Facility Type: Trucking/Transportation
Owner Name: Not reported
Owner Address: Not reported
Owner City/State/Zip: Not reported

Tank Number: T00001
Status: REM - Removed
UST Capacity: 10000
Tank Content: Gasoline
Installation Date: 01/01/1984
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: 10/21/1993
Date TCL Closed: Not reported
Date Removed: 10/21/1993
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Fiberglass Reinforced Plastic
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Fiberglass Reinforced Plastic
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORPORATION (Continued)

U004206868

Tank Number: T00002
Status: REM - Removed
UST Capacity: 1000
Tank Content: Diesel
Installation Date: 01/01/1984
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: 10/21/1993
Date TCL Closed: Not reported
Date Removed: 10/21/1993
CAS Number: 68334-30-5
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Fiberglass Reinforced Plastic
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Fiberglass Reinforced Plastic
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

**B8
NE
1/8-1/4
0.162 mi.
858 ft.**

**PUBLIC WORKS BUILDING
3001 HARRIS AVE
NORWOOD, OH 45212**

Site 4 of 5 in cluster B

**OH LUST
OH UST
OH ARCHIVE UST**

**U003975327
N/A**

**Relative:
Lower**

LUST:

Release Number: 31009465-N00001
Release Date: Not reported
Facility Status: Inactive
LTF Status: 6 Closure of regulated UST
FR Status: NFA: No Further Action
Priority: 3
Review Date: 06/20/2000
Class: Viable Responsible Party has been identified

UST:

Facility Id: 31009465
Facility Type: Government
Owner Name: CITY OF NORWOOD
Owner Address: 4645 MONTGOMERY RD

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PUBLIC WORKS BUILDING (Continued)

U003975327

Owner City/State/Zip: 45212

Tank Number: T00001
Status: REM - Removed
UST Capacity: 4000
Tank Content: Diesel
Installation Date: Not reported
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: 02/07/1997
Date TCL Closed: Not reported
Date Removed: 02/07/1997
CAS Number: 68334-30-5
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Fiberglass Reinforced Plastic
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Galvanized Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00002
Status: REM - Removed
UST Capacity: 8000
Tank Content: Gasoline
Installation Date: Not reported
Construction: Other
Date Last Used: 02/07/1997
Date TCL Closed: Not reported
Date Removed: 02/07/1997
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PUBLIC WORKS BUILDING (Continued)

U003975327

Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Galvanized Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00003
Status: CIU - Currently In Use
UST Capacity: 6000
Tank Content: Gasoline
Installation Date: 02/19/1997
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: YES
Date Of Sensitivity: 09/01/1992
UST Configurations: SC- Secondarily Contained
Construction Comments: Not reported
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: ATG - Automatic Tank Gauging
Release Detection Comments: Not reported
Piping Configuration: SC - Secondarily Contained
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Not reported
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: SS - Safe Suction
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: FILL - Fill Pipe (drop tube flapper)
OverFill Prevention Comment: Not reported
Comments: Not reported

Tank Number: T00004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PUBLIC WORKS BUILDING (Continued)

U003975327

Status: CIU - Currently In Use
UST Capacity: 6000
Tank Content: Diesel
Installation Date: 02/19/1997
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 68334-30-5
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: YES
Date Of Sensitivity: 09/01/1992
UST Configurations: SC- Secondarily Contained
Construction Comments: Not reported
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: ATG - Automatic Tank Gauging
Release Detection Comments: Not reported
Piping Configuration: SC - Secondarily Contained
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Not reported
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: SS - Safe Suction
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: FILL - Fill Pipe (drop tube flapper)
OverFill Prevention Comment: Not reported
Comments: Not reported

ARCHIVE UST:

Facility Number: 31009465
Owner Name: CITY OF NORWOOD
Owner Address: 4645 MONTGOMERY RD
Owner City,St,Zip: NORWOOD, OH 45212

Permit:

Facility Id: 31009465
Permit Id: P00001
Permit Status: Expired
Issued Date: 2/18/1997
LFD Permit Id: Not reported

Facility Id: 31009465
Permit Id: P00002
Permit Status: Expired
Issued Date: 3/14/1997
LFD Permit Id: Not reported

Inspection:

Facility Id: 31009465
Permit Number: P00001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PUBLIC WORKS BUILDING (Continued)

U003975327

Code: 103
Inspection Type: Final

Facility Id: 31009465
Permit Number: P00002
Code: 303
Inspection Type: Final

Tank ID: T00001
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Removed
Install Date: Not reported
Content: Diesel
Capacity: 4000
Corrosion Protection Tank: Not reported
CAS #: 68334-30-5
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Not reported
Date Removed: 2/7/1997
Date Last Use: 2/7/1997
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported
Release Detection On Piping: Not reported

Tank ID: T00002
Tank Type: Other
Tank Status: Removed
Install Date: Not reported
Content: Gasoline
Capacity: 8000
Corrosion Protection Tank: Not reported
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Not reported
Date Removed: 2/7/1997
Date Last Use: 2/7/1997
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported
Release Detection On Piping: Not reported

Tank ID: T00003
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Currently In Use
Install Date: 2/19/1997

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PUBLIC WORKS BUILDING (Continued)

U003975327

Content: Gasoline
Capacity: 6000
Corrosion Protection Tank: None Required
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Double Walled
Piping Type: Suction: valve at dispenser
Release Detection On Piping: No Monitoring Suction/Gravity System

Tank ID: T00004
Tank Type: Double Walled Fiberglass
Tank Status: Currently In Use
Install Date: 2/19/1997
Content: Diesel
Capacity: 6000
Corrosion Protection Tank: None Required
CAS #: 68334-30-5
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Double Walled
Piping Type: Suction: valve at dispenser
Release Detection On Piping: No Monitoring Suction/Gravity System

B9
NE
1/8-1/4
0.176 mi.
929 ft.

ACME WIPER & INDUSTRIAL LAUNDRY
3003 DUCK CREEK RD
CINCINNATI, OH
Site 5 of 5 in cluster B

EDR US Hist Cleaners **1009151670**
N/A

Relative:
Lower

EDR Historical Cleaners:

Name: ACME WIPER & INDUSTRIAL LAUNDRY
Year: 1952
Type: LAUNDRIES

Actual:
574 ft.

Name: ACME WIPER & INDUSTRIAL
Year: 1958
Type: LAUNDRIES

Name: ACME UNIFORM & SHOP TOWEL SUPPLY CO
Year: 1961
Type: LAUNDRIES INDUSTRIAL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C10
SE
1/8-1/4
0.200 mi.
1055 ft.

APKING AUTO SERVICE
2793 ROBERTSON RD
CINCINNATI, OH

EDR US Hist Auto Stat

1009034193
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: APKING AUTO SERVICE
Year: 1964
Type: AUTOMOBILE REPAIRING

Actual:
607 ft.

C11
SE
1/8-1/4
0.200 mi.
1055 ft.

MARSHALL MACHINE SERVICE
2793 ROBERTSON AVE
CINCINNATI, OH

EDR US Hist Auto Stat

1009035846
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: APKING ELMER H
Year: 1947
Type: AUTOMOBILE REPAIRING

Actual:
607 ft.

Name: APKING ELMER H
Year: 1952
Type: AUTOMOBILE REPAIRING

Name: APKING AUTO SERVICE
Year: 1958
Type: AUTOMOBILE REPAIRING

Name: APKING AUTO SERVICE
Year: 1969
Type: AUTOMOBILE REPAIRING

Name: APKING AUTO SERVICE
Year: 1974
Type: AUTOMOBILE REPAIRING

Name: MARSHALL MACHINE SERVICE
Year: 1979
Type: AUTOMOBILE REPAIRING

Name: D & I BODY SHOP
Year: 1983
Type: AUTOMOBILE REPAIRING

Name: MULLER S AUTO SERV
Year: 1989
Type: AUTOMOBILE REPAIRING

Name: MUELLERS AUTO SERVICE
Year: 2000
Address: 2793 ROBERTSON AVE

Name: MUELLERS AUTO SERVICE
Year: 2001
Address: 2793 ROBERTSON AVE

Name: MUELLERS AUTO SERVICE
Year: 2002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MARSHALL MACHINE SERVICE (Continued)

1009035846

Address: 2793 ROBERTSON AVE

Name: MUELLERS AUTO SERVICE
Year: 2003
Address: 2793 ROBERTSON AVE

Name: MUELLERS AUTO SERV
Year: 2004
Address: 2793 ROBERTSON AVE

Name: MUELLERS AUTO SERVICE
Year: 2008
Address: 2793 ROBERTSON AVE

Name: MUELLERS AUTO SERVICE
Year: 2009
Address: 2793 ROBERTSON AVE

Name: MUELLERS AUTO SVC
Year: 2010
Address: 2793 ROBERTSON AVE

Name: MUELLERS AUTO SERVICE
Year: 2011
Address: 2793 ROBERTSON AVE

Name: MULLER AUTO SERVICE
Year: 2012
Address: 2793 ROBERTSON AVE

**C12
SE
1/8-1/4
0.206 mi.
1089 ft.**

**ED & FRANK MOTORS
2795 ROBERTSON AVE
CINCINNATI, OH**

**EDR US Hist Auto Stat 1009034212
N/A**

Site 3 of 9 in cluster C

**Relative:
Lower**

EDR Historical Auto Stations:

**Actual:
607 ft.**

Name: MCCAMMON KARL R
Year: 1940
Type: GASOLINE AND OIL SERVICE STATIONS

Name: KELLEY LOUIS
Year: 1947
Type: GASOLINE AND OIL SERVICE STATIONS

Name: NICK S CORNET SERVICE
Year: 1952
Type: GASOLINE STATIONS

Name: BOB S COMET SERVICE STATION
Year: 1958
Type: GASOLINE STATIONS

Name: HICKEY S GULF SERVICE
Year: 1964
Type: GASOLINE STATIONS

Name: ED & FRANK MOTORS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ED & FRANK MOTORS (Continued)

1009034212

Year: 1969
Type: AUTOMOBILE REPAIRING

Name: ED & FRANK MOTORS
Year: 1974
Type: AUTOMOBILE REPAIRING

Name: ED & FRANK MOTORS
Year: 1974
Type: AUTOMOBILE REPAIRING

Name: ED & FRANK MOTORS
Year: 1979
Type: AUTOMOBILE REPAIRING

Name: ED & FRANK MOTORS
Year: 1983
Type: AUTOMOBILE REPAIRING

Name: ED & FRANK MOTORS
Year: 1989
Type: AUTOMOBILE REPAIRING

C13
SE
1/8-1/4
0.206 mi.
1089 ft.

FORMER ED & FRANK MOTORS
2795 ROBERTSON RD
CINCINNATI, OH 45209

OH LUST **U004090765**
N/A

Site 4 of 9 in cluster C

Relative:
Lower

LUST:

Release Number: 31010036-N00001
Release Date: 07/19/1990
Facility Status: Active
LTF Status: 6 Closure of regulated UST
FR Status: CLO: Closure
Priority: 2
Review Date: 08/19/2014
Class: Responsible Party for release has not yet been determined

Actual:
607 ft.

C14
SE
1/8-1/4
0.218 mi.
1153 ft.

KENNER
2950 ROBERTSON RD
CINCINNATI, OH 45209

OH ARCHIVE UST **U004094324**
N/A

Site 5 of 9 in cluster C

Relative:
Lower

ARCHIVE UST:

Facility Number: 31002065
Owner Name: ACK MOR PROPERTIES
Owner Address: 2790 MADISON RD
Owner City,St,Zip: CINCINNATI, OH 45208

Actual:
606 ft.

Inspection:

Facility Id: 31002065
Permit Number: P00001
Code: 103
Inspection Type: Final

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KENNER (Continued)

U004094324

Tank ID: T00001
Tank Type: Other
Tank Status: Removed
Install Date: Not reported
Content: Unknown
Capacity: Not reported
Corrosion Protection Tank: Not reported
CAS #: Not reported
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Not reported
Date Removed: 4/27/1993
Date Last Use: 4/27/1993
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Unknown
Piping Type: Not reported
Release Detection On Piping: Not reported

Tank ID: T00002
Tank Type: Other
Tank Status: Removed
Install Date: Not reported
Content: Unknown
Capacity: Not reported
Corrosion Protection Tank: Not reported
CAS #: Not reported
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Not reported
Date Removed: 4/27/1993
Date Last Use: 4/27/1993
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Unknown
Piping Type: Not reported
Release Detection On Piping: Not reported

Tank ID: T00003
Tank Type: Other
Tank Status: Removed
Install Date: Not reported
Content: Unknown
Capacity: Not reported
Corrosion Protection Tank: Not reported
CAS #: Not reported
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Not reported
Date Removed: 4/27/1993

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KENNER (Continued)

U004094324

Date Last Use: 4/27/1993
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Unknown
Piping Type: Not reported
Release Detection On Piping: Not reported

C15
SE
1/8-1/4
0.218 mi.
1153 ft.
KENNER
2950 ROBERTSON RD
CINCINNATI, OH 45209
Site 6 of 9 in cluster C

OH UST **U004206721**
N/A

Relative:
Lower

UST:
Facility Id: 31002065
Facility Type: Gas Station
Owner Name: Not reported
Owner Address: Not reported
Owner City/State/Zip: Not reported

Actual:
606 ft.

Tank Number: T00001
Status: REM - Removed
UST Capacity: Not reported
Tank Content: Unknown
Installation Date: Not reported
Construction: Other
Date Last Used: 04/27/1993
Date TCL Closed: Not reported
Date Removed: 04/27/1993
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: Unknown
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KENNER (Continued)

U004206721

Tank Number: T00002
Status: REM - Removed
UST Capacity: Not reported
Tank Content: Unknown
Installation Date: Not reported
Construction: Other
Date Last Used: 04/27/1993
Date TCL Closed: Not reported
Date Removed: 04/27/1993
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: Unknown
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00003
Status: REM - Removed
UST Capacity: Not reported
Tank Content: Unknown
Installation Date: Not reported
Construction: Other
Date Last Used: 04/27/1993
Date TCL Closed: Not reported
Date Removed: 04/27/1993
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KENNER (Continued)

U004206721

Release Detection Comments:	RD Tank: / RD Line:
Piping Configuration:	Not reported
Piping Configuration Comments:	Not reported
Piping Styles:	NA - Not Applicable
Piping Constructions:	OTH - Other (explain)
Piping Construction Comments:	Unknown
Piping Corrosion Protections:	OTH - Other (explain)
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	OTH - Other (explain)
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	NP - None Present
Spill Prevention Manhole Comments:	No
OverFill Prevention:	Not reported
OverFill Prevention Comment:	OverFill Spill: No
Comments:	Not reported

C16
SE
1/8-1/4
0.218 mi.
1153 ft.

HARTE HANKS PRINT
2950 ROBERTSON
CINCINNATI, OH 45209

Site 7 of 9 in cluster C

RCRA-SQG **1001080233**
FINDS **OHR000006858**

Relative:
Lower

RCRA-SQG:

Date form received by agency: 09/19/1995
Facility name: HARTE HANKS PRINT
Facility address: 2950 ROBERTSON
CINCINNATI, OH 45209
EPA ID: OHR000006858
Contact: DAN REISING
Contact address: 2950 ROBERTSON
CINCINNATI, OH 45209
Contact country: US
Contact telephone: (513) 458-7600
Contact email: Not reported
EPA Region: 05
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: HARTE HANKS COMMUNICATIONS INC
Owner/operator address: 200 CONCORDE PL DR #800 PO 269
SAN ANTONIO, TX 78291
Owner/operator country: Not reported
Owner/operator telephone: (210) 829-9000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HARTE HANKS PRINT (Continued)

1001080233

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D011
. Waste name: SILVER

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110004712348

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

The OH-CORE (Ohio - Core) database contains information commonly shared among the Ohio EPA environmental programs. The information is facility-based, general in nature, and used to support specific programmatic systems while simultaneously maintaining an inventory of common facility-related data. Specific programmatic details are maintained in programmatic databases.

C17
SE
1/8-1/4
0.218 mi.
1153 ft.

2950 ROBERTSON AVE
CINCINNATI, OH 45209

Site 8 of 9 in cluster C

Relative:
Lower

EDR Historical Cleaners:

Name: SECURITY AMIRKHANIAN CLEANING
Year: 2010
Address: 2950 ROBERTSON AVE

Actual:
606 ft.

EDR US Hist Cleaners **1015036295**
N/A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015036295

Name: SECURITY AMIRKHANIAN CLEANING & REST
Year: 2011
Address: 2950 ROBERTSON AVE

Name: WIDMERS CLEANERS
Year: 2011
Address: 2950 ROBERTSON AVE

Name: SECURITY AMIRKHANIAN CLEANING & REST
Year: 2012
Address: 2950 ROBERTSON AVE

Name: WIDMER S CLEANERS
Year: 2012
Address: 2950 ROBERTSON AVE

C18
SE
1/8-1/4
0.218 mi.
1153 ft.

OAKLEY COMMERCE CENTER
2950 ROBERTSON RD
CINCINNATI, OH 45209
Site 9 of 9 in cluster C

OH UNREG LTANKS S105904829
N/A

Relative:
Lower

UNREG LTANKS:

Facility Status: A possible incident is reported

Actual:
606 ft.

Facility Id: 312065
Facility Track: 0
Report Number: 3121044
RP Status: Not reported
Inspector: Not reported
Revised Date: 08/09/94
Class: D
Vacant: Not reported
Emrgncy Resp: 2
Authorized By: GILL
Added Date: 04/30/92
Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: OH
Owner Phone: Not reported
Operator Name: Not reported
Operator Address: Not reported
Operator C,S,Z: OH
Operator Phone: Not reported
Remarks: Not reported
Summary: Not reported

Facility County #: 061
Facility Phone: Not reported
Incident Number: 312104400
RP Search Date: Not reported
Coordinator: COCL
Fiscal Tracking: FY92
Priority: 2
Lust Trust Fund: 2
ER By: Not reported
Authorized Date: 08/05/94
Entry By: UNGER

19
WSW
1/8-1/4
0.231 mi.
1221 ft.

SOUTH NORWOOD DRY CLEANERS
2409 ROBERTSON AVE
CINCINNATI, OH

EDR US Hist Cleaners 1009153072
N/A

Relative:
Higher

EDR Historical Cleaners:

Name: SOUTH NORWOOD DRY CLEANERS
Year: 1961
Type: CLEANERS AND DYERS

Actual:
628 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

D20
WNW
1/8-1/4
0.233 mi.
1229 ft.

SIEMENS ENERGY & AUTOMATION
4620 FOREST AVE
NORWOOD, OH 45212

Site 1 of 2 in cluster D

OH UNREG LTANKS
OH NPDES

S105904577
N/A

Relative:
Higher

UNREG LTANKS:

Facility Status: Release is Confirmed

Actual:
629 ft.

Facility Id:	311757	Facility County #:	061
Facility Track:	0	Facility Phone:	513-841-3497
Report Number:	319190	Incident Number:	31919000
RP Status:	Not reported	RP Search Date:	Not reported
Inspector:	Not reported	Coordinator:	COCA
Revised Date:	08/31/90	Fiscal Tracking:	9000
Class:	D	Priority:	2
Vacant:	Not reported	Lust Trust Fund:	2
Emrgncy Resp:	2	ER By:	Not reported
Authorized By:	HODNETT	Authorized Date:	08/31/90
Added Date:	Not reported	Entry By:	UNGER
Owner Name:	SIEMENS ENERGY & AUTOMATION		
Owner Address:	Not reported		
Owner City,St,Zip:	Not reported		
Owner Phone:	Not reported		
Operator Name:	Not reported		
Operator Address:	Not reported		
Operator C,S,Z:	Not reported		
Operator Phone:	Not reported		
Remarks:	0		
Summary:	Not reported		

OH NPDES:

Issue Date:	04/26/2006
Township:	Not reported
Facility Npdes Permit:	1GC01790*AG
Applicant Name:	PAUL HEMMER CONSTRUCTION CO
Applicant Address:	250 GRANDVIEW DR FORT MITCHELL, KY 41017

Issue Date:	04/17/2012
Township:	Not reported
Facility Npdes Permit:	1GR00503*BG
Applicant Name:	SIEMENS INDUSTRY
Applicant Address:	4620 FOREST AVE NORWOOD, OH 45212

D21
WNW
1/8-1/4
0.233 mi.
1229 ft.

SIEMENS INDUSTRY INC
4620 FOREST AVENUE
CINCINNATI, OH 45212

Site 2 of 2 in cluster D

RCRA-LQG
TRIS
FINDS
US AIRS

1000297506
45212SMNSN4620F

Relative:
Higher

RCRA-LQG:

Actual:
629 ft.

Date form received by agency:	02/10/2014
Facility name:	SIEMENS INDUSTRY INC
Facility address:	4620 FOREST AVE NORWOOD, OH 45212
EPA ID:	OHD004258828
Contact:	AARON C SCHWARBER
Contact address:	4620 FOREST AVE NORWOOD, OH 45212
Contact country:	US

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Contact telephone: (513) 841-3443
Contact email: AARON.SCHWARBER@SIEMENS.COM
EPA Region: 05
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: SIEMENS INDUSTRY, INC.
Owner/operator address: 333 OLD MILTON PARKWAY
ALPHARETTA, GA 30005
Owner/operator country: US
Owner/operator telephone: (770) 751-2346
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/17/1977
Owner/Op end date: Not reported

Owner/operator name: SIEMENS INDUSTRY, INC.
Owner/operator address: 3333 OLD MILTON PARKWAY
ALPHARETTA, GA 30005
Owner/operator country: US
Owner/operator telephone: (770) 751-2346
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/17/1977
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: Yes
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D009
- . Waste name: MERCURY

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:

Date form received by agency: 03/07/2012
Site name: SIEMENS INDUSTRY INC
Classification: Large Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D009
- . Waste name: MERCURY

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/29/2010

Site name: SIEMENS INDUSTRY INC

Classification: Large Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D007
- . Waste name: CHROMIUM

- . Waste code: D008
- . Waste name: LEAD

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/05/2009

Site name: SIEMENS ENERGY & AUTOMATION

Classification: Large Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D007
- . Waste name: CHROMIUM

- . Waste code: D008
- . Waste name: LEAD

- . Waste code: D009
- . Waste name: MERCURY

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE(BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/26/2008

Site name: SIEMENS ENERGY & AUTOMATION

Classification: Large Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D007
- . Waste name: CHROMIUM

- . Waste code: D008
- . Waste name: LEAD

- . Waste code: D009
- . Waste name: MERCURY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- Date form received by agency: 02/20/2007
- Site name: SIEMENS ENERGY & AUTOMATION
- Classification: Large Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D007
- . Waste name: CHROMIUM

- . Waste code: D008
- . Waste name: LEAD

- . Waste code: D009
- . Waste name: MERCURY

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE(BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 03/01/2006

Site name: SIEMENS ENERGY & AUTOMATION INC

Classification: Large Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D007
- . Waste name: CHROMIUM

- . Waste code: D008
- . Waste name: LEAD

- . Waste code: D009
- . Waste name: MERCURY

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE(BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/24/2005

Site name: SIEMENS ENERGY & AUTOMATION

Classification: Large Quantity Generator

Date form received by agency: 02/21/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Site name: SIEMENS ENERGY & AUTOMATION INC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/28/2003

Site name: SIEMENS ENERGY & AUTOMATION INC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

- . Waste code: D009
- . Waste name: MERCURY

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/15/2002

Site name: SIEMENS ENERGY & AUTOMATION INC

Classification: Small Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D007
- . Waste name: CHROMIUM

- . Waste code: D008
- . Waste name: LEAD

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE(BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/28/2000

Site name: SIEMENS ENERGY & AUTOMATION INC.

Classification: Large Quantity Generator

Date form received by agency: 06/21/1999

Site name: SIEMENS ENERGY AND AUTOMATION INC

Classification: Large Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE WASTE
- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE(BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/26/1998

Site name: SIEMENS ENERGY & AUTOMATION INC.

Classification: Large Quantity Generator

Date form received by agency: 02/29/1996

Site name: SIEMENS ENERGY & AUTOMATION INC.

Classification: Large Quantity Generator

Date form received by agency: 02/17/1994

Site name: SIEMENS ENERGY & AUTOMATION INC

Classification: Large Quantity Generator

Date form received by agency: 02/24/1992

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Site name: SIEMENS ENERGY & AUTOMATION INC
Classification: Large Quantity Generator

Date form received by agency: 02/23/1990

Site name: SIEMENS ENERGY & AUTOMATION INC
Classification: Large Quantity Generator

Date form received by agency: 11/14/1980

Site name: SIEMENS ENERGY AND AUTOMATION INC
Classification: Not a generator, verified

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F010
. Waste name: QUENCHING BATH RESIDUES FROM OIL BATHS FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: F011
. Waste name: SPENT CYANIDE SOLUTIONS FROM SLAT BATH POT CLEANING FROM METAL HEAT TREATING OPERATIONS.

. Waste code: U002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)
. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)
. Waste code: U131
. Waste name: ETHANE, HEXACHLORO- (OR) HEXACHLOROETHANE
. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)
. Waste code: U160
. Waste name: 2-BUTANONE, PEROXIDE (R,T) (OR) METHYL ETHYL KETONE PEROXIDE (R,T)
. Waste code: U171
. Waste name: 2-NITROPROPANE (I,T) (OR) PROPANE, 2-NITRO- (I,T)
. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE
. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM
. Waste code: U228
. Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE
. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 01/01/1979

Site name: SIEMENS ENERGY AND AUTOMATION INC

Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 27679

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BE WASTE GUNPOWDER.

Amount (Lbs): 6100

Waste code: D009
Waste name: MERCURY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Amount (Lbs): 5

Waste code: D035
Waste name: METHYL ETHYL KETONE
Amount (Lbs): 23450

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 27135

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 27135

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 11/09/2010
Date achieved compliance: 03/09/2011
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/01/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 11/09/2010
Date achieved compliance: 11/09/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/01/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Paid penalty amount: Not reported

Regulation violated: SR - 3745-52-41(A)(5)&(8)
Area of violation: Generators - Records/Reporting
Date violation determined: 03/29/2006
Date achieved compliance: 04/03/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/29/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 04/07/2005
Date achieved compliance: 11/13/2006
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 11/13/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 4400
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 04/07/2005
Date achieved compliance: 11/13/2006
Violation lead agency: State
Enforcement action: Director-Division Warning Letter
Enforcement action date: 07/21/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-52(D)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/28/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Regulation violated: SR - 3745-65-52(F)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/28/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-33(A)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/28/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(C)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-52-34(A)(3)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 12/07/1999
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/28/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(D)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(A)(2)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/28/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-52(D)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-52-34(C)(1)(b)
Area of violation: Generators - Pre-transport

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Date violation determined: 12/07/1999
Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(D)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/10/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(B)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(C)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/28/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-52(F)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/10/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-52-34(A)(2)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 12/07/1999
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-52(E)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/28/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-52(F)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-33(A)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-52(E)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(B)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/28/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(A)(2)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 02/10/2000
Violation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-52(E)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/10/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-65-16(D)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 03/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/28/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 3745-66-73(A)
Area of violation: Generators - Pre-transport
Date violation determined: 12/07/1999
Date achieved compliance: 12/07/1999
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 11/09/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 03/09/2011
Evaluation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Evaluation date: 11/09/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 11/09/2010
Evaluation lead agency: State

Evaluation date: 11/13/2006
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/29/2006
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Records/Reporting
Date achieved compliance: 04/03/2006
Evaluation lead agency: State

Evaluation date: 03/07/2006
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/07/2005
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: State Statute or Regulation
Date achieved compliance: 11/13/2006
Evaluation lead agency: State

Evaluation date: 12/07/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 12/07/1999
Evaluation lead agency: State

Evaluation date: 12/07/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 02/10/2000
Evaluation lead agency: State

Evaluation date: 12/07/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 03/31/2000
Evaluation lead agency: State

TRIS:

[Click this hyperlink](#) while viewing on your computer to access
7 additional US_TRIS: record(s) in the EDR Site Report.

FINDS:

Registry ID: 110001626535

Environmental Interest/Information System

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

AIR MINOR

The OH-CORE (Ohio - Core) database contains information commonly shared among the Ohio EPA environmental programs. The information is facility-based, general in nature, and used to support specific programmatic systems while simultaneously maintaining an inventory of common facility-related data. Specific programmatic details are maintained in programmatic databases.

AIRS (AFS):

Airs Minor Details:

EPA plant ID:	110001626535
Plant name:	SIEMENS ENERGY & AUTOMATION, INC.
Plant address:	4620 FOREST AVENUE CINCINNATI, OH 45212
County:	HAMILTON
Region code:	05
Dunn & Bradst #:	004258828
Air quality cntrl region:	079
Sic code:	3621
Sic code desc:	MOTOR AND GENERATORS
North Am. industrial classf:	335312

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

NAIC code description: Motor and Generator Manufacturing
Default compliance status: IN COMPLIANCE - CERTIFICATION
Default classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility: ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR
LOCAL GOVERNMENT
Current HPV: Not reported

Historical Compliance Minor Sources:

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1403
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1401
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1402
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1304
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE - CERTIFICATION
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIEMENS INDUSTRY INC (Continued)

1000297506

Compliance & Violation Data by Minor Sources:

Air program code: SIP SOURCE
Plant air program pollutant: VOLATILE ORGANIC COMPOUNDS
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE - CERTIFICATION
Def. attainment/non attainment: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

E22
North
1/4-1/2
0.257 mi.
1356 ft.

SHEPHERD CHEMICAL CO, NORWOOD
4900 BEECH ST
NORWOOD, OH 45212

OH DERR
OH SPILLS
OH AIRS

S106958329
N/A

Site 1 of 2 in cluster E

Relative:
Lower

DERR:

DERR ID: 531000968
District: SWDO
Alias: Not reported
Lat/Long: 39.1655 -84.4336
EPA ID: Not reported
Program: Not reported

Actual:
620 ft.

SPILLS:

Spill No.: 9204-31-1322
Spill Number: 1322
Spill Month/Year: 4/1992
Date Spill Reported: 04/10/1992
Reporter Name: FD
Confidential: No
District Code: SW
Employee Number: Not reported
Product Spilled Name: NOX
Lat/Long: Not reported

Spill No.: 1305-31-1162
Spill Number: 1162
Spill Month/Year: 5/2013
Date Spill Reported: 05/29/2013
Reporter Name: LYNN BARTLETT
Confidential: Not reported
District Code: SW
Employee Number: Not reported
Product Spilled Name: UNISOL LIQUID RED
Lat/Long: Not reported

Spill No.: 1406-31-1270
Spill Number: 1270
Spill Month/Year: 6/2014
Date Spill Reported: 06/24/2014
Reporter Name: BAYARD PELSOR
Confidential: Not reported
District Code: SW
Employee Number: 1799
Product Spilled Name: NOX
Lat/Long: 3909563 / 8426166

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SHEPHERD CHEMICAL CO, NORWOOD (Continued)

S106958329

AIRS:

Facility Id: 1431370150
Permit Classification: PI
Emission Units Meeting Def of Trivial Outlined in EngGuide62: 0
Insignificant Emission Units: 18
Significant Emission Units: 8
Contact First Name: Lisa
Contact Last Name: Thamann
Mailing Address 1: 4900 BEECH ST
Mailing Address 2: Not reported
Mailing City/State/Zip: CINCINNATI, OH 45212
Contact Phone: 5134586819
Contact EMail: lthamann@shepchem.com
Lat Deg: 39
Lat Min: 9
Lat Sec: 54.8
Lon Deg: -84
Lon Min: 26
Lon Sec: 13.929

F23
WSW
1/4-1/2
0.273 mi.
1440 ft.

KNOWLTON MFG.
2524 LESLIE AVE
CINCINNATI, OH 45212

Site 1 of 2 in cluster F

OH LUST **U004206596**
OH UST **N/A**

Relative:
Higher

LUST:

Actual:
630 ft.

Release Number: 31001415-N00001
Release Date: 08/14/1995
Facility Status: Active
LTF Status: 1 SUS/CON from regulated UST
FR Status: T2E: Tier 2 Evaluation
Priority: 2
Review Date: 09/17/2014
Class: Viable Responsible Party has been identified

Release Number: 31001415-N00002
Release Date: 10/14/1999
Facility Status: Active
LTF Status: 6 Closure of regulated UST
FR Status: NFC: No Further Action Data Cleaning
Priority: 2
Review Date: 09/17/2013
Class: Viable Responsible Party has been identified

UST:

Facility Id: 31001415
Facility Type: Commercial
Owner Name: Not reported
Owner Address: Not reported
Owner City/State/Zip: Not reported

Tank Number: T00001
Status: REM - Removed
UST Capacity: 550
Tank Content: Gasoline
Installation Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KNOWLTON MFG. (Continued)

U004206596

Construction: BM - Bare Metal
Date Last Used: 11/01/1991
Date TCL Closed: Not reported
Date Removed: 07/18/1995
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Bare Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00002
Status: REM - Removed
UST Capacity: 2000
Tank Content: Heating Oil
Installation Date: Not reported
Construction: Other
Date Last Used: 07/18/1995
Date TCL Closed: Not reported
Date Removed: 07/18/1995
CAS Number: 68476-30-2
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: OTH - Other (explain)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KNOWLTON MFG. (Continued)

U004206596

Piping Construction Comments: Unknown
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

G24
NNW
1/4-1/2
0.281 mi.
1485 ft.

KLEIMAN AUTO BODY INC
2506 NORWOOD AVE
NORWOOD, OH 45212

OH LUST **U004094475**
N/A

Site 1 of 2 in cluster G

Relative:
Higher

LUST:

Release Number: 31010248-N00001
Release Date: 10/18/1993

Actual:
622 ft.

Facility Status: Active
LTF Status: 1 SUS/CON from regulated UST
FR Status: T1S: Tier 1 Source Investigation

Priority: 2
Review Date: 08/21/2014
Class: Responsible Party for release has not yet been determined

G25
NNW
1/4-1/2
0.286 mi.
1509 ft.

DEE SIGN CO
2501 NORWOOD
CINCINNATI, OH 45212

CERC-NFRAP **1000131838**
RCRA NonGen / NLR **OHD041593427**
OH DERR

Site 2 of 2 in cluster G

Relative:
Higher

CERC-NFRAP:

Site ID: 0504329
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Actual:
623 ft.

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY
Date Started: / /
Date Completed: 06/01/81
Priority Level: Not reported

Action: ARCHIVE SITE
Date Started: / /
Date Completed: 09/01/84
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 09/01/84
Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEE SIGN CO (Continued)

1000131838

RCRA NonGen / NLR:

Date form received by agency: 09/15/1998
Facility name: KDM SIGNS
Facility address: 2501 NORWOOD AVE
CINCINNATI, OH 452122725
EPA ID: OHD041593427
Contact: MICHELLE RINEHART
Contact address: 2501 NORWOOD AVE
CINCINNATI, OH 452122725
Contact country: US
Contact telephone: (513) 351-1733
Contact email: Not reported
EPA Region: 05
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NAME NOT REPORTED
Owner/operator address: ADDRESS NOT REPORTED
CITY NOT REPORTED, AK 99998
Owner/operator country: Not reported
Owner/operator telephone: (312) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: KISSEL WILLIAM A
Owner/operator address: 2501 NOWOOD AVE
CINCINNATI, OH 45212
Owner/operator country: Not reported
Owner/operator telephone: (513) 351-1733
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEE SIGN CO (Continued)

1000131838

- . Waste name: IGNITABLE WASTE
- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:

Date form received by agency: 02/24/1992
Site name: DEE SIGN COMPANY
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 03/11/1988
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/11/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

DERR:

DERR ID: 531000221
District: SWDO
Alias: Not reported
Lat/Long: 39.1636 -84.4447
EPA ID: OHD041593427
Program: Site Assessment

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

E26
North
1/4-1/2
0.287 mi.
1516 ft.

J.H. DAY COMPANY
4932 BEECH ST
CINCINNATI, OH 45212

Site 2 of 2 in cluster E

OH LUST
OH UST

U004206837
N/A

Relative:
Lower

LUST:

Release Number: 31002561-N00001
Release Date: 11/04/1992
Facility Status: Active
LTF Status: 6 Closure of regulated UST
FR Status: CLO: Closure
Priority: 2
Review Date: 08/22/2014
Class: Responsible Party is non-viable

Actual:
620 ft.

UST:

Facility Id: 31002561
Facility Type: Gas Station
Owner Name: Not reported
Owner Address: Not reported
Owner City/State/Zip: Not reported

Tank Number: T00001
Status: REM - Removed
UST Capacity: 550
Tank Content: Gasoline
Installation Date: Not reported
Construction: BM - Bare Metal
Date Last Used: 01/01/1973
Date TCL Closed: Not reported
Date Removed: 11/04/1992
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Bare Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F27
WSW
1/4-1/2
0.307 mi.
1620 ft.
UNITED DAIRY FARMERS #075
4344 SMITH RD
CINCINNATI, OH 45212
Site 2 of 2 in cluster F

OH LUST
OH UST
OH ARCHIVE UST
U000892267
N/A

Relative:
Higher

LUST:

Release Number: 31000457-N00002
Release Date: 05/10/2012
Facility Status: Active
LTF Status: 1 SUS/CON from regulated UST
FR Status: T2E: Tier 2 Evaluation
Priority: 2
Review Date: 03/24/2014
Class: Viable Responsible Party has been identified

Actual:
630 ft.

UST:

Facility Id: 31000457
Facility Type: Gas Station
Owner Name: UNITED DAIRY FARMERS
Owner Address: 3955 MONTGOMERY RD
Owner City/State/Zip: 45212

Tank Number: T00001
Status: CIU - Currently In Use
UST Capacity: 10000
Tank Content: Gasoline
Installation Date: 06/01/1984
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: SW - Single Wall
Construction Comments: Not reported
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: ATG - Automatic Tank Gauging
Release Detection Comments: Not reported
Piping Configuration: SW - Single Wall
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Not reported
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: FILL - Fill Pipe (drop tube flapper)
OverFill Prevention Comment: Not reported
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED DAIRY FARMERS #075 (Continued)

U000892267

Tank Number: T00002
Status: CIU - Currently In Use
UST Capacity: 10000
Tank Content: Gasoline
Installation Date: 06/01/1984
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: SW - Single Wall
Construction Comments: Not reported
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: ATG - Automatic Tank Gauging
Release Detection Comments: Not reported
Piping Configuration: SW - Single Wall
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Not reported
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: FILL - Fill Pipe (drop tube flapper)
OverFill Prevention Comment: Not reported
Comments: Not reported

ARCHIVE UST:

Facility Number: 31000457
Owner Name: UNITED DAIRY FARMERS
Owner Address: 3955 MONTGOMERY RD
Owner City,St,Zip: CINCINNATI, OH 45212

Permit:

Facility Id: 31000457
Permit Id: P00001
Permit Status: Expired
Issued Date: 1/12/1994
LFD Permit Id: Not reported

Facility Id: 31000457
Permit Id: P00002
Permit Status: Closed
Issued Date: 6/20/2000
LFD Permit Id: Not reported

Inspection:

Facility Id: 31000457

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED DAIRY FARMERS #075 (Continued)

U000892267

Permit Number: P00002
Code: 302
Inspection Type: Final

Facility Id: 31000457
Permit Number: P00001
Code: 302
Inspection Type: Preliminary

Facility Id: 31000457
Permit Number: P00001
Code: 302
Inspection Type: Preliminary

Tank ID: T00001
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Currently In Use
Install Date: 6/1/1984
Content: Gasoline
Capacity: 10000
Corrosion Protection Tank: None Required
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Fiberglass Reinforced Plastic
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00002
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Currently In Use
Install Date: 6/1/1984
Content: Gasoline
Capacity: 10000
Corrosion Protection Tank: None Required
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Fiberglass Reinforced Plastic
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

28
NW
1/4-1/2
0.328 mi.
1734 ft.

THE C.W. ZUMBIEL CO
2339 HARRIS AVE
NORWOOD, OH 45212

OH LUST
OH UST

U004218305
N/A

Relative:
Lower

LUST:

Release Number: 31009853-N00001
Release Date: Not reported
Facility Status: Inactive
LTF Status: 6 Closure of regulated UST
FR Status: NFA: No Further Action
Priority: 3
Review Date: 06/20/2000
Class: Viable Responsible Party has been identified

Actual:
619 ft.

UST:

Facility Id: 31009853
Facility Type: Commercial
Owner Name: Not reported
Owner Address: Not reported
Owner City/State/Zip: Not reported

Tank Number: T00001
Status: CIS - Change in Service
UST Capacity: 2000
Tank Content: Other Petroleum Distillate
Installation Date: 08/20/1998
Construction: Other
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: NO
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Double Walled (Interstice)
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Automatic Tank Gauging; Interstitial Monitoring Double Walled /
RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: Double Walled
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: IMT - Interstitial Monitoring
Piping Release Detection Comments: Interstitial Monitoring Double Walled
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Yes
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: Yes
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

29
ESE
1/4-1/2
0.344 mi.
1818 ft.

VACANT LOT
2970 ROBERTSON AVENUE
CINCINNATI, OH 45208

OH LUST
OH UST

U004207191
N/A

Relative:
Lower

LUST:

Release Number: 31010514-N00001
Release Date: 08/30/2001
Facility Status: Inactive
LTF Status: 6 Closure of regulated UST
FR Status: NFA: No Further Action
Priority: 2
Review Date: 02/20/2002
Class: Viable Responsible Party has been identified

Actual:
599 ft.

UST:

Facility Id: 31010514
Facility Type: Other
Owner Name: Not reported
Owner Address: Not reported
Owner City/State/Zip: Not reported

Tank Number: T00001
Status: REM - Removed
UST Capacity: 1000
Tank Content: Diesel
Installation Date: 01/01/1989
Construction: Other
Date Last Used: 08/30/2001
Date TCL Closed: Not reported
Date Removed: 08/30/2001
CAS Number: 68334-30-5
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: Secondary Containment
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: OTH - Other (Explain)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: Not reported
OverFill Prevention Comment: Not reported
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

30
South
1/4-1/2
0.389 mi.
2054 ft.

BP OIL CO. #08942
4004 EDWARDS RD
CINCINNATI, OH 45209

OH LUST
OH UST

U004206607
N/A

Relative:
Higher

LUST:

Actual:
626 ft.

Release Number: 31001458-N00001
Release Date: Not reported
Facility Status: Inactive
LTF Status: 1 SUS/CON from regulated UST
FR Status: DIS: a release is disproved
Priority: 2
Review Date: 06/20/2000
Class: Responsible Party for release has not yet been determined

Release Number: 31001458-N00002
Release Date: Not reported
Facility Status: Inactive
LTF Status: 1 SUS/CON from regulated UST
FR Status: NFA: No Further Action
Priority: 2
Review Date: 06/20/2000
Class: Viable Responsible Party has been identified

UST:

Facility Id: 31001458
Facility Type: Gas Station
Owner Name: KANTAM ENTERPRISES LLC
Owner Address: 6135 MONTGOMERY ROAD
Owner City/State/Zip: 45213

Tank Number: T00001
Status: REM - Removed
UST Capacity: 8000
Tank Content: Unknown
Installation Date: Not reported
Construction: Other
Date Last Used: 04/21/1993
Date TCL Closed: Not reported
Date Removed: 04/21/1993
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: Unknown
Piping Corrosion Protections: OTH - Other (explain)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP OIL CO. #08942 (Continued)

U004206607

Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00002
Status: REM - Removed
UST Capacity: 8000
Tank Content: Unknown
Installation Date: Not reported
Construction: Other
Date Last Used: 04/21/1993
Date TCL Closed: Not reported
Date Removed: 04/21/1993
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: Unknown
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00003
Status: REM - Removed
UST Capacity: 6000
Tank Content: Unknown
Installation Date: Not reported
Construction: Other
Date Last Used: 04/21/1993
Date TCL Closed: Not reported
Date Removed: 04/21/1993
CAS Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP OIL CO. #08942 (Continued)

U004206607

Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: Unknown
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00004
Status: REM - Removed
UST Capacity: 1000
Tank Content: Unknown
Installation Date: Not reported
Construction: Other
Date Last Used: 04/21/1993
Date TCL Closed: Not reported
Date Removed: 04/21/1993
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: Unknown
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP OIL CO. #08942 (Continued)

U004206607

Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

31
North
1/4-1/2
0.390 mi.
2060 ft.

KING RECYCLING
5038 BEECH STREET
NORWOOD, OH 45212

OH SWRCY
OH SPILLS

S111003405
N/A

Relative:
Higher

SWRCY:
Facility Type: Scrap Yard
Owner Type: Privately Owned
Contact Name: Not reported
Contact Phone: (513) 731-7222
Materials Accepted: Not reported

Actual:
626 ft.

SPILLS:
Spill No.: 1104-31-1020
Spill Number: 1020
Spill Month/Year: 4/2011
Date Spill Reported: 04/04/2011
Reporter Name: ROB PAXTON
Confidential: Not reported
District Code: SW
Employee Number: 1767
Product Spilled Name: PIGMENT RESIDUE/SOLUTION
Product Spilled Name: PIGMENT RESIDUE/SOLUTION
Product Spilled Name: PIGMENT RESIDUE/SOLUTION
Lat/Long: 3909589 / 8426258

32
SSW
1/4-1/2
0.392 mi.
2068 ft.

SPEEDWAY #9582
2713 WILLIAMS AVE
CINCINNATI, OH 45209

OH LUST
OH UST
OH ARCHIVE UST

U000892516
N/A

Relative:
Higher

LUST:
Release Number: 31001765-N00001
Release Date: Not reported
Facility Status: Inactive
LTF Status: 1 SUS/CON from regulated UST
FR Status: NFA: No Further Action
Priority: 2
Review Date: 06/20/2000
Class: Viable Responsible Party has been identified

Actual:
626 ft.

Release Number: 31001765-N00002
Release Date: 10/22/2003
Facility Status: Inactive
LTF Status: 1 SUS/CON from regulated UST
FR Status: DIS: a release is disproved
Priority: 2
Review Date: 11/07/2003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #9582 (Continued)

U000892516

Class: Viable Responsible Party has been identified

UST:

Facility Id: 31001765
Facility Type: Gas Station
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 1500
Owner City/State/Zip: 45501

Tank Number: T00001
Status: CIU - Currently In Use
UST Capacity: 12000
Tank Content: Gasoline
Installation Date: 01/01/1989
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Fiberglass Reinforced Plastic
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Automatic Tank Gauging / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Fiberglass Reinforced Plastic
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Electronic Line Leak Detector
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Yes
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: Yes
Comments: Not reported

Tank Number: T00002
Status: CIU - Currently In Use
UST Capacity: 10000
Tank Content: Gasoline
Installation Date: 01/01/1989
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #9582 (Continued)

U000892516

Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: SW - FRP - Fiberglass
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Automatic Tank Gauging / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: FPTP - Flexible Plastic Technology Piping
Piping Construction Comments: SW FPTP - Flex Pipe
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Electronic Line Leak Detector
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Yes
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: Yes
Comments: Not reported

Tank Number: T00003
Status: CIU - Currently In Use
UST Capacity: 8000
Tank Content: Gasoline
Installation Date: 01/01/1989
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: SW - FRP - Fiberglass
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Automatic Tank Gauging / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: SW FRP - Fiberglass
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Electronic Line Leak Detector
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #9582 (Continued)

U000892516

Spill Prevention Manhole Comments: Yes
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: Yes
Comments: Not reported

Tank Number: T00004
Status: CIU - Currently In Use
UST Capacity: 8000
Tank Content: Gasoline
Installation Date: 01/01/1989
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Fiberglass Reinforced Plastic
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Automatic Tank Gauging / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Fiberglass Reinforced Plastic
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Electronic Line Leak Detector
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Yes
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: Yes
Comments: Not reported

Tank Number: T00005
Status: CIU - Currently In Use
UST Capacity: 4000
Tank Content: Diesel
Installation Date: 01/01/1989
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 68334-30-5
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #9582 (Continued)

U000892516

UST Configurations:	Not reported
Construction Comments:	Fiberglass Reinforced Plastic
Corrosion Protections:	NR - None Required by Rule
Corrosion Protection Comments:	Not reported
Primary Release Detection:	ATG - Automatic Tank Gauging
Secondary Release Detection:	Not reported
Release Detection Comments:	RDTank: Automatic Tank Gauging / RDLine:
Piping Configuration:	Not reported
Piping Configuration Comments:	Not reported
Piping Styles:	S - Suction
Piping Constructions:	FRP - Fiberglass Reinforced Plastic
Piping Construction Comments:	Fiberglass Reinforced Plastic
Piping Corrosion Protections:	NR - None required by rule
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	SS - Safe Suction
Piping Release Detection Comments:	No Monitoring Suction/Gravity System
Spill Prevention Manholes:	SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments:	Yes
OverFill Prevention:	Not reported
OverFill Prevention Comment:	OverFill Spill: Yes
Comments:	Not reported

ARCHIVE UST:

Facility Number:	31001765
Owner Name:	SPEEDWAY LLC
Owner Address:	PO BOX 1500
Owner City,St,Zip:	SPRINGFIELD, OH 45501

Permit:

Facility Id:	31001765
Permit Id:	P00001
Permit Status:	Expired
Issued Date:	6/3/1994
LFD Permit Id:	Not reported

Facility Id:	31001765
Permit Id:	P00002
Permit Status:	Closed
Issued Date:	10/5/2005
LFD Permit Id:	Not reported

Facility Id:	31001765
Permit Id:	P00003
Permit Status:	Active
Issued Date:	8/16/2010
LFD Permit Id:	Not reported

Inspection:

Facility Id:	31001765
Permit Number:	P00003
Code:	502
Inspection Type:	Final

Facility Id:	31001765
Permit Number:	P00001
Code:	302
Inspection Type:	Final

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #9582 (Continued)

U000892516

Facility Id: 31001765
Permit Number: P00002
Code: 504
Inspection Type: Final

Tank ID: T00001
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Currently In Use
Install Date: 1/1/1989
Content: Gasoline
Capacity: 12000
Corrosion Protection Tank: None Required
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Fiberglass Reinforced Plastic
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00002
Tank Type: SW - FRP - Fiberglass
Tank Status: Currently In Use
Install Date: 1/1/1989
Content: Gasoline
Capacity: 10000
Corrosion Protection Tank: NR - None Required by Rule
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NR - None Required
Piping Material: SW FPTP - Flex Pipe
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00003
Tank Type: SW - FRP - Fiberglass
Tank Status: Currently In Use
Install Date: 1/1/1989
Content: Gasoline
Capacity: 8000
Corrosion Protection Tank: NR - None Required by Rule

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #9582 (Continued)

U000892516

CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NR - None Required
Piping Material: SW FRP - Fiberglass
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00004
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Currently In Use
Install Date: 1/1/1989
Content: Gasoline
Capacity: 8000
Corrosion Protection Tank: None Required
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Fiberglass Reinforced Plastic
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00005
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Currently In Use
Install Date: 1/1/1989
Content: Diesel
Capacity: 4000
Corrosion Protection Tank: None Required
CAS #: 68334-30-5
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Fiberglass Reinforced Plastic
Piping Type: Suction: valve at dispenser
Release Detection On Piping: No Monitoring Suction/Gravity System

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

H33
NNW
1/4-1/2
0.426 mi.
2248 ft.

PERRY & DERRICK PAINT SITE
2511 HIGHLAND AVENUE
NORWOOD, OH 45212

Site 1 of 2 in cluster H

CERCLIS
ICIS
PRP

1014914989
OHN000510588

Relative:
Higher

CERCLIS:

Actual:
671 ft.

Site ID: 0510588
EPA ID: OHN000510588
Facility County: HAMILTON
Short Name: PERRY & DERRICK PAINT SIT
Congressional District: 01
IFMS ID: C539
SMSA Number: Not reported
USGC Hydro Unit: Not reported
Federal Facility: Not a Federal Facility
DMNSN Number: 0.00000
Site Orphan Flag: Not reported
RCRA ID: Not reported
USGS Quadrangle: Not reported
Site Init By Prog: S
NFRAP Flag: Not reported
Parent ID: Not reported
RST Code: Not reported
EPA Region: 05
Classification: Not reported
Site Settings Code: Not reported
NPL Status: Not on the NPL
DMNSN Unit Code: Not reported
RBRAC Code: Not reported
RResp Fed Agency Code: Not reported
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)
Non NPL Status Date: 04/27/11
Site Fips Code: 39061
CC Concurrence Date: / /
CC Concurrence FY: Not reported
Alias EPA ID: Not reported
Site FUDS Flag: Not reported

CERCLIS Site Contact Name(s):

Contact ID: 5270195.00000
Contact Name: STEVEN L. RENNINGER
Contact Tel: (513) 260-7849
Contact Title: On-Scene Coordinator (OSC)
Contact Email: Not reported

Alias Comments: Not reported

Site Description: On April 27, 2011, the Norwood Fire Department (NFD) discovered a potential hazardous situation at the Perry & Derrick Paint Site located at 2511 Highland Avenue in Norwood, Ohio. The NFD requested assistance from the U.S. EPA to perform a site investigation and to evaluate the site for a potential time-critical removal action. The site contains multiple buildings containing large quantities of known and unknown chemicals. U.S. EPA estimated there are approximately 1,500 55-gallon drums, over

CERCLIS Assessment History:

Action Code: 001
Action: REMOVAL ASSESSMENT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK PAINT SITE (Continued)

1014914989

Date Started: 04/27/11
Date Completed: 04/29/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: Notice Letters Issued
Date Started: / /
Date Completed: 05/05/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 05/10/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 006
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 05/12/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 005
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 05/12/11
Priority Level: Not reported
Operable Unit: SITEWIDE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK PAINT SITE (Continued)

1014914989

Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 05/12/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 05/12/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 004
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 05/12/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 007
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 05/20/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK PAINT SITE (Continued)

1014914989

Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 008
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 05/23/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 06/16/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: Notice of Intent by All Parties
Date Started: / /
Date Completed: 07/08/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 009
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 10/25/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK PAINT SITE (Continued)

1014914989

Action Code: 010
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 11/01/11
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMOVAL
Date Started: 08/24/11
Date Completed: 12/28/11
Priority Level: Cleaned up
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Time Critical
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: POTENTIALLY RESPONSIBLE PARTY REMOVAL
Date Started: 07/15/11
Date Completed: 04/03/12
Priority Level: Cleaned up
Operable Unit: SITEWIDE
Primary Responsibility: Responsible Party
Planning Status: Primary
Urgency Indicator: Time Critical
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: NON-NATIONAL PRIORITIES LIST POTENTIALLY RESPONSIBLE PARTY SEARCH
Date Started: / /
Date Completed: 04/03/12
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 011
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 04/30/12
Priority Level: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK PAINT SITE (Continued)

1014914989

Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

[Click this hyperlink](#) while viewing on your computer to access
120 additional US CERCLIS Financial: record(s) in the EDR Site Report.

ICIS:

Enforcement Action ID: 05-2011-1017
FRS ID: 110043571015
Program ID: BR OHD004246468
Action Name: PERRY & DERRICK PAINT UNILATERAL ADMIN ORDER (CERCLA)
Full Address: 2511 HIGHLAND AVENUE NORWOOD OH 45212
State: Ohio
Facility Name: PERRY & DERRICK PAINT SITE
Facility Address: 2511 HIGHLAND AVENUE
NORWOOD, OH 45212
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: HAMILTON
EPA Region #: 5

Enforcement Action ID: 05-2011-1017
FRS ID: 110043571015
Program ID: RCRAINFO OHD004246468
Action Name: PERRY & DERRICK PAINT UNILATERAL ADMIN ORDER (CERCLA)
Full Address: 2511 HIGHLAND AVENUE NORWOOD OH 45212
State: Ohio
Facility Name: PERRY & DERRICK PAINT SITE
Facility Address: 2511 HIGHLAND AVENUE
NORWOOD, OH 45212
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: HAMILTON
EPA Region #: 5

Enforcement Action ID: 05-2011-1017
FRS ID: 110043571015
Program ID: FRS 110043571015
Action Name: PERRY & DERRICK PAINT UNILATERAL ADMIN ORDER (CERCLA)
Full Address: 2511 HIGHLAND AVENUE NORWOOD OH 45212
State: Ohio
Facility Name: PERRY & DERRICK PAINT SITE
Facility Address: 2511 HIGHLAND AVENUE
NORWOOD, OH 45212
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: HAMILTON
EPA Region #: 5

Enforcement Action ID: 05-2011-1017
FRS ID: 110043571015
Program ID: CERCLIS OHN000510588
Action Name: PERRY & DERRICK PAINT UNILATERAL ADMIN ORDER (CERCLA)
Full Address: 2511 HIGHLAND AVENUE NORWOOD OH 45212

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK PAINT SITE (Continued)

1014914989

State: Ohio
Facility Name: PERRY & DERRICK PAINT SITE
Facility Address: 2511 HIGHLAND AVENUE
NORWOOD, OH 45212
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: HAMILTON
EPA Region #: 5

Program ID: BR OHD004246468
Facility Name: PERRY & DERRICK PAINT SITE
Address: 2511 HIGHLAND AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Program ID: CERCLIS OHN000510588
Facility Name: PERRY & DERRICK PAINT SITE
Address: 2511 HIGHLAND AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Program ID: FRS 110043571015
Facility Name: PERRY & DERRICK PAINT SITE
Address: 2511 HIGHLAND AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Program ID: RCRAINFO OHD004246468
Facility Name: PERRY & DERRICK PAINT SITE
Address: 2511 HIGHLAND AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

PRP:
PRP name: EMD2 CHEMICLAS. INC
JETS2 REALTY GROUP, LLC
JETS2 REALTY GROUP, LLC
MARK DERRICK
MARK2 DERRICK
NORWOOD2 DREAMS LLC
NORWOOD2 DREAMS LLC
P & D PAINTS, LLC
P & D PAINTS, LLC
PERRY2 AND DERRICK COMPANY
PHILIP2 SCHWORER, ESQ
STOOKEY2 CONSTRUCTION, LLC
WINTech2 PRODUCTS
WINTech2 PRODUCTS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

H34
NNW
1/4-1/2
0.427 mi.
2257 ft.

PERRY & DERRICK CO.
2510 HIGHLAND AVE
NORWOOD, OH 45212

Site 2 of 2 in cluster H

OH LUST
OH UST

U004206535
N/A

Relative:
Higher

LUST:

Release Number: 31001224-N00001
Release Date: 09/09/1998
Facility Status: Inactive
LTF Status: 6 Closure of regulated UST
FR Status: NFA: No Further Action
Priority: 3
Review Date: 12/01/1998
Class: Viable Responsible Party has been identified

Actual:
672 ft.

UST:

Facility Id: 31001224
Facility Type: Commercial
Owner Name: Not reported
Owner Address: Not reported
Owner City/State/Zip: Not reported

Tank Number: T00001
Status: REM - Removed
UST Capacity: 4000
Tank Content: Unknown
Installation Date: 01/01/1987
Construction: BM - Bare Metal
Date Last Used: 09/12/1998
Date TCL Closed: Not reported
Date Removed: 09/12/1998
CAS Number: ESTER ALCOHOL
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Cathodically Protected Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Manual Tank Gauging;Tnk Tightness Testing;Statistical Inventory Reconciliation;Ground Water Monitoring / RDLine:

Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Cathodically Protected
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK CO. (Continued)

U004206535

Tank Number: T00002
Status: REM - Removed
UST Capacity: 4000
Tank Content: Unknown
Installation Date: 01/01/1987
Construction: BM - Bare Metal
Date Last Used: 09/12/1998
Date TCL Closed: Not reported
Date Removed: 09/12/1998
CAS Number: ETHYLENE GLYCOL
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Cathodically Protected Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Manual Tank Gauging;Tnk Tightness Testing;Statistical
Inventory Reconciliation;Ground Water Monitoring / RDLLine:

Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Cathodically Protected
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00003
Status: REM - Removed
UST Capacity: 4000
Tank Content: Unknown
Installation Date: 01/01/1987
Construction: BM - Bare Metal
Date Last Used: 09/12/1998
Date TCL Closed: Not reported
Date Removed: 09/12/1998
CAS Number: PROPOLENE GLYCOL
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Cathodically Protected Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK CO. (Continued)

U004206535

Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Manual Tank Gauging;Tnk Tightness Testing;Statistical
Inventory Reconciliation;Ground Water Monitoring / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Cathodically Protected
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00004
Status: REM - Removed
UST Capacity: 4000
Tank Content: Unknown
Installation Date: 01/01/1987
Construction: BM - Bare Metal
Date Last Used: 09/12/1998
Date TCL Closed: Not reported
Date Removed: 09/12/1998
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Cathodically Protected Steel;Epoxy/Ashpalt Coate
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Cathodically Protected
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: 64742-88-7

Tank Number: T00005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK CO. (Continued)

U004206535

Status: REM - Removed
UST Capacity: 4000
Tank Content: Unknown
Installation Date: 01/01/1987
Construction: BM - Bare Metal
Date Last Used: 09/12/1998
Date TCL Closed: Not reported
Date Removed: 09/12/1998
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Cathodically Protected Steel;Epoxy/Ashpalt Coate
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Cathodically Protected
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: 64742-95-6

Tank Number: T00006
Status: REM - Removed
UST Capacity: 4000
Tank Content: Unknown
Installation Date: 01/01/1987
Construction: BM - Bare Metal
Date Last Used: 09/12/1998
Date TCL Closed: Not reported
Date Removed: 09/12/1998
CAS Number: Not reported
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Cathodically Protected Steel;Epoxy/Ashpalt Coate
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK CO. (Continued)

U004206535

Piping Configuration:	Not reported
Piping Configuration Comments:	Not reported
Piping Styles:	S - Suction
Piping Constructions:	BM - Bare Metal
Piping Construction Comments:	Cathodically Protected
Piping Corrosion Protections:	OTH - Other (explain)
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	OTH - Other(explain)
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	NP - None Present
Spill Prevention Manhole Comments:	No
OverFill Prevention:	Not reported
OverFill Prevention Comment:	OverFill Spill: No
Comments:	Not reported
Tank Number:	T00007
Status:	REM - Removed
UST Capacity:	4000
Tank Content:	Unknown
Installation Date:	01/01/1987
Construction:	BM - Bare Metal
Date Last Used:	09/12/1998
Date TCL Closed:	Not reported
Date Removed:	09/12/1998
CAS Number:	VM&P
Abandoned Approved:	Not reported
Regulated:	YES
Sensitive Area:	NO
Date Of Sensitivity:	Not reported
UST Configurations:	Not reported
Construction Comments:	Cathodically Protected Steel
Corrosion Protections:	Not reported
Corrosion Protection Comments:	Not reported
Primary Release Detection:	AMO - Alternative Method (Other, explain)
Secondary Release Detection:	Not reported
Release Detection Comments:	RDTank: Manual Tank Gauging;Tnk Tightness Testing;Statistical Inventory Reconciliation;Ground Water Monitoring / RDLine:
Piping Configuration:	Not reported
Piping Configuration Comments:	Not reported
Piping Styles:	S - Suction
Piping Constructions:	BM - Bare Metal
Piping Construction Comments:	Cathodically Protected
Piping Corrosion Protections:	OTH - Other (explain)
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	OTH - Other(explain)
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	NP - None Present
Spill Prevention Manhole Comments:	No
OverFill Prevention:	Not reported
OverFill Prevention Comment:	OverFill Spill: No
Comments:	Not reported
Tank Number:	T00008
Status:	REM - Removed
UST Capacity:	2000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK CO. (Continued)

U004206535

Tank Content:	Unknown
Installation Date:	01/01/1987
Construction:	BM - Bare Metal
Date Last Used:	09/12/1998
Date TCL Closed:	Not reported
Date Removed:	09/12/1998
CAS Number:	ALIPHATIC HYDROCARB
Abandoned Approved:	Not reported
Regulated:	YES
Sensitive Area:	NO
Date Of Sensitivity:	Not reported
UST Configurations:	Not reported
Construction Comments:	Cathodically Protected Steel;Epoxy/Ashpalt Coate
Corrosion Protections:	Not reported
Corrosion Protection Comments:	Not reported
Primary Release Detection:	AMO - Alternative Method (Other, explain)
Secondary Release Detection:	Not reported
Release Detection Comments:	RDTank: / RDLine:
Piping Configuration:	Not reported
Piping Configuration Comments:	Not reported
Piping Styles:	S - Suction
Piping Constructions:	BM - Bare Metal
Piping Construction Comments:	Cathodically Protected
Piping Corrosion Protections:	OTH - Other (explain)
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	OTH - Other(explain)
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	NP - None Present
Spill Prevention Manhole Comments:	No
OverFill Prevention:	Not reported
OverFill Prevention Comment:	OverFill Spill: No
Comments:	8052-41-3
Tank Number:	T00009
Status:	REM - Removed
UST Capacity:	2000
Tank Content:	Unknown
Installation Date:	01/01/1987
Construction:	BM - Bare Metal
Date Last Used:	09/12/1998
Date TCL Closed:	Not reported
Date Removed:	09/12/1998
CAS Number:	ALIPHATIC HYDROCARB
Abandoned Approved:	Not reported
Regulated:	YES
Sensitive Area:	NO
Date Of Sensitivity:	Not reported
UST Configurations:	Not reported
Construction Comments:	Cathodically Protected Steel
Corrosion Protections:	Not reported
Corrosion Protection Comments:	Not reported
Primary Release Detection:	AMO - Alternative Method (Other, explain)
Secondary Release Detection:	Not reported
Release Detection Comments:	RDTank: Manual Tank Gauging;Tnk Tightness Testing;Statistical Inventory Reconciliation;Ground Water Monitoring / RDLine:
Piping Configuration:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PERRY & DERRICK CO. (Continued)

U004206535

Piping Configuration Comments:	Not reported
Piping Styles:	S - Suction
Piping Constructions:	BM - Bare Metal
Piping Construction Comments:	Cathodically Protected
Piping Corrosion Protections:	OTH - Other (explain)
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	OTH - Other(explain)
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	NP - None Present
Spill Prevention Manhole Comments:	No
OverFill Prevention:	Not reported
OverFill Prevention Comment:	OverFill Spill: No
Comments:	Not reported
Tank Number:	T00010
Status:	REM - Removed
UST Capacity:	2000
Tank Content:	Unknown
Installation Date:	01/01/1987
Construction:	BM - Bare Metal
Date Last Used:	09/12/1998
Date TCL Closed:	Not reported
Date Removed:	09/12/1998
CAS Number:	ESTER
Abandoned Approved:	Not reported
Regulated:	YES
Sensitive Area:	NO
Date Of Sensitivity:	Not reported
UST Configurations:	Not reported
Construction Comments:	Cathodically Protected Steel
Corrosion Protections:	Not reported
Corrosion Protection Comments:	Not reported
Primary Release Detection:	AMO - Alternative Method (Other, explain)
Secondary Release Detection:	Not reported
Release Detection Comments:	RD Tank: Manual Tank Gauging; Tnk Tightness Testing; Statistical Inventory Reconciliation; Ground Water Monitoring / RD Line:
Piping Configuration:	Not reported
Piping Configuration Comments:	Not reported
Piping Styles:	S - Suction
Piping Constructions:	BM - Bare Metal
Piping Construction Comments:	Cathodically Protected
Piping Corrosion Protections:	OTH - Other (explain)
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	OTH - Other(explain)
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	NP - None Present
Spill Prevention Manhole Comments:	No
OverFill Prevention:	Not reported
OverFill Prevention Comment:	OverFill Spill: No
Comments:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

35
SSW
1/4-1/2
0.428 mi.
2259 ft.

SHELL OIL CO. #23461780241
2564 WILLIAMS RD
NORWOOD, OH 45212

OH LUST
OH UST
OH ARCHIVE UST

U003130271
N/A

Relative:
Lower

LUST:

Release Number: 31001186-N00001
Release Date: 01/03/1990
Facility Status: Inactive
LTF Status: 6 Closure of regulated UST
FR Status: NFA: No Further Action
Priority: 3
Review Date: 05/22/2003
Class: Viable Responsible Party has been identified

Actual:
602 ft.

Release Number: 31001186-N00002
Release Date: 09/02/2005
Facility Status: Inactive
LTF Status: 1 SUS/CON from regulated UST
FR Status: NFA: No Further Action
Priority: 2
Review Date: 05/11/2011
Class: Viable Responsible Party has been identified

UST:

Facility Id: 31001186
Facility Type: Gas Station
Owner Name: GILLIGAN OIL CO.
Owner Address: 625 EDEN PARK RD SUITE 525
Owner City/State/Zip: 45202

Tank Number: T00001
Status: CIU - Currently In Use
UST Capacity: 10000
Tank Content: Gasoline
Installation Date: 12/01/1972
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: YES
Date Of Sensitivity: 09/01/1992
UST Configurations: SW - Single Wall
Construction Comments: Not reported
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: ATG - Automatic Tank Gauging
Release Detection Comments: Not reported
Piping Configuration: SW - Single Wall
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Not reported
Piping Corrosion Protections: NR - None required by rule

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL OIL CO. #23461780241 (Continued)

U003130271

Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: FILL - Fill Pipe (drop tube flapper)
OverFill Prevention Comment: Not reported
Comments: Not reported

Tank Number: T00002
Status: CIU - Currently In Use
UST Capacity: 10000
Tank Content: Gasoline
Installation Date: 12/01/1972
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: YES
Date Of Sensitivity: 09/01/1992
UST Configurations: SW - Single Wall
Construction Comments: Not reported
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: ATG - Automatic Tank Gauging
Release Detection Comments: Not reported
Piping Configuration: SW - Single Wall
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: FRP - Fiberglass Reinforced Plastic
Piping Construction Comments: Not reported
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: FILL - Fill Pipe (drop tube flapper)
OverFill Prevention Comment: Not reported
Comments: Not reported

Tank Number: T00003
Status: CIU - Currently In Use
UST Capacity: 8000
Tank Content: Gasoline
Installation Date: 12/01/1972
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL OIL CO. #23461780241 (Continued)

U003130271

Abandoned Approved:	Not reported
Regulated:	YES
Sensitive Area:	YES
Date Of Sensitivity:	09/01/1992
UST Configurations:	SW - Single Wall
Construction Comments:	Not reported
Corrosion Protections:	NR - None Required by Rule
Corrosion Protection Comments:	Not reported
Primary Release Detection:	ATG - Automatic Tank Gauging
Secondary Release Detection:	ATG - Automatic Tank Gauging
Release Detection Comments:	Not reported
Piping Configuration:	SW - Single Wall
Piping Configuration Comments:	Not reported
Piping Styles:	P - Pressure
Piping Constructions:	FRP - Fiberglass Reinforced Plastic
Piping Construction Comments:	Not reported
Piping Corrosion Protections:	NR - None required by rule
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	ELLD - Electronic Line Leak Detector
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments:	Not reported
OverFill Prevention:	FILL - Fill Pipe (drop tube flapper)
OverFill Prevention Comment:	Not reported
Comments:	Not reported

ARCHIVE UST:

Facility Number:	31001186
Owner Name:	GILLIGAN OIL CO.
Owner Address:	4030 Smith Road Suite 450
Owner City,St,Zip:	CINCINNATI, OH 45209

Permit:

Facility Id:	31001186
Permit Id:	P00001
Permit Status:	Expired
Issued Date:	1/29/1998
LFD Permit Id:	Not reported

Facility Id:	31001186
Permit Id:	P00002
Permit Status:	Expired
Issued Date:	1/29/2001
LFD Permit Id:	Not reported

Facility Id:	31001186
Permit Id:	P00003
Permit Status:	Closed
Issued Date:	1/29/2001
LFD Permit Id:	Not reported

Facility Id:	31001186
Permit Id:	P00004
Permit Status:	Closed
Issued Date:	1/12/2006
LFD Permit Id:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL OIL CO. #23461780241 (Continued)

U003130271

Inspection:

Facility Id: 31001186
Permit Number: P00001
Code: 504
Inspection Type: Final

Facility Id: 31001186
Permit Number: P00004
Code: 502
Inspection Type: Final

Facility Id: 31001186
Permit Number: P00003
Code: 504
Inspection Type: Final

Tank ID: T00001
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Currently In Use
Install Date: 12/1/1972
Content: Gasoline
Capacity: 10000
Corrosion Protection Tank: None Required
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Fiberglass Reinforced Plastic
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00002
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Currently In Use
Install Date: 12/1/1972
Content: Gasoline
Capacity: 10000
Corrosion Protection Tank: None Required
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Fiberglass Reinforced Plastic

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL OIL CO. #23461780241 (Continued)

U003130271

Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00003
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Currently In Use
Install Date: 12/1/1972
Content: Gasoline
Capacity: 8000
Corrosion Protection Tank: None Required
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: None Required
Piping Material: Fiberglass Reinforced Plastic
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

36
East
1/4-1/2
0.437 mi.
2307 ft.

CAST-FAB TECHNOLOGIES, INC.
3040 FORRER ST
CINCINNATI, OH 45209

OH LUST **U004206898**
OH UST **N/A**

Relative:
Lower

LUST:
Release Number: 31004242-N00001
Release Date: Not reported
Facility Status: Inactive
LTF Status: 6 Closure of regulated UST
FR Status: NFA: No Further Action
Priority: 3
Review Date: 06/20/2000
Class: Viable Responsible Party has been identified

Actual:
598 ft.

UST:
Facility Id: 31004242
Facility Type: Commercial
Owner Name: Not reported
Owner Address: Not reported
Owner City/State/Zip: Not reported

Tank Number: T00001
Status: REM - Removed
UST Capacity: 10000
Tank Content: Heating Oil
Installation Date: 01/01/1941
Construction: BM - Bare Metal
Date Last Used: 08/01/1990
Date TCL Closed: Not reported
Date Removed: 07/22/1993

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CAST-FAB TECHNOLOGIES, INC. (Continued)

U004206898

CAS Number: 68476-30-2
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Bare Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00002
Status: REM - Removed
UST Capacity: 10000
Tank Content: Diesel
Installation Date: 01/01/1941
Construction: BM - Bare Metal
Date Last Used: 08/01/1990
Date TCL Closed: Not reported
Date Removed: 07/22/1993
CAS Number: 68334-30-5
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Bare Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CAST-FAB TECHNOLOGIES, INC. (Continued)

U004206898

Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00003
Status: REM - Removed
UST Capacity: 550
Tank Content: Gasoline
Installation Date: Not reported
Construction: BM - Bare Metal
Date Last Used: 07/22/1993
Date TCL Closed: Not reported
Date Removed: 07/22/1993
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Bare Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

Tank Number: T00004
Status: REM - Removed
UST Capacity: 550
Tank Content: Gasoline
Installation Date: Not reported
Construction: BM - Bare Metal
Date Last Used: 07/22/1993
Date TCL Closed: Not reported
Date Removed: 07/22/1993
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CAST-FAB TECHNOLOGIES, INC. (Continued)

U004206898

Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Bare Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Not reported

37
North
1/4-1/2
0.444 mi.
2344 ft.

KUTAL PROD
2700 HIGHLAND AVE
CINCINNATI, OH 45212

OH LUST **U004094618**
N/A

Relative:
Higher

LUST:

Actual:
651 ft.

Release Number: 31010186-N00001
Release Date: Not reported
Facility Status: Inactive
LTF Status: 6 Closure of regulated UST
FR Status: NFA: No Further Action
Priority: 3
Review Date: 06/20/2000
Class: Viable Responsible Party has been identified

38
West
1/4-1/2
0.448 mi.
2363 ft.

SALVATION ARMY
2250 PARK AVE
NORWOOD, OH 45212

OH LUST **U004206878**
OH UST **N/A**

Relative:
Higher

LUST:

Actual:
637 ft.

Release Number: 31003455-N00001
Release Date: 01/14/1994
Facility Status: Inactive
LTF Status: 1 SUS/CON from regulated UST
FR Status: NFA: No Further Action
Priority: 2
Review Date: 11/24/2004
Class: Viable Responsible Party has been identified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SALVATION ARMY (Continued)

U004206878

UST:

Facility Id: 31003455
Facility Type: Gas Station
Owner Name: Not reported
Owner Address: Not reported
Owner City/State/Zip: Not reported

Tank Number: T00001
Status: REM - Removed
UST Capacity: 6000
Tank Content: Diesel
Installation Date: Not reported
Construction: CS-Clad Steel
Date Last Used: 06/22/1998
Date TCL Closed: Not reported
Date Removed: 06/22/1998
CAS Number: 68334-30-5
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Composite (Steel with Fiberglass);Other
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMO - Alternative Method (Other, explain)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: NA - Not Applicable
Piping Constructions: OTH - Other (explain)
Piping Construction Comments: Unknown
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Yes
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: Yes
Comments: Not reported

39
ENE
1/4-1/2
0.463 mi.
2445 ft.

**MILACRON PLANT 5
3025 DISNEY STREET
CINCINNATI, OH**

**OH BROWNFIELDS S111008848
N/A**

**Relative:
Lower**

BROWNFIELDS:

App Id: 1651
District: SWDO
Community Name: USS Realty, LLC
Community Website: N/A
Contact Name: Dragon, Steve
Contact Title: Professional Engineer
Contact Address: 9900 Springboro Pike

**Actual:
589 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILACRON PLANT 5 (Continued)

S111008848

Contact County: Montgomery
Contact City/State/Zip: Miamisburg, OH
Contact Phone: (513) 272-3600
Contact Email: sdragon@vanhold.com
Current Land Use: Industrial;
Current Land Use (Other): Not reported
Past Land Use: Industrial;
Past Land Use (Other): Not reported
Current Zoning: PD
Vacancy: Vacant
Site Size (Acres): 16.31
Usable Buildings: Not reported
Building Space (Sq. Ft.): 220000
Utilities Available: Electrical; Water; Sewer; Natural Gas Service; Telecommunication Service;
Parcel Numbers: 051-0001-0001-00 (complete) 051-0001-0013-00 (partial) 051-0001-0050-00 (complete) 051-0001-0051-00 (partial)
Environmental Assessment: Asbestos Inspection Report; Phase I; Phase II;
General Comments: None.
Property History: Cincinnati Milacron, Cincinnati Milacron, Milling machine manufacturing, 01-JAN-04; UNOVA Industrial Automation Systems, UNOVA Industrial Automation Systems, Milling machine manufacturing, 01-JAN-05; Kirk & Blum Manufacturing Company, Kirk & Blum Manufacturing Company, Air handling system manufacturing, 01-JAN-10;
Proximity: This property is one-half mile from I-71. The property is 22 miles from the Cincinnati-Northern Kentucky International Airport. The property is 900 feet from a CSX railroad. The property is nine miles from the Ohio River. The property is accessible to pedestrians and public transportation is available.
COF Project: COAF
Date Entered: 06/14/2011
Owner Permission Rec: Yes
Associated Sites: 531002238

40
NW
1/4-1/2
0.482 mi.
2543 ft.

SWIFTY SERVICE STATION #275
2265 NORWOOD AVE
NORWOOD, OH 45212

OH LUST **U003130276**
OH UST **N/A**
OH ARCHIVE UST

Relative:
Higher

LUST:

Actual:
638 ft.

Release Number: 31001251-N00001
Release Date: Not reported
Facility Status: Inactive
LTF Status: 6 Closure of regulated UST
FR Status: NFA: No Further Action
Priority: 3
Review Date: 06/20/2000
Class: Viable Responsible Party has been identified

Release Number: 31001251-N00002
Release Date: 05/23/2014
Facility Status: Active
LTF Status: 1 SUS/CON from regulated UST
FR Status: T1N: Tier 1 Notification
Priority: 2
Review Date: 01/20/2015
Class: Viable Responsible Party has been identified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SWIFTY SERVICE STATION #275 (Continued)

U003130276

UST:

Facility Id:	31001251
Facility Type:	Gas Station
Owner Name:	SWIFTY OIL CO., INC.
Owner Address:	1515 W TIPTON PO BOX 1002
Owner City/State/Zip:	47274
Tank Number:	T00001
Status:	REM - Removed
UST Capacity:	12000
Tank Content:	Gasoline
Installation Date:	08/01/1981
Construction:	BM - Bare Metal
Date Last Used:	08/18/1994
Date TCL Closed:	Not reported
Date Removed:	08/18/1994
CAS Number:	8006-61-9
Abandoned Approved:	Not reported
Regulated:	YES
Sensitive Area:	NO
Date Of Sensitivity:	Not reported
UST Configurations:	Not reported
Construction Comments:	Steel
Corrosion Protections:	Not reported
Corrosion Protection Comments:	Not reported
Primary Release Detection:	AMSIR - Alternative Method (SIR)
Secondary Release Detection:	Not reported
Release Detection Comments:	RDTank: Manual Tank Gauging;Tnk Tightness Testing;Statistical Inventory Reconciliation / RDLine:
Piping Configuration:	Not reported
Piping Configuration Comments:	Not reported
Piping Styles:	S - Suction
Piping Constructions:	BM - Bare Metal
Piping Construction Comments:	Galvanized Steel
Piping Corrosion Protections:	OTH - Other (explain)
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	OTH - Other(explain)
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	NP - None Present
Spill Prevention Manhole Comments:	No
OverFill Prevention:	Not reported
OverFill Prevention Comment:	OverFill Spill: No
Comments:	Not reported

Tank Number:	T00002
Status:	REM - Removed
UST Capacity:	12000
Tank Content:	Gasoline
Installation Date:	08/01/1981
Construction:	BM - Bare Metal
Date Last Used:	08/18/1994
Date TCL Closed:	Not reported
Date Removed:	08/18/1994
CAS Number:	8006-61-9
Abandoned Approved:	Not reported
Regulated:	YES

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SWIFTY SERVICE STATION #275 (Continued)

U003130276

Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMSIR - Alternative Method (SIR)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Manual Tank Gauging;Tnk Tightness Testing;Statistical
Inventory Reconciliation / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Galvanized Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: NP - None Present
Spill Prevention Manhole Comments: No
OverFill Prevention: Not reported
OverFill Prevention Comment: OverFill Spill: No
Comments: Gasohol

Tank Number: T00003
Status: REM - Removed
UST Capacity: 12000
Tank Content: Gasoline
Installation Date: 08/01/1981
Construction: BM - Bare Metal
Date Last Used: 08/18/1994
Date TCL Closed: Not reported
Date Removed: 08/18/1994
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: NO
Date Of Sensitivity: Not reported
UST Configurations: Not reported
Construction Comments: Steel
Corrosion Protections: Not reported
Corrosion Protection Comments: Not reported
Primary Release Detection: AMSIR - Alternative Method (SIR)
Secondary Release Detection: Not reported
Release Detection Comments: RDTank: Manual Tank Gauging;Tnk Tightness Testing;Statistical
Inventory Reconciliation / RDLine:
Piping Configuration: Not reported
Piping Configuration Comments: Not reported
Piping Styles: S - Suction
Piping Constructions: BM - Bare Metal
Piping Construction Comments: Galvanized Steel
Piping Corrosion Protections: OTH - Other (explain)
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: OTH - Other(explain)
Piping Release Detection Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SWIFTY SERVICE STATION #275 (Continued)

U003130276

Spill Prevention Manholes:	NP - None Present
Spill Prevention Manhole Comments:	No
OverFill Prevention:	Not reported
OverFill Prevention Comment:	OverFill Spill: No
Comments:	Gasohol
Tank Number:	T00004
Status:	CIU - Currently In Use
UST Capacity:	10000
Tank Content:	Gasoline
Installation Date:	11/01/1994
Construction:	FRP-Fiberglass Reinforced Plastic
Date Last Used:	Not reported
Date TCL Closed:	Not reported
Date Removed:	Not reported
CAS Number:	8006-61-9
Abandoned Approved:	Not reported
Regulated:	YES
Sensitive Area:	YES
Date Of Sensitivity:	09/01/1992
UST Configurations:	SC- Secondarily Contained
Construction Comments:	Not reported
Corrosion Protections:	NR - None Required by Rule
Corrosion Protection Comments:	Not reported
Primary Release Detection:	ATG - Automatic Tank Gauging
Secondary Release Detection:	ATG - Automatic Tank Gauging
Release Detection Comments:	Not reported
Piping Configuration:	SC - Secondarily Contained
Piping Configuration Comments:	Not reported
Piping Styles:	P - Pressure
Piping Constructions:	FPTP - Flexible Plastic Technology Piping
Piping Construction Comments:	Not reported
Piping Corrosion Protections:	NR - None required by rule
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	ELLD - Electronic Line Leak Detector
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments:	Not reported
OverFill Prevention:	VENT - Vent Line (float vent valve)
OverFill Prevention Comment:	Not reported
Comments:	Not reported

Tank Number:	T00005
Status:	CIU - Currently In Use
UST Capacity:	10000
Tank Content:	Gasoline
Installation Date:	11/01/1994
Construction:	FRP-Fiberglass Reinforced Plastic
Date Last Used:	Not reported
Date TCL Closed:	Not reported
Date Removed:	Not reported
CAS Number:	8006-61-9
Abandoned Approved:	Not reported
Regulated:	YES
Sensitive Area:	YES

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SWIFTY SERVICE STATION #275 (Continued)

U003130276

Date Of Sensitivity: 09/01/1992
UST Configurations: SC- Secondarily Contained
Construction Comments: Not reported
Corrosion Protections: NR - None Required by Rule
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: ATG - Automatic Tank Gauging
Release Detection Comments: Not reported
Piping Configuration: SC - Secondarily Contained
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: FPTP - Flexible Plastic Technology Piping
Piping Construction Comments: Not reported
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: VENT - Vent Line (float vent valve)
OverFill Prevention Comment: Not reported
Comments: Not reported

Tank Number: T00006
Status: CIU - Currently In Use
UST Capacity: 10000
Tank Content: Gasoline
Installation Date: 11/01/1994
Construction: FRP-Fiberglass Reinforced Plastic
Date Last Used: Not reported
Date TCL Closed: Not reported
Date Removed: Not reported
CAS Number: 8006-61-9
Abandoned Approved: Not reported
Regulated: YES
Sensitive Area: YES
Date Of Sensitivity: 09/01/1992
UST Configurations: SC- Secondarily Contained
Construction Comments: Not reported
Corrosion Protections: LCP - Lined & Cathodically Protected
Corrosion Protection Comments: Not reported
Primary Release Detection: ATG - Automatic Tank Gauging
Secondary Release Detection: ATG - Automatic Tank Gauging
Release Detection Comments: Not reported
Piping Configuration: SC - Secondarily Contained
Piping Configuration Comments: Not reported
Piping Styles: P - Pressure
Piping Constructions: FPTP - Flexible Plastic Technology Piping
Piping Construction Comments: Not reported
Piping Corrosion Protections: NR - None required by rule
Piping Corrosion Protection Comments: Not reported
Piping Release Detections: ELLD - Electronic Line Leak Detector
Piping Release Detection Comments: Not reported
Spill Prevention Manholes: SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments: Not reported
OverFill Prevention: VENT - Vent Line (float vent valve)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SWIFTY SERVICE STATION #275 (Continued)

U003130276

OverFill Prevention Comment:	Not reported
Comments:	Not reported
Tank Number:	T00007
Status:	CIU - Currently In Use
UST Capacity:	6000
Tank Content:	Diesel
Installation Date:	11/01/1994
Construction:	FRP-Fiberglass Reinforced Plastic
Date Last Used:	Not reported
Date TCL Closed:	Not reported
Date Removed:	Not reported
CAS Number:	8008-20-6
Abandoned Approved:	Not reported
Regulated:	YES
Sensitive Area:	YES
Date Of Sensitivity:	09/01/1992
UST Configurations:	SC- Secondarily Contained
Construction Comments:	Not reported
Corrosion Protections:	NR - None Required by Rule
Corrosion Protection Comments:	Not reported
Primary Release Detection:	ATG - Automatic Tank Gauging
Secondary Release Detection:	ATG - Automatic Tank Gauging
Release Detection Comments:	Not reported
Piping Configuration:	SC - Secondarily Contained
Piping Configuration Comments:	Not reported
Piping Styles:	P - Pressure
Piping Constructions:	FPTP - Flexible Plastic Technology Piping
Piping Construction Comments:	Not reported
Piping Corrosion Protections:	NR - None required by rule
Piping Corrosion Protection Comments:	Not reported
Piping Release Detections:	ELLD - Electronic Line Leak Detector
Piping Release Detection Comments:	Not reported
Spill Prevention Manholes:	SB - Spill Containment Manhole (bucket)
Spill Prevention Manhole Comments:	Not reported
OverFill Prevention:	VENT - Vent Line (float vent valve)
OverFill Prevention Comment:	Not reported
Comments:	Not reported

ARCHIVE UST:

Facility Number:	31001251
Owner Name:	SWIFTY OIL CO., INC.
Owner Address:	1515 W TIPTON PO BOX 1002
Owner City,St,Zip:	SEYMOUR, IN 47274

Permit:

Facility Id:	31001251
Permit Id:	P00001
Permit Status:	Expired
Issued Date:	11/21/1994
LFD Permit Id:	Not reported

Facility Id:	31001251
Permit Id:	P00001
Permit Status:	Expired
Issued Date:	11/21/1994

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SWIFTY SERVICE STATION #275 (Continued)

U003130276

LFD Permit Id: Not reported

Facility Id: 31001251
Permit Id: P00002
Permit Status: Expired
Issued Date: 1/18/2011
LFD Permit Id: Not reported

Inspection:

Facility Id: 31001251
Permit Number: P00001
Code: 303
Inspection Type: Final

Tank ID: T00001
Tank Type: Steel
Tank Status: Removed
Install Date: 8/1/1981
Content: Gasoline
Capacity: 12000
Corrosion Protection Tank: Not reported
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Manual Tank Gauging;Tnk Tightness Testing;Statistical Inventory Reconciliation
Date Removed: 8/18/1994
Date Last Use: 8/18/1994
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Galvanized Steel
Piping Type: Suction: valve at tank
Release Detection On Piping: Not reported

Tank ID: T00002
Tank Type: Steel
Tank Status: Removed
Install Date: 8/1/1981
Content: Gasoline
Capacity: 12000
Corrosion Protection Tank: Not reported
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Manual Tank Gauging;Tnk Tightness Testing;Statistical Inventory Reconciliation
Date Removed: 8/18/1994
Date Last Use: 8/18/1994
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Galvanized Steel
Piping Type: Suction: valve at tank
Release Detection On Piping: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SWIFTY SERVICE STATION #275 (Continued)

U003130276

Tank ID: T00003
Tank Type: Steel
Tank Status: **Removed**
Install Date: 8/1/1981
Content: Gasoline
Capacity: 12000
Corrosion Protection Tank: Not reported
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: No
Spill Device Installed: No
Release Detection On Tank: Manual Tank Gauging;Tnk Tightness Testing;Statistical Inventory Reconciliation
Date Removed: 8/18/1994
Date Last Use: 8/18/1994
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: Not reported
Piping Material: Galvanized Steel
Piping Type: Suction: valve at tank
Release Detection On Piping: Not reported

Tank ID: T00004
Tank Type: DW - FRP - Fiberglass
Tank Status: **Currently In Use**
Install Date: 11/1/1994
Content: Gasoline
Capacity: 10000
Corrosion Protection Tank: NR - None Required by Rule
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging;Interstitial Monitoring Double Walled
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NR - None Required
Piping Material: DW FFTP - Flex Pipe
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00005
Tank Type: DW - FRP - Fiberglass
Tank Status: **Currently In Use**
Install Date: 11/1/1994
Content: Gasoline
Capacity: 10000
Corrosion Protection Tank: NR - None Required by Rule
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging;Interstitial Monitoring Double Walled
Date Removed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SWIFTY SERVICE STATION #275 (Continued)

U003130276

Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NR - None Required
Piping Material: DW FPTP - Flex Pipe
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00006
Tank Type: DW - FRP - Fiberglass
Tank Status: Currently In Use
Install Date: 11/1/1994
Content: Gasoline
Capacity: 10000
Corrosion Protection Tank: LCP - Lined & Cathodically Prote
CAS #: 8006-61-9
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging;Interstitial Monitoring Double Walled
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NR - None Required
Piping Material: DW FPTP - Flex Pipe
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Tank ID: T00007
Tank Type: DW - FRP - Fiberglass
Tank Status: Currently In Use
Install Date: 11/1/1994
Content: Kerosene
Capacity: 6000
Corrosion Protection Tank: NR - None Required by Rule
CAS #: 8008-20-6
Regulated: Yes
Overfill Device Installed: Yes
Spill Device Installed: Yes
Release Detection On Tank: Automatic Tank Gauging;Interstitial Monitoring Double Walled
Date Removed: Not reported
Date Last Use: Not reported
Date Abandoned/Closed: Not reported
AST/UST: UST
Corrosion Protection Piping: NR - None Required
Piping Material: DW FPTP - Flex Pipe
Piping Type: Pressure
Release Detection On Piping: Electronic Line Leak Detector

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

41
NNE
1/4-1/2
0.496 mi.
2618 ft.

DE RENNA SERV
2846 HIGHLAND AVE
NORWOOD, OH 45212

OH LUST

U004089069
N/A

Relative:
Lower

LUST:

Release Number: 31010004-N00001

Release Date: 04/07/1990

Facility Status: Inactive

LTF Status: 1 SUS/CON from regulated UST

FR Status: NFA: No Further Action

Priority: 2

Review Date: 04/02/2007

Class: Responsible Party is non-viable

Actual:
617 ft.

142
WNW
1/2-1
0.627 mi.
3312 ft.

GMC ASSEMBLY DIV NORWOOD PLT
4726 SMITH RD
NORWOOD, OH 45212

CERC-NFRAP

1015735722

CORRACTS

OHD004260089

RCRA NonGen / NLR

Relative:
Higher

CERC-NFRAP:

Site ID: 0506650

Federal Facility: Not a Federal Facility

NPL Status: Not on the NPL

Non NPL Status: Deferred to RCRA

Actual:
627 ft.

Site 1 of 2 in cluster I

Program Priority:

Description: RCRA Deferral Audit

Description: RCRA Deferral - Lead Confirmed

CERCLIS-NFRAP Assessment History:

Action: PRELIMINARY ASSESSMENT

Date Started: / /

Date Completed: 01/13/92

Priority Level: Deferred to RCRA (Subtitle C)

Action: DISCOVERY

Date Started: / /

Date Completed: 06/14/91

Priority Level: Not reported

Action: ARCHIVE SITE

Date Started: / /

Date Completed: 12/27/95

Priority Level: Not reported

CORRACTS:

EPA ID: OHD004260089

EPA Region: 05

Area Name: ENTIRE FACILITY

Actual Date: 20060701

Action: CA001

NAICS Code(s): 336211

Motor Vehicle Body Manufacturing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GMC ASSEMBLY DIV NORWOOD PLT (Continued)

1015735722

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: OHD004260089
EPA Region: 05
Area Name: ENTIRE FACILITY
Actual Date: 20090501
Action: CA070NO - RFA Determination Of Need For An RFI, RFI is Not Necessary
NAICS Code(s): 336211
Motor Vehicle Body Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: OHD004260089
EPA Region: 05
Area Name: ENTIRE FACILITY
Actual Date: 19920331
Action: CA075ME - CA Prioritization, Facility or area was assigned a medium
corrective action priority
NAICS Code(s): 336211
Motor Vehicle Body Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA NonGen / NLR:

Date form received by agency: 05/03/1999
Facility name: GMC ASSEMBLY DIV NORWOOD PLT
Facility address: 4726 SMITH RD
NORWOOD, OH 45212
EPA ID: OHD004260089
Contact: GERRY KILLEEN
Contact address: 4726 SMITH RD
NORWOOD, OH 45212
Contact country: US
Contact telephone: (513) 841-5102
Contact email: Not reported
EPA Region: 05
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: GMC-GM ASSEMBLY DIV - NORWOOD PLANT
Owner/operator address: 4726 SMITH ROAD
NORWOOD, OH 45212
Owner/operator country: Not reported
Owner/operator telephone: (513) 841-5102
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GMC ASSEMBLY DIV NORWOOD PLT (Continued)

1015735722

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GMC ASSEMBLY DIV NORWOOD PLT (Continued)

1015735722

- . Waste code: F008
- . Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Historical Generators:

Date form received by agency: 04/25/1990
Site name: GENERAL MOTORS CORP. CPC GROUP
Classification: Large Quantity Generator

Date form received by agency: 11/18/1980
Site name: GMC ASSEMBLY DIV NORWOOD PLT
Classification: Not a generator, verified

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D008
- . Waste name: LEAD

- . Waste code: F002
- . Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F006
- . Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

- . Waste code: F007
- . Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GMC ASSEMBLY DIV NORWOOD PLT (Continued)

1015735722

- . Waste code: F008
- . Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Date form received by agency: 08/18/1980

Site name: GMC ASSEMBLY DIV NORWOOD PLT

Classification: Large Quantity Generator

- . Waste code: D000
- . Waste name: Not Defined

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D008
- . Waste name: LEAD

- . Waste code: F002
- . Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F006
- . Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GMC ASSEMBLY DIV NORWOOD PLT (Continued)

1015735722

STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

. Waste code: F008
. Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: F009
. Waste name: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U007
. Waste name: 2-PROPENAMIDE (OR) ACRYLAMIDE

. Waste code: U123
. Waste name: FORMIC ACID (C,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

. Waste code: U171
. Waste name: 2-NITROPROPANE (I,T) (OR) PROPANE, 2-NITRO- (I,T)

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 01/01/1979

Site name: GMC ASSEMBLY DIV NORWOOD PLT

Classification: Large Quantity Generator

Corrective Action Summary:

Event date: 03/31/1992
Event: CA Prioritization, Facility or area was assigned a medium corrective action priority.

Event date: 07/01/2006
Event: CA001

Event date: 05/01/2009
Event: RFA Determination Of Need For An RFI, RFI is Not Necessary;

Facility Has Received Notices of Violations:

Regulation violated: Not reported